



# AEI Consultants

September 9, 2022

## HUD MAP CAPITAL NEEDS ASSESSMENT

### Property Identification:

Annapolis  
52 Sumner Street  
Dorchester, Massachusetts 02125

AEI Project No. 463356  
Site Inspection Date: July 6, 2022

### Prepared For:

Boston Housing Authority  
52 Chauncy Street  
Boston, Massachusetts 02111

### Prepared By:

AEI Consultants  
112 Water Street, 5th Floor  
Boston, MA 02109  
(857) 205-4165  
AEI Main Contact: Karla King

Environmental  
Due Diligence

Building Assessments

Site Investigation  
& Remediation

Energy Performance  
& Benchmarking

Industrial Hygiene

Construction  
Risk Management

Zoning Analysis  
Reports & ALTA  
Surveys

National Presence  
Regional Focus  
Local Solutions

Boston Housing Authority  
52 Chauncy Street,  
Boston, Massachusetts 02111

**Subject: HUD MAP CAPITAL NEEDS ASSESSMENT**  
Annapolis  
52 Sumner Street, Dorchester, Massachusetts 02125  
AEI Project No. 463356

Dear Rick Jegorow:

AEI's Capital Needs Assessment (CNA) (the Physical Inspection Report) has been prepared for the above-mentioned asset (the Property). During the property assessment and research, our needs assessor met with agents representing the Property, or agents of the owner, and reviewed the property and its history. This assessment and Physical Inspection Report have been prepared in accordance with ASTM E2018-15 "Standard Guide for Property Condition Assessments: Baseline Property Condition Assessment Process", and HUD protocols, including the use of MAP Guide, revised March 2021. This Physical Inspection Report is written to meet the Multifamily Accelerated Processing (MAP) guidelines pursuant to the U.S. Department of Housing and Urban Development (HUD) mortgage insurance programs.

The purpose for which this report shall be used shall be limited to the use as stated in the contract between the Client and AEI.

The CNA was performed at the Client's request using the methods and procedures consistent with good commercial or customary practice designed to conform to acceptable industry standards. The Report may be relied upon by Boston Housing Authority, their respective successors and assigns, and by the United States Department of Housing and Urban Development (HUD).

In expressing the opinions stated in this report, AEI has exercised the degree of skill and care ordinarily exercised by a reasonably prudent capital needs assessor in the same community and in the same time frame given the same or similar facts and circumstances. Documentation and data provided by the Client, designated representatives of the Client or other interested third





parties, or from the public domain, and referred to in the preparation of this assessment, have been used and referenced with the understanding that AEI assumes no responsibility or liability for their accuracy.

The independent conclusions represent our professional judgment based on information and data available to us during the course of this assignment. AEI's evaluations, analyses and opinions are not representations regarding the design integrity, structural soundness, or actual value of the property. Factual information regarding operations, conditions and test data provided by the Client or their representative has been assumed to be correct and complete. The conclusions presented are based on the data provided, observations and conditions that existed on the date of the on-site visit.

Should you have any questions or require additional information, please contact Jeb Bonnett at 804-955-8373 or [jbonnett@aeiconsultants.com](mailto:jbonnett@aeiconsultants.com).

Sincerely,

DRAFT  
Karla King  
Executive Vice President  
AEI Consultants

DRAFT  
Jeb Bonnett  
Vice President - HUD Building Assessments  
AEI Consultants

# TABLE OF CONTENTS

---

<b>1.0 EXECUTIVE SUMMARY AND PROPERTY DESCRIPTION</b>	<b>6</b>
1.1 Overall Condition Of The Property	7
1.2 Remaining Useful Life	7
1.3 List of Commonly Used Acronyms	7
<b>2.0 PURPOSE AND SCOPE</b>	<b>9</b>
2.1 Purpose	11
2.2 Scope of Work	11
2.3 Site Visit Information	13
2.4 Reliance	13
<b>3.0 OVERALL GENERAL DESCRIPTION</b>	<b>15</b>
3.1 Building and Unit Summary	15
3.2 Site	15
3.3 Structural Frame & Building Envelope	25
3.4 Mechanical & Electrical Systems	36
3.5 Elevators	42
3.6 Life & Fire Safety	42
3.7 Interior Elements	44
<b>4.0 ADDITIONAL CONSIDERATIONS</b>	<b>54</b>
4.1 Moisture and Microbial Growth	54
4.2 Pest Management	55
4.3 Seismic Zone	55
4.4 Wind Zone	56
4.5 Flood Plain	56
4.6 Known Problematic Building Materials	57
<b>5.0 DOCUMENT REVIEW &amp; INTERVIEWS</b>	<b>58</b>
5.1 Documents Reviewed	58
5.2 Interviews	58
5.3 Building Code Compliance	58
5.4 Fire Code Compliance	58
5.5 Zoning Compliance	58
5.6 HUD Real Estate Assessment Center (REAC) Inspection	58
<b>6.0 ACCESSIBILITY &amp; INTRUSIVE EXAMINATIONS</b>	<b>59</b>
6.1 Accessibility	59
6.2 Intrusive Examinations	66
6.3 Owner Proposed Improvements	66
<b>7.0 OPINIONS OF PROBABLE COST</b>	<b>67</b>
7.1 Financial Recap	67
7.2 Critical Repairs	67
7.3 Non-Critical Repairs	69
7.4 Replacement Reserves	71
7.5 Insurable Value - Replacement Cost	73
<b>8.0 ASSESSOR QUALIFICATIONS</b>	<b>74</b>
<b>9.0 LIMITING CONDITIONS</b>	<b>76</b>

# TABLE OF APPENDICES

---

- APPENDIX A: Dwelling Unit Photo Documentation
- APPENDIX B: General Photo Documentation
- APPENDIX C: Street Map and Aerial Photo
- APPENDIX D: USGS Seismic Design Map

APPENDIX E: Record of all Documents Reviewed, Interviews, and Supporting Information  
APPENDIX F: Property Evaluator Qualifications

DRAFT

## 1.0 EXECUTIVE SUMMARY AND PROPERTY DESCRIPTION

AEI was retained by Boston Housing Authority on May 18, 2022 to conduct a Capital Needs Assessment (CNA) at Annapolis located at 52 Sumner Street in Dorchester, Massachusetts. The property features 56 dwelling units within 3 buildings, which were built in Circa 1950 and are situated on 1.268 acres. The property was observed in fair physical condition.

A summary of the Property improvements is provided in the following table.

Item	Description
Property Type	Senior apartments
Number of Floors	2
Number of Apartment Units	56
Total Number of Buildings	3
Number of Apartment Buildings	3
Ancillary Buildings	Not applicable
Parking	10 total spaces 8 regular spaces 2 accessible spaces of which 1 is a van-accessible space Source: Site Count
Gross Floor Area	41,961 sqft per Parcel records
Net Rentable Floor Area	24,766 sqft per Client provided
Site Area	1.268 acres per Assessor
Year of Construction	Circa 1950 per Assessor

## 1.1 OVERALL CONDITION OF THE PROPERTY

### Code Compliance and Design

Subject property improvements appear to have been carried out in compliance with contemporary building codes and standard building practices at the time of their construction. The Project Manager did not observe any obvious building code violations, nor did management or City report any violations. The quality of planning and design provided for site improvements appears to be suitable, reflecting a relatively efficient use of space and an acceptable use of building materials and systems.

### Overall Condition of the Property

Based on AEI's observation of the Property and improvements, the Property appears to be in overall fair condition.

Assuming the level of maintenance currently being provided at the subject property is continued and deferred maintenance specified herein is corrected, the property should continue to retain its ability to perform and compete in the local market in the future.

### Recommendations in this Report

The recommendations in this report are based upon ASTM guidelines and are limited to visual observations. Testing of systems was not performed and no invasive or destructive testing was undertaken. No recommendations for immediate, further investigation have been included in the Assessment and Recommendation sections of this report.

## 1.2 REMAINING USEFUL LIFE

Based on the general condition of the Property reported above, it is AEI's opinion that the Remaining Useful Life (RUL) of the Property is estimated to be not less than 50 years barring any natural disasters. This opinion is based on its current condition and maintenance status, assuming any recommended Immediate Repairs or Replacement Reserves are completed and appropriate routine maintenance and replacement items are performed on an annual or as-needed basis. AEI's building RUL estimate is a subjective opinion based on observed and reported conditions obtained as part of the CNA assessment and is not an estimate of the Remaining Economic Life (REL) of the property.

AEI will identify items addressed as operating expenses as opposed to capital replacements that would be included in our Reserves for Replacement when sufficient documentation has been provided by the borrower.

No documentation regarding the differentiation between operating expenses and capital replacements was provided by the borrower.

## 1.3 LIST OF COMMONLY USED ACRONYMS

ADA	The Americans with Disabilities Act
-----	-------------------------------------

AHU	Air Handling Unit
ASTM	American Society for Testing and Materials
BOMA	Building Owners & Managers Association
BUR	Built-up Roof System
BTU	British Thermal Unit (a measurement of heat)
DWV	Drainage, Waste, Ventilation
EIFS	Exterior Insulation and Finish System
EMS	Energy Management System
EPDM	Ethylene Propylene Diene Monomer (rubber membrane roof)
EUL	Expected Useful Life
FCU	Fan Coil Unit
FEMA	Federal Emergency Management Agency
FFHA	Federal Fair Housing Act
FHA	Forced Hot Air
FHW	Forced Hot Water
FIRMS	Flood Insurance Rate Maps
FOIA	U.S. Freedom of Information Act (5 USC 552 et seq.) and similar state statutes.
FOIL	Freedom of Information Letter
GFI	Ground Fault Interrupt (circuit)
GPNA	Green Physical Needs Assessment
GWB	Gypsum Wall Board
HVAC	Heating, Ventilating and Air Conditioning
IAQ	Indoor Air Quality
IM / IR	Critical or Non-Critical Repair
MEP	Mechanical, Electrical & Plumbing
MDP	Main Distribution Panel
NA	Not Applicable
NFPA	National Fire Protection Association
PCA	Property Condition Assessment
PCR	Property Condition Report
PML	Probable Maximum Loss
PTAC	Packaged Through-wall Air Conditioning (Unit)
R&M	Repair and Maintain - Routine Maintenance
RR	Replacement Reserve
RTU	Rooftop Unit
SF	Square Feet
TPO	Thermoplastic Polyolefin Roof Membrane
VAV	Variable Air Volume Box
WDO	Wood Destroying Organisms

## 2.0 PURPOSE AND SCOPE

---

### Cost Calculation Methodology

Estimates are based on construction costs developed by construction resources such as Marshall & Swift, RS Means, AEI's Commercial Inspectors' experience with past costs for similar projects, city cost indexes, consulting with local specialty contractors, client provided information, and assumptions regarding future economic conditions.

Actual costs may differ from AEI's cost estimates. Actual cost estimates are determined by many factors including but not limited to: choice and availability of materials, choice and availability of a qualified contractor, regional climate zone, quality of existing materials, site compatibility, and access to the subject property and buildings. Costs are solely based on material replacement and do not account for soft costs.

### Critical Repairs

Items which will need to be performed as Critical Repairs (before loan closing) are included in the Critical Repairs Cost Estimate Table 7.2. Critical repairs are identified as either Life Safety or Accessibility. Those identified as "Life Safety" are needed to address hazards to life and health while those identified as "Accessibility" are needed to correct accessibility deficiencies. While these are not mutually exclusive, only one designation may be applied to each repair or alteration.

Life Safety repairs must be completed prior to Endorsement.

Accessibility repairs must be completed as soon as possible; and the CNA e Tool requires that the time estimated to complete each accessibility repair be identified as a number of months. If "as soon as" possible exceeds twelve months for any Accessibility repair, the corrective action plan must be referred to HUD headquarters to the attention of the Director of Technical Support in the Office of Multifamily Housing Production, who will determine whether the proposed corrective action plan is acceptable.

### Non-Critical Repairs

Each of the Non-Critical (within 1 year of loan closing) Repair items noted during the survey is listed Table 7.3. Non-Critical Repairs are recommended for deferred maintenance that could result in physical depreciation or loss of property value. Non-critical repairs must be promptly and timely executed and completed within twelve months of endorsement, provided that the MF Regional Center/Satellite Office Director may approve an extended period not to exceed six additional months for unusual circumstances (e.g. work constrained by weather conditions or work requiring temporary relocation of elderly or disabled tenants.). A program of repairs and alterations which because of scale or quantity is reasonably expected to require more than a year to complete should be reconsidered as substantial rehabilitation.

### Replacement Reserves



Items that will most likely need to be performed over the length of the evaluation period (20 years) such as repairs, replacements and significant maintenance items are listed in the Replacement Reserves Table (Table 7.4).

Items included in the Replacement Reserve Table are determined based upon the estimated useful life (EUL) of a system or component, the effective age (EA) of the system, and the remaining useful life (RUL) of that system. Factors that may affect the age and condition of a system include, but are not limited to, the frequency of use, exposure to environmental elements, quality of construction and installation, and amount of maintenance provided. Based on these factors, a system may have an effective age that is greater or less than its actual chronological age. Routine maintenance costs are not included as part of this assessment.

The Effective Useful Life (EUL) is the average amount of time in years that a system, component or structure is estimated to function when installed new and assuming that routine maintenance is practiced. It is based upon site observations, research, and judgment, along with referencing EUL tables from the United States Department of Housing and Urban Development guidelines. Accurate historical replacement records, if provided, are typically the best source of information. Exposure to the elements, initial quality and installation, extent of use, the quality and amount of preventive maintenance exercised, etc., are all factors that impact the effective age of a system or component. As a result, a system or component may have an effective age that is greater or less than its actual chronological age. The Remaining Useful Life (RUL) of a component or system equals the EUL less its effective age.

The Remaining Useful Life (RUL) is a subjective estimate based upon observations, or average estimates of similar items, components, or systems, or a combination thereof, of the number of remaining years that it is estimated to be able to function in accordance with its intended purpose before requiring replacement. Such period of time is affected by the initial quality of the system or component, the quality of the initial installation, the quality and amount of preventive maintenance, climatic conditions, extent of use and other factors.

The RUL estimate is an expression of a professional opinion and is not a guarantee or warranty, expressed or implied. This estimate is based upon the observed physical condition of the property at the time of the visit and is subject to the possible effect of concealed conditions or the occurrence of extraordinary events such as natural disasters or other unforeseen events that may occur subsequent to the date of the site visit. The RUL estimate is made only with regard to the expected physical or structural integrity of the improvements on the Property. Based upon observations during our site visit and information received from our interviews with building management and service personnel, which for the purpose of the CNA was deemed reliable, AEI prepared general-scope, Opinions of Probable Cost based on appropriate remedies for the deficiencies noted. Such remedies and their associated costs were considered commensurate with the Property's position in the market and prudent expenditures. These opinions are for components of systems exhibiting significant deferred maintenance, and existing deficiencies requiring major repairs or replacement. Repairs or improvements that could be classified as (i) cosmetic, (ii) decorative, (iii) part or parcel of a building's renovation program or to reposition the asset in the marketplace, (iv) routine or normal preventative maintenance, or (v) that are the responsibility of the tenants were not included.

## 2.1 PURPOSE

The purpose of this survey and related report is to assist Boston Housing Authority and HUD in the evaluation of the physical aspects of the subject property and how its condition may affect the soundness of their financial decisions over time. For this assessment, the Project Manager has performed a reconnaissance assessment of the subject property and its improvements, evaluated the apparent physical conditions, reviewed available documentation, assessed the expected useful life (EUL), and estimated the cost for repairs, replacements, and significant maintenance items. The Project Manager assessed a representative sample of the building/s; the assessment typically included roofs, operational components, parking structures, and all common areas and exteriors.

The CNA is not, and should not be construed as, a warranty or guarantee about the condition of the improvements. Neither is the Assessment intended to assure clear title to the property in question. This investigation was prepared for the sole use and benefit of Boston Housing Authority and HUD. Neither this report, nor any of the information contained herein shall be used or relied upon for any purpose by any person or entity other than Boston Housing Authority and HUD.

We have performed our services and prepared this Report in accordance with applicable, generally accepted engineering, environmental or appraisal consulting practices. We make no other warranties, either expressed or implied, as to the character and nature of such services and product.

## 2.2 SCOPE OF WORK

AEI was retained by Boston Housing Authority on May 18, 2022 to conduct a Capital Needs Assessment (CNA) to fulfill the due diligence requirements of a pending real estate transaction. The CNA was performed in conformance with the scope and limitations of ASTM Standard Practice E2018-15 and the U.S. Department of Housing and Urban Development Multifamily Accelerated Processing (MAP) Guide, Chapter 5 and related Appendices, revised March 2021. The CNA was performed at Annapolis property located at 52 Sumner Street in Dorchester, Massachusetts. The scope of work included the following:

- The inspection of at least 25% of each unit type;
- The visual examination of the property's components, including MEP equipment, exterior walls, roofing, foundations, landscaping, utilities, and interior elements;
- The interviewing of property management and tenants;
- The information gathering from Freedom of Information request letters from the local Building, Zoning, and Fire departments;
- The data population of HUD's CNA E-Tool;

Any exceptions to, or deletions from, this practice are described in Section 7 of this report.

### **2.2.1 ASSESSMENT METHODOLOGY**

The CNA meets the specifications of the lender and has included the following:

#### **Preliminary Due Diligence**

Prior to the site visit by the Property Evaluator, the pre-survey questionnaire was provided to the managers of the Property with a request that the questionnaire be completed prior to the visit.

#### **Site Reconnaissance**

The CNA findings are based on the visual, non-intrusive and non-destructive evaluation of various external and internal site and building systems and components as noted during a site walk-through survey conducted by AEI representatives. The survey included access and observation of representative tenant spaces and common areas.

#### **Interviews and Research**

AEI representatives conducted limited research to identify and review available maintenance procedures, available drawings, and other readily available documentation concerning the property. AEI representatives also conducted interviews with available management and maintenance staff. As conditions warranted, contractors for the property were contacted for pertinent information. AEI requested readily available records with public agencies familiar with the property to gather historical property information. A summary of findings have been included in the narrative sections of this report.

#### **Report**

The evaluation covered readily apparent conditions at the property. Upon completion of the site reconnaissance, interviews, and research, AEI produced this summary report. This report includes a discussion of topics related to the property condition and outlines the costs to correct the deficiencies noted. AEI formulates and presents the Critical Repairs, Non-Critical Repairs, and Replacement Reserves Schedule. The content in these tables is generated from the HUD CNA E-Tool.

Based upon observations during our site visit and information received from our interviews with building management and service personnel, which for the purpose of the CNA was deemed reliable, AEI prepared general-scope, Opinions of Probable Cost based on appropriate remedies for the deficiencies noted. Such remedies and their associated costs were considered commensurate with the Property's position in the market and prudent expenditures. These opinions are for components of systems exhibiting significant deferred maintenance, and existing deficiencies requiring major repairs or replacement. Repairs or improvements that could be classified as (i) cosmetic, (ii) decorative, (iii) part or parcel of a building's renovation program or to reposition the asset in the marketplace, (iv) routine or normal preventative maintenance, or (v) that are the responsibility of the tenants were not included.

It is the intent of the CNA to reflect material physical deficiencies and the corresponding opinion of probable costs that are (i) commensurate with the complexity of the Property and (ii) not minor or insignificant.

### **Standard Estimated Useful Life (EUL)**

The EUL is the average amount of time in years that a system, component or structure is estimated to function when installed new and assuming that routine maintenance is practiced. HUD has hard coded an EUL associated with every component in the HUD CNA E-Tool. Neither AEI, nor any other provider can use different EULs for components in the CNA E-Tool.

### **Assessed Remaining Useful Life (ARUL)**

This is the Needs Assessor's best professional judgment of the actual RUL of the Component ID based on observed conditions that may not agree with the auto-populated value in the Standard Remaining Useful Life field. Needs Assessors must provide a comment each time the ARUL field is populated in the CNA E-Tool.

### **Standard Remaining Useful Life (SRUL)**

The SRUL Displays the RUL based on the Standard EUL less the current age of the component. This is an auto-populated field that is strictly math based.

## **2.3 SITE VISIT INFORMATION**

### *Site Visit Facts*

Date of Site Visit	July 6, 2022
Time of Site Visit	10:00 am
Weather Conditions	82° F and clear
Site Assessor	Juan Sequeira
Site Escorts	Mr. James Barner
Point of Contact	Mrs. Lynne Jones
Total Units Inspected	10

### *Dwelling Units Inspected*

<b>Building Identification</b>	<b>Unit Type</b>	<b>Unit Identification</b>	<b>Unit Status</b>
Building 1	2 Bed / 1 Bath	4	Occupied
Building 1	2 Bed / 1 Bath	17	Occupied
Building 1	1 Bed / 1 Bath	18	Occupied
Building 1	1 Bed / 1 Bath	20	Occupied
Building 2	2 Bed / 1 Bath	24	Occupied
Building 2	1 Bed / 1 Bath	34	Occupied
Building 2	1 Bed / 1 Bath	35	Occupied
Building 2	1 Bed / 1 Bath	38	Occupied
Building 3	1 Bed / 1 Bath	45	Occupied
Building 3	1 Bed / 1 Bath	48	Occupied

## **2.4 RELIANCE**

The CNA is not, and should not be construed as, a warranty or guarantee about the condition of the improvements. Neither is the Assessment intended to assure clear title to the property in question. The investigation was conducted on behalf of and for the exclusive use of Boston Housing Authority (Client) and HUD solely for use in a property condition evaluation of the subject property. The report has been prepared only for the purpose of securing mortgage

financing/re-financing and/or loan securitization. This report and findings contained herein shall not, in whole or in part, be disseminated or conveyed to any other party, nor used by any other party, in whole or in part without prior written consent of AEI. AEI acknowledges and agrees that the report may be conveyed to and relied upon by the Client, their successors and assigns, rating agencies and bond investors.

Reliance is provided in accordance with AEI's Proposal and Terms and Conditions executed by Boston Housing Authority on May 18, 2022. The limitation of liability defined in the Terms and Conditions is the aggregate limit of AEI's liability to the client and all relying parties.

DRAFT

### 3.0 OVERALL GENERAL DESCRIPTION

#### 3.1 BUILDING AND UNIT SUMMARY

The Project Manager's findings are derived from a thorough review of all available resources, including but not limited to, construction drawings, rent rolls, interviews with property management, and field inspection observations. Please note that the building and unit matrices were populated in the CNA E-Tool and the Building Unit Mix report generated from that effort is attached below:

##### *Unit Mix Breakdown*

Unit Type ID	Square Feet	# of This Floorplan	Total Unit Square Footage
1 Bed / 1 Bath	440	50	22,000
2 Bed / 1 Bath	461	6	2,766
	<b>Total:</b>	<b>56</b>	<b>24,766</b>

##### *Building Breakdown*

Building Identifier	Number of Stories	Gross Square Feet
Building 1	2	14,215
Building 2	2	14,173
Building 3	2	13,573
	<b>Total:</b>	<b>41,961</b>

#### 3.2 SITE

##### 3.2.1 SITE TOPOGRAPHY

The property is generally flat with only minor variations in slope. There are no notable deficiencies or indications of deferred maintenance associated with the site's topography.

##### 3.2.2 STORMWATER DRAINAGE

Item	Description	Action	Condition
Topography	Gentle slopes throughout Property	R&M	Good
Retaining Walls	Not applicable	NA	Not applicable
Adjoining Properties	Roughly at similar elevation to the Property.	R&M	Good
Storm Water Collection System	Underground municipal drainage system	R&M	Good
Landscape Drainage System	Landscaped areas sloped towards area drains	R&M	Good
Pavement Drainage System	Storm water area drains	R&M	Good
Foundation Drainage System	Rain leaders are attached to downspouts at the base of the building.	R&M	Good



**ASSESSMENT / RECOMMENDATION**

No notable deficiencies or indications of deferred maintenance of topography, drainage or retaining wall features were observed or reported.

**Photographs**



Stormwater Drainage: Typical topography found throughout the site.



Stormwater Drainage: Typical adjoining property found around the site.



Stormwater Drainage: Typical adjoining property found around the site.



Stormwater Drainage: Typical paving drainage found throughout site.





Stormwater Drainage: Typical downspout found throughout site.



Landscaping & Appurtenances: Damaged CMU wall found on the north perimeter of the property. (Non-Critical Repair)

### 3.2.3 ACCESS & EGRESS

Items	Description	Action	Condition
Site Access	Provided by two entrances / exits from adjoining municipal streets:	R&M	Good
Signalization at Site Access	No traffic lights are provided at the entrances to the Property.	NA	Not applicable
Easement or Alley Way	Not applicable	NA	Not applicable

### Photographs



Access & Egress: West access drive to the property.



Access & Egress: East access drive to the property.

### 3.2.4 PAVING, CURBING, & PARKING

Items	Description	Action	Condition
Asphalt Pavement	Asphalt pavement is provided for on-site parking and drive lanes	RR	Good

Items	Description	Action	Condition
Concrete Pavement	Not applicable	NA	Not applicable
Curbing	Concrete	RR	Good
Seal Coating	Recently applied	RR	Good
Striping	Pavement painted striping recently applied/ reapplied	RR	Good
Total Number of Parking Spaces	10 spaces in open lots	NA	Not applicable
Number of ADA Spaces	2	NA	Not applicable

### Photographs



Paving, Curbing, & Parking: Typical asphalt pavement found throughout the site.



Paving, Curbing, & Parking: Typical concrete curving found throughout the site.



Paving, Curbing, & Parking: Typical accessible parking spaces found throughout the property.



Paving, Curbing, & Parking: Typical parking spaces found throughout the property.





Paving, Curbing, & Parking: Typical striping found throughout the property.

### 3.2.5 FLATWORK (WALKS, PLAZAS, TERRACES, PATIOS)

Item	Description	Action	Condition
Sidewalks	Concrete	RR	Good
Ramps	Poured in place concrete	RR	Good
Exterior Steps	Concrete steps and landings at building entrances	RR	Good
Handrails	Steel handrails protect exterior steps and ramps.	R&M	Good
Loading Docks	Not applicable	NA	Not applicable

#### Photographs



Flatwork (Walks, Plazas, Terraces, Patios): Poured in place concrete ramp and sidewalks found at the property.



Flatwork (Walks, Plazas, Terraces, Patios): Concrete steps with steel handrails found at the property.



Flatwork (Walks, Plazas, Terraces, Patios):  
Typical concrete sidewalks found at the property.

### 3.2.6 LANDSCAPING & APPURTENANCES

The perimeter brick wall located on the north side of the property was observed damaged, with sections of plaster missing or falling off. AEI recommends repairing the perimeter wall to prevent further damage. (Non-Critical Repair)

Item	Description	Action	Condition
Landscaping	Trees, shrubbery, and lawn	R&M	Good
Irrigation	Not applicable	NA	Not applicable
Perimeter Fencing	Wrought iron fencing and Concrete Masonry Unit (CMU) wall	IM/RR	Poor
Entry Gates	Not applicable	NA	Not applicable
Patio Fencing	Not applicable	NA	Not applicable
Refuse Area Fencing	Dumpsters surrounded by chain-link fencing	R&M	Good
Site/Building Lighting	Exterior building mounted high intensity lights	R&M	Good
Parking Area Lighting	HID (high intensity discharge) lights mounted on building	R&M	Good
Signage	Monument sign	RR	Good/Fair
Water Features	Not applicable	NA	Not applicable



## Photographs



Landscaping & Appurtenances: Typical landscaping found throughout at the property.



Landscaping & Appurtenances: Typical landscaping found throughout at the property.



Landscaping & Appurtenances: Typical landscaping found throughout at the property.



Landscaping & Appurtenances: Perimeter wrought iron fencing found on north of the property.



Landscaping & Appurtenances: Damaged CMU wall found on the north perimeter of the property. (Non-Critical Repair)



Landscaping & Appurtenances: Refuse area fencing found on the property.



Landscaping & Appurtenances: Typical building lighting found throughout the property.



Landscaping & Appurtenances: Typical parking area lighting found throughout the property.



Landscaping & Appurtenances: Monumental signage found on the property.

### 3.2.7 RECREATIONAL FACILITIES

Item	Description	Action	Condition
Swimming Pool Filtration Equipment	Not applicable	NA	Not applicable
Swimming Pool / Spa / Pool Decking	Not Applicable	NA	Not applicable
Barbecue	Not Applicable	NA	Not applicable
Picnic Areas	Not Applicable	NA	Not applicable
Sport Courts	Not Applicable	NA	Not applicable
Tennis Courts	Not Applicable	NA	Not applicable
Playground	Not Applicable	NA	Not applicable

#### Other Structures

Item	Description	Action	Condition
Garages	Not applicable	NA	Not applicable
Carpports	Not applicable	NA	Not applicable

Item	Description	Action	Condition
Maintenance Shed	Not applicable	NA	Not applicable
Porte Cochere	Not applicable	NA	Not applicable
Landscaping Structures	Not applicable	NA	Not applicable

### 3.2.8 SITE UTILITIES

Utility Provider	Provider
Natural Gas	National Grid
Electricity	Eversource
Potable Water	Boston Water & Sewer
Sanitary Sewerage	Boston Water & Sewer
Storm Sewer	Municipal
Fuel Oil	Not Applicable

DRAFT



## Photographs



Site Utilities: Central gas meter found at the site.



Site Utilities: Central electric meter found at the site.



Site Utilities: Central water meter found at the site.

Item	Description	Action	Condition
Domestic Water Supply Lines	Copper pipe	IM/RR	Fair/Poor
Waste Service Lines	PVC and Cast Iron pipes	RR	Good/Fair
Lift Stations	Not applicable	NA	Not applicable
Waste Water Treatment System	Not applicable	NA	Not applicable
Water Wells	Not applicable	NA	Not applicable
Emergency Generator	Not applicable	NA	Not applicable
Transformers	Utility-owned, pad-mounted electrical transformer(s)	R&M	Good
Alternative Energy Systems	Not applicable	NA	Not applicable

## Photographs



Foundation: Typical basement found throughout the site.



Foundation: Typical cracks on basement walls and ceilings found throughout the site. (Critical Repair)



Foundation: Typical cracks on basement walls and ceilings found throughout the site. (Critical Repair)



Plumbing: Typical corroded pipes found throughout the property. (Non-Critical Repair)

### 3.3 STRUCTURAL FRAME & BUILDING ENVELOPE

#### 3.3.1 FOUNDATION

Item	Description	Action	Condition
Foundation Type	Basement	IM	Poor
Foundation Walls	Masonry basement walls	IM	Poor
Building Slab	Concrete slab-on-grade	R&M	Good
Moisture Control	Pavement abuts the perimeter of the foundation.	R&M	Good
Uniformity	The foundation is considered to be generally uniform, but this could not be confirmed.	NA	Not applicable

**ASSESSMENT / RECOMMENDATION**

AEI observed significant concrete cracking and splitting at the basements throughout the site. This may be a sign of a structural problem with the concrete structure. AEI recommended having a structural engineer assess this issue for safety reasons. (Critical Repair)

Address findings by a structural engineer to prevent future damage to the buildings. (Non-Critical Repair)

**Photographs**



Foundation: Typical basement found throughout the site.



Foundation: Typical basement found throughout the site.



Foundation: Typical cracks on basement walls and ceilings found throughout the site. (Critical Repair)



Foundation: Typical cracks on basement walls and ceilings found throughout the site. (Critical Repair)





Foundation: Typical cracks on basement walls and ceilings found throughout the site.  
(Critical Repair)



Foundation: Typical cracks on basement walls and ceilings found throughout the site.  
(Critical Repair)



Foundation: Typical cracks on basement walls and ceilings found throughout the site.  
(Critical Repair)



Foundation: Typical cracks on basement walls and ceilings found throughout the site.  
(Critical Repair)

### 3.3.2 FRAMING

#### 3.3.2.1 FRAMING SYSTEM, FLOORS & WALLS

Item	Description	Action	Condition
Wall Structure	Solid masonry walls and Wood framing	R&M	Good
Secondary Framing Members	Steel lintels at window and door openings	R&M	Good
Mezzanine	Not applicable	NA	Not applicable
Walls and Floors Plumb, Level and Stable	No unusual problems were observed or reported.	R&M	Good
Significant Signs of Deflection, Movement	No unusual problems were observed or reported.	R&M	Good

### 3.3.2.2 CRAWL SPACES, ENVELOPE PENETRATIONS

There are no crawl spaces in the apartment buildings.

### 3.3.2.3 ROOF FRAME & SHEATHING

Item	Description	Action	Condition
Roof Design	Pitched with attic space	R&M	Good
Roof Framing	Pre-cast concrete planks and wood rafters	R&M	Good
Roof Deck or Sheathing	Plywood decking	R&M	Good
FRT Plywood	FRT plywood was not observed in the attic area.	NA	Not applicable
Significant Signs of Deflection, Movement	No unusual problems were observed or reported.	R&M	Good

### 3.3.2.4 FLASHING & MOISTURE PROTECTION

Roof flashing appeared to be in overall fair condition.

### 3.3.2.5 ATTICS & EAVES

The attics are ventilated by a combination of ridge vents and perforated eave vents. The ridge vent is aluminum and covered with shingles to match the rest of the roofing.

#### Photographs



Attics & Eaves: Typical perforated eaves vents found throughout the site (Non-Critical Repair)



Attics & Eaves: Typical ridge vents found throughout the site.

### 3.3.2.6 INSULATION

The roofs are insulated with fiberglass batts.

The depth of the insulation could not be observed.

### 3.3.2.7 EXTERIOR STAIRS, RAILS, BALCONIES/PORCHES, CANOPIES

Item	Description	Action	Condition
Balcony Framing	Not applicable	NA	Not applicable
Balcony Deck Material	Not applicable	NA	Not applicable
Balcony Railing	Not applicable	NA	Not applicable
Patio Construction	Not applicable	NA	Not applicable
Terraces	Not applicable	NA	Not applicable
Fire Escapes	Not Applicable	NA	Not applicable
Elevated Walkway	Not applicable	NA	Not applicable
Exterior Stairs	Not applicable	NA	Not applicable

### 3.3.2.8 EXTERIOR DOORS & ENTRY SYSTEMS

Item	Description	Action	Condition
Unit Entry Doors	Painted wood	RR	Good
Service Doors	Not applicable	NA	Not applicable
Sliding Glass Doors	Not applicable	NA	Not applicable
Overhead Doors	Not applicable	NA	Not applicable
Common Entrance Doors	Aluminum storefront	RR	Good

### Photographs



Exterior Doors & Entry Systems: Typical unit door found throughout the site.



Exterior Doors & Entry Systems: Typical building access door found throughout the site.

### 3.3.3 SIDEWALL SYSTEM

The wood trim on the soffits throughout the site was observed damaged, weathered, and rotted. Any damaged or weathered wood trim can be a source of water intrusion and allow pests to access the building. Therefore, AEI recommends addressing any damaged sections of wood trim to maintain the building's structural integrity. (Non-Critical Repair)



Large sections of cracked brick were observed at 52-56 Summer street and other sections throughout the site. Cracks on the brick can be a source of water intrusion and allow pests to access the building. Therefore, AEI recommends addressing any damaged brick sections to maintain the building's structural integrity. (Non-Critical Repair)

Item	Description	Action	Condition
Primary Exterior Wall Finishes and Cladding	Masonry Brick (Unpainted)	IM/RR	Fair
Trim Finishes	Painted wood	IM/RR	Poor
Soffits/Eaves	Exposed	IM/RR	Poor
Sealants	Sealants are used at control joint locations of dissimilar materials as well as at windows and doors.	R&M	Good
Painting	Last painted 15 year ago.	IM/RR	Poor

### Photographs



Sidewall System: Typical sidewall unpainted brick found throughout the site.



Sidewall System: Typical sidewall unpainted brick found throughout the site.



Sidewall System: Typical sidewall unpainted brick found throughout the site.



Sidewall System: Typical sidewall unpainted brick found throughout the site.





Sidewall System: Typical cracked unpainted brick found throughout the site. (Non-Critical Repair)



Sidewall System: Typical weathered and damaged wood trim found throughout the site. (Non-Critical Repair)



Sidewall System: Typical weathered and damaged wood trim found throughout the site. (Non-Critical Repair)



Sidewall System: Typical weathered and damaged wood trim found throughout the site. (Non-Critical Repair)



Sidewall System: Typical weathered and damaged wood trim found throughout the site. (Non-Critical Repair)

## Photographs



Sidewall System: Building 2 northeast corner facade.



Sidewall System: Building 2 east facade.



Sidewall System: Building 2 southeast corner facade.



Sidewall System: Building 2 south facade.



Sidewall System: Building 2 southwest corner facade.



Sidewall System: Building 2 west internal facade.





Sidewall System: Building 1 southeast corner facade.



Sidewall System: Building 1 southwest corner facade.



Sidewall System: Building 1 west facade.



Sidewall System: Building 1 west facade.



Sidewall System: Building 1 northwest corner facade.



Sidewall System: Building 1 northeast internal corner facade.



Sidewall System: Building 3 southwest corner facade.



Sidewall System: Building 3 southwest corner facade.



Sidewall System: Building 3 south corner facade.



Sidewall System: Building 3 west facade.



Sidewall System: Building 3 northwest corner facade.

### 3.3.3.1 WINDOWS

Item	Description	Action	Condition
Window Type	Single hung windows	RR	Good



Item	Description	Action	Condition
Window Frame	Aluminum frame	RR	Good
Window Panes	Double pane insulated	RR	Good

### Photographs



Windows: Typical single-hung style double-pane aluminum windows found throughout the site.



Windows: Typical single-hung style double-pane aluminum windows found throughout the site.

### 3.3.4 ROOFING FINISH

Roof ID	Construction Type	Approx. Area	Reported Age	RUL	Warranty	Action	Condition
All	Pitched with asphalt shingles	22,342 SF	17 years	3 years	No	RR	Fair

Roof ID	Drainage	Coping (parapet)	Skylights	Action	Condition
All	Gutters and downspouts	Not applicable	Not applicable	RR	Fair

## Photographs



Roofing Finish: Typical asphalt shingle roofing found throughout the site.



Roofing Finish: Typical asphalt shingle roofing found throughout the site.



Roofing Finish: Typical gutters and downspouts found throughout the site.



Roofing Finish: Typical gutters and downspouts found throughout the site.

## 3.4 MECHANICAL & ELECTRICAL SYSTEMS

### 3.4.1 PLUMBING

Sections of pipe corrosion were observed in the basement on 15-19 Basketfield st. The pipes showed signs of deterioration that will cause significant leaks in the short term. Therefore, AEI recommends addressing the issue causing the corrosion and replacing any damaged piping sections. (Non-Critical Repair)

Several tenants reported that the property has boiling water issues when turned low. Boiling hot water increases suddenly and burns the tenants while bathing or doing the dishes. AEI recommends having a certified plumber assess the system to ensure all valves are working correctly. (Non-Critical Repair)

Several tenants reported that the property has sewer issues. Tenants reported constant backing up and sewage coming out of the drains. AEI recommends having a certified plumber assess the system to ensure the sewer system is working correctly. (Non-Critical Repair)

Item	Description	Action	Condition
Hot and Cold Water Distribution	Copper pipe	IM/RR	Fair/Poor
Polybutylene Water Piping	No polybutylene piping was observed or reported.	NA	Not applicable
Sanitary Waste and Vent	Cast iron and PVC pipes	IM	Poor
Domestic Water Circulation Pumps	Four (4) water circulation pumps on site	RR	Good
Domestic Water Heaters	Not applicable	NA	Not applicable
Domestic Water Boilers	Central high-efficiency boiler with separate storage tank	IM/RR	Good
Boiler Peripherals	Not applicable	NA	Not applicable
Water Softening / Treatment	Not applicable	NA	Not applicable

### Photographs



Plumbing: Typical cast iron and PVC waste pipes found throughout the property.



Plumbing: Typical cast iron and PVC waste pipes found throughout the property.





Plumbing: Typical cast iron and PVC waste pipes found throughout the property.



Plumbing: Typical corroded pipes found throughout the property. (Non-Critical Repair)



Plumbing: Typical corroded pipes found throughout the property. (Non-Critical Repair)



Plumbing: Typical corroded pipes found throughout the property. (Non-Critical Repair)




Central gas-fired boilers found on the property.



Plumbing: Storage tanks found on the property.





Plumbing: Circulation pumps found on the property.

### 3.4.2 HVAC SYSTEMS

Item	Description	Action	Condition
Cooling Equipment	Individual Window-mounted Air-Conditioners Tenant-owned.	R&M	Good/Fair
Heating Equipment	Central Hydronic Boiler with Radiator distribution	RR	Good/Fair
Cooling Tower	Not applicable	NA	Not applicable
Terminal Units	Baseboard radiant heaters	RR	Good/Fair
Tonnage of Cooling Equipment	1 condenser unit with a rated capacity of 3 tons	RR	Good/Fair
Distribution System	Plumbing lines for heating system	RR	Good/Fair
Controls	Individual controls on each mechanical unit	R&M	Good
Supplemental Systems	Not applicable	NA	Not applicable
Corridor and Stair-tower Ventilation	Not applicable	NA	Not applicable
Toilet Room Ventilation	Not applicable	NA	Not applicable

## Photographs



HVAC Systems: Typical tenant owned window unit AC system found throughout the site.



HVAC Systems: Typical tenant owned window unit AC system found throughout the site.




HVAC Systems: Typical tenant owned window unit AC system found throughout the site.



HVAC Systems: 3 ton AC system found at the community room.



Central gas boilers found on the property.



Central gas boilers found on the property.



Central gas-fired boilers found on the property.



HVAC Systems: Typical hydronic radiant heater found in dwelling units throughout the property.

### 3.4.3 ELECTRICAL SYSTEM

Item	Description	Action	Condition
Service Type	Underground lines to pad-mounted transformers	R&M	Good
Building Service	1600-Amp, 120/240-Volt, three-phase, four-wire, alternating current (AC)	R&M	Good
Typical Tenant Service Amperage	70 Ampere breaker panel	RR	Fair
Panel Manufacturer	Square D	RR	Fair
Overload Protection	Circuit breaker switches	R&M	Good
Service Wire	Copper wiring	R&M	Good
Branch Wiring	Copper wiring	R&M	Good
Ground Fault Circuit Interrupter	Observed in kitchen, bathrooms, and wet areas	R&M	Good

### Photographs



Electrical System: Typical electric meter bank found throughout the site.



Electrical System: Central electric meter found at the site.





During the assessment, AEI was informed that the emergency pull cords in the bathrooms were not functioning. Therefore, AEI recommends repairing any pull cords that are not performing correctly for the safety of the tenants. (Critical Repair)

Item	Description	Condition	Action
Fire Suppression Systems	Not applicable	Not applicable	NA
Fire Suppression System Inspection Date	Not Applicable	Not applicable	NA
Other Equipment and Devices	Illuminated exit signs Battery back up light fixtures Hard-wired and non-compliant battery powered smoke and CO detectors with battery back-up. Emergency pull-cords in the bedrooms and bathrooms.	Poor	IM
Fire Extinguishers	Mounted on common area walls Last inspection completed on February 2022	Good	R&M
Fire Alarms	Not Applicable	Not applicable	NA
Fire Alarm Inspection Date	Not Applicable	Not applicable	NA
Fire Hydrants	There are fire hydrants located along the drive lanes	Good	R&M
Fire Egress Stairs	The buildings feature interior staircase towers	Not applicable	NA

### Photographs




Life & Fire Safety: Typical emergency lighting found throughout the site.



Life & Fire Safety: Typical illuminated exit sign found throughout the site.



Life & Fire Safety: Typical non-compliant smoke detector found throughout the site. (Critical Repair)



Life & Fire Safety: Typical non-compliant smoke detector found throughout the site. (Critical Repair)



Life & Fire Safety: Typical fire extinguisher found throughout the site.

### 3.7 INTERIOR ELEMENTS

#### 3.7.1 COMMON AREA INTERIOR ELEMENTS

The majority of the hallway staircases were observed with worn down or damaged finishes. Therefore, sanding and repainting the railings and replacing all floor and wall finishes are recommended. (Non-Critical Repair)

Item	Description	Action	Condition
Community Room	A community room with numerous chairs, tables, and accessories is located in the community building. Finishes include vinyl flooring with painted drywall walls and ceilings.	RR	Good
Community Kitchen	A community kitchen with numerous appliances and accessories is located in the community building. Finishes include vinyl flooring with painted drywall walls and ceilings.	RR	Good

Item	Description	Action	Condition
Common Area Laundry	A common laundry room with numerous washers and dryers is located in the community building. Finishes include vinyl flooring with painted drywall walls and ceilings.	RR	Good

**Photographs**



Common Area Interior Elements: Community room.



Common Area Interior Elements: Community room.



Common Area Interior Elements: Common laundry room.



Common Area Interior Elements: Community Kitchen.





Common Area Interior Elements: Typical staircase with worn down finishes found throughout the site. (Non-Critical Repair)



Common Area Interior Elements: Typical staircase with worn down finishes found throughout the site. (Non-Critical Repair)



Common Area Interior Elements: Typical staircase with worn down finishes found throughout the site. (Non-Critical Repair)

### 3.7.2 DWELLING UNIT INTERIOR ELEMENTS

The flooring and some of the finishes in unit 35 were removed due to hazmat concerns after the death of a person occurred in the unit. AEI was informed that the property got the all-clear to address all repairs in the unit. Therefore, AEI recommends that the work be completed, and proof of occupancy be provided. (Critical Repair)

Units 4 and 20 were observed with damaged finishes ranging from damaged doors, wood flooring, vinyl flooring, and paint. The tenants reported that the damages were present when they moved in, and work orders had been issued. AEI recommends addressing this and any other work order that has not been addressed. (Non-Critical Repair)

Large areas of damaged sheetrock ceilings were observed in 2 Annapolis and 6-8 Annapolis. These damages were caused because of leaking pipes. The site ensures AEI that all repairs have been concluded. Therefore, AEI recommends replacing all the damaged sheetrock and installing a new ceiling where needed. (Non-Critical Repair)

#### Unit Finishes

Item	Description	Action	Condition
Carpet	Not applicable	NA	Not applicable
Resilient Flooring (vinyl)	Vinyl tile	IM/RR	Fair/Poor
Other	Wood laminate	IM/RR	Fair
Walls	Gypsum board with painted finish	R&M	Good/Fair
Ceilings	Gypsum board with painted finish	R&M	Good/Fair
Window Coverings	Window blinds are provided	R&M	Good/Fair

#### Photographs



Dwelling Unit Interior Elements: Typical wood laminate flooring and sheetrock finish found in dwelling units throughout the site.



Dwelling Unit Interior Elements: Typical vinyl flooring and sheetrock finish found in dwelling units throughout the site.



Dwelling Unit Interior Elements: Typical tile flooring and sheetrock finish found in dwelling units throughout the site.




Dwelling Unit Interior Elements: Removed flooring and finishes due to decomposing body removal. (Critical Repair)



Dwelling Unit Interior Elements: Damaged finishes observed in unit 4. (Non-Critical Repair)



Dwelling Unit Interior Elements: Damaged finishes observed in unit 4. (Non-Critical Repair)



Dwelling Unit Interior Elements: Damaged finishes observed in unit 4. (Non-Critical Repair)



Dwelling Unit Interior Elements: Damaged finishes observed in unit 4. (Non-Critical Repair)





Dwelling Unit Interior Elements: Damaged finishes observed in unit 20. (Non-Critical Repair)



Dwelling Unit Interior Elements: Damaged finishes observed in unit 20. (Non-Critical Repair)



Dwelling Unit Interior Elements: Damaged finishes observed in unit 20. (Non-Critical Repair)



Dwelling Unit Interior Elements: Damaged finishes observed in unit 20. (Non-Critical Repair)



Dwelling Unit Interior Elements: Damaged finishes observed in unit 20. (Non-Critical Repair)



Dwelling Unit Interior Elements: Damaged finishes observed in unit 20. (Non-Critical Repair)






Dwelling Unit Interior Elements: Damaged finishes observed in unit 20. (Non-Critical Repair)



Dwelling Unit Interior Elements: Typical damaged sheetrock ceilings found throughout the site. (Non-Critical Repair)



Dwelling Unit Interior Elements: Typical damaged sheetrock ceilings found throughout the site. (Non-Critical Repair)

*Appliances*

<b>Item</b>	<b>Description</b>	<b>Action</b>	<b>Condition</b>
Refrigerators	Units vary in age and condition	RR	Good/Fair
Ranges	Units vary in age and condition	RR	Good/Fair
Range hoods	Not applicable	NA	Not applicable
Dishwashers	Not applicable	NA	Not applicable
Microwaves	Not applicable	NA	Not applicable
Garbage Disposals	Not applicable	NA	Not applicable
Dryers	Not applicable	NA	Not applicable
Washers	Not applicable	NA	Not applicable
Washer/Dryer Connection	Not applicable	NA	Not applicable

## Photographs



Appliances: Typical range found throughout the site.



Appliances: Typical appliance package found throughout the site.

### Cabinets & Fixtures

Item	Description	Action	Condition
Kitchen Sink & Countertop	Plastic laminated particle board	RR	Good/Fair
Bathroom Sink and Countertop	Wall mounted porcelain sink	RR	Fair
Kitchen Cabinetry	Wood frame with solid wood doors	RR	Good/Fair
Bathroom Cabinetry	Not applicable	NA	Not applicable
Bathtub/Shower and Enclosure	Enamel over steel bathtub with ceramic tile tub surround	RR	Fair
Toilet	Water saver toilet	RR	Fair
Accessories	Medicine cabinet	RR	Fair
	Towel bars		
	Wall mounted mirror		

## Photographs



Cabinets & Fixtures: Typical dwelling unit kitchen sink, countertop, and wood cabinets found throughout the site.



Cabinets & Fixtures: Typical dwelling unit kitchen sink, countertop, and wood cabinets found throughout the site.



Cabinets & Fixtures: Typical dwelling unit kitchen sink, countertop, and wood cabinets found throughout the site.



Cabinets & Fixtures: Typical dwelling unit porcelain sink and toilet found throughout the site.



Cabinets & Fixtures: Typical dwelling unit enamel tub and tile surround found throughout the site.

DRAFT



## 4.0 ADDITIONAL CONSIDERATIONS

---

### 4.1 MOISTURE AND MICROBIAL GROWTH

Microbial growth (e.g., mold or fungus) may occur when excess moisture is present. Porous building materials such as gypsum board, insulation in walls and ceilings, and carpeting retain moisture and become microbial growth sites if moisture sources are not controlled or mitigated. Potential sources of moisture include rainwater intrusion, groundwater intrusion, condensation on cold surfaces, and water leaks from building systems (e.g., plumbing leaks, HVAC system leaks, overflowing drains, etc.). Inadequate ventilation of clothes dryers and shower stalls may also result in excess moisture conditions. Microbial growth may be clearly visible (e.g., ceramic tile mortar in shower stalls) or may be concealed with no visible evidence of its existence (e.g., inside wall cavities). However, without proper tests, the existence of mold cannot be verified. Testing for mold is outside the scope of a base-line PNA.

AEI conducted a limited visual survey for the presence of microbial growth at the Property. Sampling or testing was not included in the scope of work for this survey. The assessment consisted of gaining entry to interior spaces, and visually evaluating the accessible areas.

### ASSESSMENT / RECOMMENDATION

Suspect Mold growth was observed in a large number of pipes in many of the basements. Therefore, EAI recommends addressing any suspect Mold growth throughout the property for safety reasons. (Critical Repair)

### Photographs



Moisture and Microbial Growth: Mold on water pipes observed throughout the site. (Critical Repair)



Moisture and Microbial Growth: Mold on water pipes observed throughout the site. (Critical Repair)

## 4.2 PEST MANAGEMENT

As part of the site and property assessment, AEI conducted limited, visual, non-intrusive observations to ascertain if there was evidence of wood destroying organism (WDO) activity on the physical structures at the Property during our site visit. Our WDO assessment process included visual observation of select interior and exterior building systems for noticeable signs of WDO activity, such as damaged or deteriorated wood, noticeable remnants of deceased WDO's (termites, beetles, ants, bees, etc.), and applying hand pressure (with a hard object tool) to reachable areas where these types of organisms generally attack to determine if there is any hidden damage to such surfaces (surfaces generally limited to trim work along baseboards and around windows).

Our WDO assessment process also included a limited visual and physical assessment of easily accessible and observable site conditions. The visual assessment included looking for noticeable signs of WDO activity on the Property, such as mud tubes on walls, round or oval holes, mounded soil around building perimeters, trace insect residue, and damaged wood. Our observations of exterior materials also include the application of hand pressure to reachable areas where these types of organisms generally attack, to determine if there is any hidden damage to such surfaces. This information is provided incidental to our standard PNA assessment. WDO observations, conducted by AEI, are not intended, and may not be interpreted as a professional pest inspection, and AEI makes no representation or warranty as to these activities or observations.

Our WDO assessment did not identify any unusual problems or concerns related to WDO activity on the property.

### ASSESSMENT / RECOMMENDATION

No unusual problems or concerns with termites or wood destroying organisms were reported or observed.

No repair or reserve funding is recommended at this time.

## 4.3 SEISMIC ZONE

AEI reviewed the property location in order to determine whether or not the site is located in an area that may constitute a seismic hazard as determined by the ASCE/SEI Standard ASCE 41-13 "Seismic Evaluation and Retrofit of Existing Buildings. The determination employs output from design mapping with data provided from the US Geological Survey.

Per HUD MAP Guide (revised March 19, 2021), any detached or semi-detached structure where the calculated Design Earthquake Spectral Response Acceleration Parameter ( $S_{XS}$ ) is less than .400g and any building where both Design Earthquake Spectral Response Acceleration Parameters ( $S_{XS}$  and  $S_{X1}$ ) are less than .330g and .133g respectively, a detailed seismic hazard and building performance analysis is not required.

The values for  $S_{XS}$  and  $S_{X1}$  have been provided as output from a Design Maps Summary Report as derived from current USGS data.

A copy of the USGS data is included in the USGS Design Maps Appendix.

The value for  $S_{XS}$  was calculated at less than 0.330g.

The value for  $S_{X1}$  was calculated at less than 0.133g.

## **ASSESSMENT / RECOMMENDATION**

There are no further recommendations.

### **4.4 WIND ZONE**

AEI reviewed the property location in order to determine the wind zone in which the property is located. The Design Wind Speed measuring criteria are consistent with ASCE 7-05. Our judgement is that the property is located in Wind Zone IV. This map also indicates that the Property is also located in a Hurricane Susceptible Region.

Wind Zones are defined as follows:

**Zone I** (130 MPH)

**Zone II** (160 MPH)

**Zone III** (200 MPH)

**Zone IV** (250 MPH)

**Special Wind Zone**

**Hurricane Susceptible Zone**

### **4.5 FLOOD PLAIN**

AEI reviewed FEMA flood zone maps to identify the flood zone in which the property is located. According to Panel No. 25025C0083J, dated 03/16/2016, this property is located within Flood Zone X (Non-shaded).

Flood Zones are described as follows:

**Flood Zone A**, defined as an area of 100-year flood; base flood elevations and flood hazard factors not determined.

**Flood Zone AE**, defined as an area of 100-year flood; base flood elevation determined.

**Flood Zone B**, defined as an area between limits of the 100-year flood and 500-year flood; an area subject to 100-year flooding with average depths less than one foot or where the contributing drainage area is less than one square mile; or an area protected by levees from the base flood.

**Flood Zone C**, defined as an area of minimal flooding.

**Flood Zone D**, defined as an area of undetermined, but possible flood hazards.

**Flood Zone V**, defined as an area of 100-year flood with velocity (wave action); base flood elevations and flood hazard factors not determined.

**Flood Zone X (shaded area)**, defined as an area of 500-year flood; an area of 100- year flood with average depths of less than one foot or with drainage areas less than one square mile; or an area protected by levees from 100-year flood.

**Flood Zone X (non-shaded area)**, defined as an area outside the 500-year flood plain.

This information is provided for reference purposes only. Further Study may be undertaken at the discretion of our client.

#### 4.6 KNOWN PROBLEMATIC BUILDING MATERIALS

The following list of Known Problematic Building Materials has been developed by Fannie Mae and is typically referenced in CNA reports as a general summary of systems or organisms that have been part of a manufacturer recalled or have been specifically identified as problematic. If these items are identified through reports or observation, the topic will be further discussed in the report sections listed in the following table:

Red Flag Material or System	Identified	Action Recommended
Fire Retardant Treated Plywood (FRTP)	No	Not applicable
Compressed Wood or Composite Board Siding	No	Not applicable
Exterior Insulation and Finishing (EIFS)	No	Not applicable
Problem Drywall (aka "Chinese Drywall")	No	Not applicable
Unit electrical capacity less than 60 amps	No	Not applicable
Electrical Overload Protection - Fused Subpanels	No	Not applicable
Federal Pacific Electric Stab-Lok panels	No	Not applicable
Polybutylene Water Distribution Lines	No	Not applicable
Galvanized Steel Water Distribution Lines	No	Not applicable
Recalled fire sprinkler heads (Central, Omega, Gem, Star)	No	Not applicable
Recalled Cadet Brand Electric in-Wall Heaters	No	Not applicable
Recalled General Electric / Hotpoint dishwashers	No	Not applicable
Microbial Growth	Yes	Repair
Wood Destroying Organisms	No	Not applicable



## 5.0 DOCUMENT REVIEW & INTERVIEWS

### 5.1 DOCUMENTS REVIEWED

Document	Source / Author	Date
Construction Drawings	John M. Gray Co. Architects	02/17/1961
Rent Roll	Managment	Unknown

### 5.2 INTERVIEWS

Contact Name	Contact Title	Contact Phone	Information Source Provided
Mrs. Lynne Jones	Property Manager	(617)-438-1136	Provided interview and conducted the site visit
Mr. Mark Harris	Maintenance Supervisor	(617)-596-7983	Provided interview and conducted the site visit

### 5.3 BUILDING CODE COMPLIANCE

AEI requested a record of open violations on file for the Property from the City of Dorchester Building Department.

As of the date of this report, a written response has not been provided. AEI will continue to follow-up with the respective parties and will forward information received separately as soon as it has been received.

### 5.4 FIRE CODE COMPLIANCE

AEI requested a record of open violations on file for the Property from the City of Dorchester Fire Department.

As of the date of this report, a written response has not been provided. AEI will continue to follow-up with the respective parties and will forward information received separately as soon as it has been received.

### 5.5 ZONING COMPLIANCE

The property is zoned MFR: Multifamily Residential and based on online research.

### 5.6 HUD REAL ESTATE ASSESSMENT CENTER (REAC) INSPECTION

Information not provided.

## 6.0 ACCESSIBILITY & INTRUSIVE EXAMINATIONS

### 6.1 ACCESSIBILITY

#### *Determination of ADA, UFAS, FHA Applicability*

<b>Application</b>	<b>Yes/No</b>	<b>Definition</b>
<b>Age:</b> Was this property constructed after July 1992? (ADAAG Question)	No	Under Title III of the ADA, all "new construction" (construction, modification, or alterations) after the effective date of the ADA (approx. July 1992) must be fully compliant with the ADAAG.
<b>Use:</b> Does the property feature areas of public accommodation? (ADAAG Question)	Yes, leasing office	A public accommodation is a private entity that owns, operates, leases, or leases to a place of public accommodation. Places of public accommodation include restaurants, hotels, theaters, doctor's offices, pharmacies, retail stores, museums, libraries, parks, private schools, and day care centers, and entities that offer certain examinations and courses related to educational or occupational certification.
<b>Use:</b> Is the property classified as a historic structure? (ADAAG Question)	No	Properties listed or are eligible for listing in the National Register of Historic Places or properties designated as historic under state or local law should comply to the "maximum extent feasible" unless the changes would destroy the historic significance of a feature of the building.
<b>Use:</b> Is the property classified as a private club or religious structure? (ADAAG Question)	No	Properties classified as such are exempt from complying with the ADAAG.
<b>Use:</b> Does the property plan a significant renovation that is at least 20% of the value of the building? (If so, the renovation budget should include upgrades to correct all ADA issues). (ADAAG Question)	No	Alterations include, but are not limited to, remodeling, renovation, rehabilitation, reconstruction, historic restoration, changes or rearrangement in structural parts or elements, and changes or rearrangement in the plan configuration of walls and full-height partitions.  Normal maintenance, reroofing, painting or wallpapering, asbestos removal, or changes to mechanical and electrical systems are not alterations unless they affect the usability of the building or facility.
<b>Use:</b> Does the property feature federal financial assistance? (UFAS Question)	Yes	Section 504 of the Rehabilitation Act of 1973 states: No otherwise qualified individual with a disability in the United States. . .shall, solely by reason of her or his disability, be excluded from participation in, be denied the benefits of, or be subjected to discrimination under any program, service or activity receiving federal financial assistance or under any program or activity conducted by any Executive agency or by the United States Postal Service. (29 U.S.C. 794). This

Application	Yes/No	Definition
		means that Section 504 prohibits discrimination on the basis of disability in any program or activity that receives financial assistance from any federal agency, including the U.S. Department of Housing and Urban Development (HUD) as well as in programs conducted by federal agencies including HUD.
<b>Age:</b> Was this property constructed prior to July 11, 1988? (UFAS Question)	Yes	While UFAS is still applicable for all project based properties; HUD has allowed for load bearing wall, financial, and administrative burden exceptions to retroactively achieving UFAS compliance.
<b>Age:</b> Was this property constructed after March 13, 1991? (FHA Question)	No	Multi-family properties constructed after March 13, 1991 should be in compliance with the Fair Housing Act Accessibility Guidelines. There are select exceptions.
<b>Age:</b> Was this property provided original building permits after June 15, 1990? (FHA Question)	No	Buildings where the last building permit was issued on or before June 15, 1990 are not covered by the design and construction requirements. Even if the last building permit was issued after June 15, 1990, if the property was occupied before March 13, 1991, it is not covered. HUD adopted these dates to allow time for the requirements to be considered during the design and construction phase of new properties.

*Abbreviated Screening Checklist for ADAAG Compliance*

	<b>Building History</b>	Yes	No	N/A	Comments
1.	Has an ADA survey previously been completed on the property?		✓		No previous ADA Survey for the property was provided or reported.
2.	Have any ADA improvements been made to the property?		✓		
3.	Does a Transition Plan / Barrier Removal Plan exist for the property?		✓		
4.	Has building ownership or management received any ADA-related complaints that have not been resolved?		✓		
5.	Is any litigation pending related to ADA issues?		✓		
<b>Parking</b>					
1.	Are there sufficient accessible parking spaces with respect to the total number of reported spaces?	✓			10 total spaces 2 designated accessible spaces
2.	Are there sufficient van-accessible parking spaces available (96" wide aisle for van)?	✓			1 van-accessible space is provided
3.	Are accessible spaces marked with the International Symbol of Accessibility? Are there signs reading "Van Accessible" at van spaces?	✓			

<b>Building History</b>		<b>Yes</b>	<b>No</b>	<b>N/A</b>	<b>Comments</b>
4.	Is there at least one accessible route provided within the boundary of the site from public transportation stops, accessible parking spaces, passenger loading zones, if provided, and public streets and sidewalks?	✓			
5.	Do curbs on the accessible route have depressed, ramped curb cuts at drives, paths, and drop-offs?	✓			
6.	If required does signage exist directing you to accessible parking and an accessible building entrance?	✓			
<b>Ramps</b>					
1.	Do all ramps along accessible path of travel appear to meet slope requirements? (1:12 or less) Please note shorter ramps can be more steep than 1:12 if rise is less than 6-inches.	✓			
2.	Are ramps that appear longer than 6 ft complete with railings on both sides?	✓			
3.	Does the width between railings appear to be at least 36 inches?	✓			
4.	Are the cross slopes less steep than 1:48?	✓			
5.	Do the ramp runs rise no more than 30-inches?	✓			
6.	Are there level landings at the bottom and top of the ramp runs?	✓			
<b>Entrances/Exits</b>					
1.	Do all required accessible entrance doorways appear at least 32 inches wide and not a revolving door?	✓			
2.	If the main entrance is inaccessible, are there alternate accessible entrances?	✓			
3.	Is the door hardware easy to operate (lever/push type hardware, no twisting required and not higher than approximately 48 inches above the floor)?	✓			
<b>Paths of Travel</b>					
1.	Are all paths of travel free of obstruction and wide enough for a wheelchair (appear at least 36 inches wide)?	✓			
2.	Are wheelchair-accessible facilities (toilet rooms, exits, etc.) identified with signage?	✓			
3.	Is there a path of travel that does not require the use of stairs?	✓			



	Building History	Yes	No	N/A	Comments
<b>Elevators</b>					
1.	Do the call buttons have visual and audible signals to indicate when a call is registered and answered when car arrives?			✓	
2.	Are there visual and audible signals inside cars indicating floor change?			✓	
3.	Are there standard raised and Braille marking on both jambs of each hoist way entrance as well as all cab/call buttons?			✓	
4.	Do elevator doors have a reopening device that will stop and reopen a car door if an object or a person obstructs the door?			✓	
5.	Are elevator controls low enough to be reached from a wheelchair (appears to be between 15 and 48 inches)?			✓	
6.	If a two-way emergency communication system is provided within the elevator cab, is it usable without voice communication?			✓	
<b>Toilet Rooms</b>					
1.	Are common area public restrooms located on an accessible route?	✓			
2.	Are pull handles push/pull or lever type?	✓			
3.	Are toilet room access doors wheelchair-accessible (appear to be at least 32 inches wide)?	✓			
4.	Are public restrooms large enough to accommodate a wheelchair turnaround (appear to have 60"• turning diameter)?	✓			
5.	Are toilet stall doors wheelchair accessible (appear to be at least 32"• wide)?			✓	
6.	Are grab bars provided in toilet stalls?	✓			
7.	Are sinks provided with clearance for a wheelchair to roll under?	✓			
8.	Are sink handles operable with one hand without grasping, pinching or twisting?		✓		The common restroom sink was observed with knob-style hardware.
9.	Are exposed pipes under sink sufficiently insulated against contact?	✓			
<b>Pools</b>					
1.	Are public access pools provided? If the answer is no, please disregard this section.			✓	
2.	How many accessible access points are provided to each pool/spa? Provide number in comment field.			✓	

Abbreviated Screening Checklist for UFAS Compliance

	<b>Building History</b>	<b>Yes</b>	<b>No</b>	<b>N/A</b>	<b>Comments</b>
<b>Common Area Paths of Travel</b>					
1.	Are all paths of travel free of obstruction and wide enough for a wheelchair?	✓			
2.	Do the common laundry rooms have a front controlled washing machine?	✓			
3.	Is there a path of travel that does not require the use of stairs to get to all common areas?	✓			
<b>Play Area</b>					
1.	Are the common area playgrounds accessible by wheelchair?			✓	
<b>Designated Handicapped Dwelling Units</b>					
1.	Do the unit entrance doors as well as the bathroom and bedroom doors feature 32" clear openings and low entrance thresholds for wheelchair access?			✓	The property does not feature any mobility or sensory units.
2.	Do all accessible doors have adequate space provided at latch side of door (see UFAS Figure 25)?			✓	
3.	Are exterior balconies/decks <1/2" below interior floor level?			✓	
4.	Are all switches, controls and outlets located at between 15" and 54" above floor			✓	
5.	Accessible Kitchens: Is a 30x48 clear space provided at range/cooktop as well as front controls?			✓	
6.	Accessible Kitchens: Is 40" clearance provided between counters, cabinets, walls, or appliances and opposing item. Is a 60" turning radius available in U-shaped kitchens if sink or range/cooktop is located at base of U? Are the sinks roll-under for a 30"x48" forward approach?			✓	
7.	Accessible Kitchens: Are the countertops and sinks lowered from 36" to approximately 34"?			✓	
8.	Accessible Bathrooms: Do the bathrooms feature adequate clear floor space to each of the fixtures?			✓	
9.	Accessible Bathrooms: Do the bathrooms feature accessible accessories (levered hardware, shower hoses, shower chairs or benches, lowered mirrors etc)?			✓	

Abbreviated Screening Checklist for FHA Compliance

Building History		Yes	No	N/A	Comments
<b>Fair Housing Act Accessibility Review</b>					
1.	<b>Requirement 1. Are there accessible building entrances on an accessible route?</b> All covered multifamily dwellings must have at least one accessible building entrance on an accessible route unless it is impractical to do so because of the terrain or unusual characteristics of the site.			✓	
2.	<b>Requirement 2. Are the public and common use areas accessible?</b> Covered housing must have accessible and usable public and common-use areas. Public and common-use areas cover all parts of the housing outside individual units. They include -- for example -- building-wide fire alarms, parking lots, storage areas, indoor and outdoor recreational areas, lobbies, mailrooms and mailboxes, and laundry areas.			✓	
3.	<b>Requirement 3. Are the doors "Usable" (usable by a person in a wheelchair)?</b> All doors that allow passage into and within all premises must be wide enough to allow passage by persons using wheelchairs (32-inch nominal clearance).			✓	
4.	<b>Requirement 4. Is there an accessible route into and through the dwelling unit?</b> There must be an accessible route into and through each covered unit.			✓	
5.	<b>Requirement 5. Are the light switches, electrical outlets, thermostats and other environmental controls in accessible locations?</b> Light switches, electrical outlets, thermostats and other environmental controls must be in accessible locations.			✓	
6.	<b>Requirement 6. Are there reinforced walls in bathrooms for later installation of grab bars?</b> Reinforcements in bathroom walls must be installed, so that grab bars can be added when needed. The law does not require installation of grab bars in bathrooms.			✓	

	<b>Building History</b>	<b>Yes</b>	<b>No</b>	<b>N/A</b>	<b>Comments</b>
7.	<b>Requirement 7. Are the kitchens and bathrooms "Usable"?.</b> Kitchens and bathrooms must be usable - that is, designed and constructed so an individual in a wheelchair can maneuver in the space provided.			✓	

**RECOMMENDATIONS**

**ADAAG Concerns:**

- The common restroom sink was observed with knob-style hardware. Accessibility standards require all sink hardware to be levered style hardware. AEI recommended replacing existing sink hardware to comply with accessibility design standards. (Critical Repair)

**UFAS/State Code Concerns:**

- UFAS does apply but there are no dedicated mobility units or sensory units. It is AEI's understanding that the subject property is part of a portfolio of properties that, when added together, meet the requirement of 5% mobility and 2% sensory units as stipulated per section 504 requirements.

If the property were to be separate from the portfolio during a RAD transaction than a UFAS feasibility study would have to be performed at the property. There are steps leading into all sections of the building, as a result, it is not realistic that UFAS compliant could be achieved at the property.

**FHA Design Concerns:**

The property was built before March 13, 1991, and therefore FHA Design does not apply.



## Photographs



UFAS Concern: Common accessible restroom without levered sink hardware. (Critical Repair)

## 6.2 INTRUSIVE EXAMINATIONS

### 6.2.1 SEWER INSPECTION

No sewer inspections were performed as part of this investigation.

### 6.2.2 ELECTRICAL INSPECTION

No electrical inspections were performed as part of this investigation.

## 6.3 OWNER PROPOSED IMPROVEMENTS

There are no additional owner proposed improvements.

## 7.0 OPINIONS OF PROBABLE COST

---

### 7.1 FINANCIAL RECAP

*Replacement Reserve Summary Table*

<b>Replacement Reserve Schedule Term/Inflation Status</b>	<b>Replacement Reserve Schedule Summary Costs</b>	<b>Replacement Reserve Schedule Summary Costs/Per Unit Per Annum</b>
1-10 Year Un-Inflated Costs	\$1,892,339	\$3,379
1-10 Year Inflated Costs	\$2,217,970	\$3,961
11-20 Year Un-Inflated Costs	\$1,433,005	\$2,559
11-20 Year Inflated Costs	\$2,047,958	\$3,657
1-20 Year Un-Inflated Costs	\$3,325,345	\$2,969
1-20 Year Inflated Costs	\$4,265,927	\$3,809

### 7.2 CRITICAL REPAIRS

CRITICAL REPAIRS								
Need Category	Component	Repair or Replacement Location	Classification of Work	Quantity	Unit of Measure	Unit Cost	Total	Comments
<b>CRITICAL REPAIRS (ACCESSIBILITY)</b>								
Common area bath accessories (towel bars, grab bars, toilet stalls, etc.)	Accessible Common Restroom Sink Hardware (Critical Repair)	Common Accessible Restroom	Repair	1	Each	\$ 150.00	\$ 150.00	The common restroom sink was observed with knob-style hardware. Accessibility standards require all sink hardware to be levered style hardware. AEI recommended replacing existing sink hardware to comply with accessibility design standards.
<b>CRITICAL REPAIRS (LIFE SAFETY)</b>								
Residential smoke detectors	Install HUD Compliant Smoke Detectors (Critical Repair)	General Site	Repair	114	Each	\$ 25.00	\$ 2,850.00	A large portion of the apartment units were observed with 9-volt battery smoke detectors in the living room. The installation of HUD compliant 10-year life, tamper proof battery powered smoke detectors or hardwired smoke detectors is required. HUD additionally requires that smoke detectors be installed in all living areas. At the moment of the assessment, there were no smoke detectors in the bedrooms. Installation of HUD-compliant smoke detectors in all bedrooms is required.
Call station	Repair Emergency Call System (Critical Repair)	General Site	Repair	56	Each	\$ 300.00	\$ 16,800.00	During the assessment, AEI was informed that the emergency pull cords in the bathrooms were not functioning. Therefore, AEI recommends repairing any pull cords that are not performing correctly for the safety of the tenants.
Mold-treat-remediate	Treat Mold (Critical Repair)	Pipes in Basements	Repair	3	Each	\$ 2,000.00	\$ 6,000.00	Suspect Mold growth was observed in a large number of pipes in many of the basements. Therefore, EAI recommends addressing any suspect Mold growth throughout the property for safety reasons.
Cabinets & vanities	Refinish Down Unit (Critical Repair)	Unit 35	Repair	1	Each	\$ 10,000.00	\$ 10,000.00	The flooring and some of the finishes in unit 35 were removed due to hazmat concerns after the death of a person occurred in the unit. AEI was informed that the property got the all-clear to address all repairs in the unit. Therefore, AEI recommends that the work be completed, and proof of occupancy be provided.
Wood, timbers, dimensioned lumber, laminated beams, trusses	Hire Structural Engineer (Critical Repair)	Basements	Repair	1	Each	\$ 6,000.00	\$ 6,000.00	AEI observed significant concrete cracking and splitting at the basements throughout the site. This may be a sign of a structural problem with the concrete structure. AEI recommended having a structural engineer assess this issue for safety reasons.

Accessibility Subtotal: \$ 150.00  
 Life Safety Subtotal: \$ 41,650.00  
**Total: \$ 41,800.00**

### 7.3 NON-CRITICAL REPAIRS

DRAFT



NON-CRITICAL REPAIRS								
Need Category	Component	Repair or Replacement Location	Classification of Work	Quantity	Unit of Measure	Unit Cost	Total	Comments
Fascia, Wood, Vinyl	Repair Damaged Wood Trim (Non-Critical Repair)	General Site	Repair	1683	SF	\$ 20.00	\$ 33,660.00	The wood trim on the soffits throughout the site was observed damaged, weathered, and rotted. Any damaged or weathered wood trim can be a source of water intrusion and allow pests to access the building. Therefore, AEI recommends addressing any damaged sections of wood trim to maintain the building's structural integrity.
Retaining Walls, treated timber	Repair Brick Wall (Non-Critical Repair)	Brick Wall North Side of Property	Repair	283	SF	\$ 10.00	\$ 2,830.00	The perimeter brick wall located on the north side of the property was observed damaged, with sections of plaster missing or falling off. AEI recommends repairing the perimeter wall to prevent further damage.
Brick/block veneer	Repoint Brick Veneer (Non-Critical Repair)	General Site	Repair	2500	SF	\$ 10.00	\$ 25,000.00	Large sections of cracked brick were observed at 52-56 Summer street and other sections throughout the site. Cracks on the brick can be a source of water intrusion and allow pests to access the building. Therefore, AEI recommends addressing any damaged brick sections to maintain the building's structural integrity.
Drywall - Common	Replace Damaged Sheetrock Ceilings (Non-Critical Repair)	2 Annapolis and 6-8 Annapolis	Repair	2	Each	\$ 4,000.00	\$ 8,000.00	Large areas of damaged sheetrock ceilings were observed in 2 Annapolis and 6-8 Annapolis. These damages were caused because of leaking pipes. The site ensures AEI that all repairs have been concluded. Therefore, AEI recommends replacing all the damaged sheetrock and installing a new ceiling where needed.
Galvanized pipe, supply	Address Pipe Corrosion (Non-Critical Repair)	15-19 Basketfield St.	Repair	1	Each	\$ 15,000.00	\$ 15,000.00	Sections of plumbing pipe corrosion were observed in the basement on 15-19 Basketfield St. The pipes showed signs of deterioration that will cause significant leaks in the short term. Therefore, AEI recommends addressing the issue causing the corrosion and replacing any damaged piping sections.
Boilers, Oil/ Gas/ Dual Fuel, High MBH	Address Hot Water Issues (Non-Critical Repair)	Hot Water System	Repair	2	Each	\$ 5,000.00	\$ 10,000.00	Several tenants reported that the property has boiling water issues when turned low. Boiling hot water increases suddenly and burns the tenants while bathing or doing the dishes. AEI recommends having a certified plumber assess the system to ensure all valves are working correctly.
Cast iron sanitary waste	Address Sewer Lines (Non-Critical Repair)	Sewer System	Repair	3	Each	\$ 8,000.00	\$ 24,000.00	Several tenants reported that the property has sewer issues. Tenants reported constant backing up and sewage coming out of the drains. AEI recommends having a certified plumber assess the system to ensure the sewer system is working correctly.
Exterior Stairs-steel frame/stringer	Staircase Sanding and Painting (Non-Critical Repair)	General Site	Repair	32	Each	\$ 1,400.00	\$ 44,800.00	The majority of the hallway staircases were observed with worn down or damaged finishes. Therefore, sanding and repainting the railings and replacing all floor and wall finishes are recommended.
Hardwood floor (3/4" strip or parquet) - Common	Repair Damaged Unit Finishes (Non-Critical Repair)	Units 4 and 20	Repair	2	Each	\$ 3,000.00	\$ 6,000.00	Units 4 and 20 were observed with damaged finishes ranging from damaged doors, wood flooring, vinyl flooring, and paint. The tenants reported that the damages were present when they moved in, and work orders had been issued. AEI recommends addressing this and any other work order that has not been addressed.
Wood, timbers, dimensioned lumber, laminated beams, trusses	Address Structural Issues (Non-Critical Repair)	Structural Assessment Findings	Repair	1	Each	\$ 50,000.00	\$ 50,000.00	Address findings by a structural engineer to prevent future damage to the buildings.

Total: \$ 219,290.00

## 7.4 REPLACEMENT RESERVES

DRAFT



## 7.5 INSURABLE VALUE - REPLACEMENT COST

### *Replacement Cost Per Building*

<b>Building Identifier</b>	<b>Replacement Cost of Building Per SF</b>	<b>Source of Replacement Cost</b>	<b>Replacement Cost of Building</b>
Building 1	\$219	RS Means	\$3,113,085.00
Building 2	\$219	RS Means	\$3,103,887.00
Building 3	\$219	RS Means	\$2,972,487.00
		Total:	\$ 9,189,459.00

DRAFT



## 8.0 ASSESSOR QUALIFICATIONS

---

I understand that my Capital Needs Assessment will be used by Boston Housing Authority to document to the U.S. Department of Housing and Urban Development that the MAP Lender's application for FHA multifamily mortgage insurance was prepared and reviewed in accordance with HUD requirements. I certify that my review was in accordance with the HUD requirements applicable on the date of my review and that I have no financial interest or family relationship with the officers, directors, stockholders, or partners of the Borrower, the general contractor, any subcontractors, the buyer or seller of the proposed property or engage in any business that might present a conflict of interest.

I am employed full time by the MAP Lender (underwriter) or under contract for this specific assignment (as Needs Assessor) and I have no other side deals, agreements, or financial considerations with the MAP Lender or others in connection with this transaction.

I hereby certify under penalty of perjury that all of the information I have provided on this form and in any accompanying documentation is true and accurate. I acknowledge that if I knowingly have made any false, fictitious, or fraudulent statement, representation, or certification on this form or on any accompanying documents, I may be subject to criminal, civil, and/or administrative sanctions, including fines, penalties, and/or imprisonment under applicable federal law, including but not limited to 12 U.S.C. § 1833a; 18 U.S.C. §§1001, 1006, 1010, 1012, and 1014; 12 U.S.C. §1708 and 1735f-14; and 31 U.S.C. §§3729 and 3802.

The site inspection was completed on July 6, 2022

A resume of the property evaluator and the senior reviewers are included in the appendix of this report.

DRAFT

Juan Sequeira, Assessment Project Manager

DRAFT

Jeb Bonnett, Senior Vice President - HUD Building Assessments



David Taylor, Accessibility Manager

DRAFT

Roy Anderson PE, Vice President

Warning: Title 18 U.S.C. 1001, provides in part that whoever knowingly and willfully makes or uses a document containing any false, fictitious, or fraudulent statement or entry, in any manner in the jurisdiction of any department or agency of the United States, shall be fined not more than \$10,000 or imprisoned for not more than five years or both.

DRAFT

## 9.0 LIMITING CONDITIONS

---

Capital Needs Assessments performed by AEI Consultants are based upon, but not limited to, the scope of work outlined by ASTM Standard E2018-15. Our review of the subject property consisted of a visual inspection of the site, the structure(s) and the interior spaces. Technical Assessments were made based on the appearance of the improvements at the time of this Assessment. No destructive or invasive testing was included in the scope of this review.

The recommendations and conclusions presented as a result of this Assessment apply strictly to the time the Assessment was performed. Available documentation has been analyzed using currently accepted Assessment techniques and AEI believes that the inferences made are reasonably representative of the property.

No warranty is expressed or implied, except that the services rendered have been performed in accordance with generally accepted Assessment practices applicable at the time and location of the study.

This report should not be construed as technically exhaustive. This report does not warranty or guarantee compliance with any Federal, state or local statute, ordinance or regulation including but not limited to, building codes, safety codes, environmental regulations, health codes or zoning ordinances or compliance with trade/design standards or the standards developed by the insurance industry. Local, state and federal regulations, and codes change significantly over time from when the subject property was developed and the subject building was constructed. The subject property and subject building may not meet all current regulations, and code requirements put forth on a local, state, or federal level.

AEI Consultants has made reasonable efforts to properly assess the property conditions within the contracted scope of services; however, limitations during the assessment may be encountered.

AEI Consultants' findings and conclusions were based primarily on the visual assessment of the property at the time the site visit. In addition, the assessment value is based upon comparative judgments with similar properties in the property observer's experience. The Client is herewith advised that the conditions observed by AEI are subject to change. AEI's property observations included areas that were readily accessible without opening or dismantling secure areas or components. AEI's conclusions did not include any destructive or invasive testing, laboratory analysis, exploratory probing or engineering evaluations of structural, mechanical, electrical, or other systems with related calculations.

No assessment can wholly eliminate the uncertainty regarding the presence of physical deficiencies and performances of the building system. According to the ASTM guidelines, a property condition assessment is intended to reduce the risk regarding potential building system and component failure. The ASTM standard recognizes the inherent subjective nature of the assessment regarding such issues as workmanship, quality of care during installation, maintenance of building systems and remaining useful of the building system or components.

Assessments, analysis and opinions expressed within this report are not representations regarding either the design integrity or the structural soundness of the project.

No destructive or invasive testing was included in the scope of this Assessment.

DRAFT



# **APPENDIX A**

## **Dwelling Unit Photo Documentation**

DRAFT



1. Building 1; Unit: 4; Floor: 2; Style: 2 Bed / 1 Bath:



2. Building 1; Unit: 4; Floor: 2; Style: 2 Bed / 1 Bath: Kitchen.



3. Building 1; Unit: 4; Floor: 2; Style: 2 Bed / 1 Bath: Damaged kitchen finishes. (Non-Critical Repair)



4. Building 1; Unit: 4; Floor: 2; Style: 2 Bed / 1 Bath: Living room.



5. Building 1; Unit: 4; Floor: 2; Style: 2 Bed / 1 Bath: Damaged living room finishes. (Non-Critical Repair)



6. Building 1; Unit: 4; Floor: 2; Style: 2 Bed / 1 Bath: Bedroom 1.



7. Building 1; Unit: 4; Floor: 2; Style: 2 Bed / 1 Bath: Heater.



8. Building 1; Unit: 4; Floor: 2; Style: 2 Bed / 1 Bath: Bathroom.





9. Building 1; Unit: 4; Floor: 2; Style: 2 Bed / 1  
Bath: Bathroom.



10. Building 1; Unit: 18; Floor: 2; Style: 1 Bed / 1  
Bath



11. Building 1; Unit: 18; Floor: 2; Style: 1 Bed / 1  
Bath: Kitchen.



12. Building 1; Unit: 18; Floor: 2; Style: 1 Bed / 1  
Bath: Living room.






13. Building 1; Unit: 18; Floor: 2; Style: 1 Bed / 1 Bath: Bedroom.



14. Building 1; Unit: 18; Floor: 2; Style: 1 Bed / 1 Bath: Bathroom.



15. Building 1; Unit: 18; Floor: 2; Style: 1 Bed / 1 Bath: Bathroom.



16. Building 1; Unit: 18; Floor: 2; Style: 1 Bed / 1 Bath: Bathroom.



17. Building 2; Unit: 35; Floor: 2; Style: 1 Bed / 1 Bath



18. Building 2; Unit: 35; Floor: 2; Style: 1 Bed / 1 Bath: Kitchen.



19. Building 2; Unit: 35; Floor: 2; Style: 1 Bed / 1 Bath: Living room with missing finishes. (Critical Repair)



20. Building 2; Unit: 35; Floor: 2; Style: 1 Bed / 1 Bath: Bedroom.



21. Building 2; Unit: 35; Floor: 2; Style: 1 Bed / 1  
Bath: Bathroom.

# **APPENDIX B**

## **General Photo Documentation**

DRAFT





1. Stormwater Drainage: Typical topography found throughout the site.



2. Stormwater Drainage: Typical adjoining property found around the site.



3. Stormwater Drainage: Typical adjoining property found around the site.



4. Stormwater Drainage: Typical paving drainage found throughout site.





5. Stormwater Drainage: Typical downspout found throughout site.



6. Landscaping & Appurtenances: Damaged CMU wall found on the north perimeter of the property. (Non-Critical Repair)



7. Access & Egress: West access drive to the property.



8. Access & Egress: East access drive to the property.





9. Paving, Curbing, & Parking: Typical asphalt pavement found throughout the site.



10. Paving, Curbing, & Parking: Typical concrete curbing found throughout the site.



11. Paving, Curbing, & Parking: Typical accessible parking spaces found throughout the property.



12. Paving, Curbing, & Parking: Typical parking spaces found throughout the property.





13. Paving, Curbing, & Parking: Typical striping found throughout the property.



14. Flatwork (Walks, Plazas, Terraces, Patios): Poured in place concrete ramp and sidewalks found at the property.



15. Flatwork (Walks, Plazas, Terraces, Patios): Concrete steps with steel handrails found at the property.



16. Flatwork (Walks, Plazas, Terraces, Patios): Typical concrete sidewalks found at the property.





17. Landscaping & Appurtenances: Typical landscaping found throughout at the property.



18. Landscaping & Appurtenances: Typical landscaping found throughout at the property.



19. Landscaping & Appurtenances: Typical landscaping found throughout at the property.



20. Landscaping & Appurtenances: Perimeter wrought iron fencing found on north of the property.





21. Landscaping & Appurtenances: Refuse area fencing found on the property.



22. Landscaping & Appurtenances: Typical building lighting found throughout the property.



23. Landscaping & Appurtenances: Typical parking area lighting found throughout the property.



24. Landscaping & Appurtenances: Monumental signage found on the property.



25. Site Utilities: Central gas meter found at the site.



26. Site Utilities: Central electric meter found at the site.



27. Site Utilities: Central water meter found at the site.



28. Foundation: Typical basement found throughout the site.





29. Foundation: Typical cracks on basement walls and ceilings found throughout the site. (Critical Repair)



30. Foundation: Typical cracks on basement walls and ceilings found throughout the site. (Critical Repair)



31. Plumbing: Typical corroded pipes found throughout the property. (Non-Critical Repair)



32. Foundation: Typical basement found throughout the site.





33. Foundation: Typical cracks on basement walls and ceilings found throughout the site. (Critical Repair)



34. Foundation: Typical cracks on basement walls and ceilings found throughout the site. (Critical Repair)



35. Foundation: Typical cracks on basement walls and ceilings found throughout the site. (Critical Repair)



36. Foundation: Typical cracks on basement walls and ceilings found throughout the site. (Critical Repair)



37. Attics & Eaves: Typical perforated eaves vents found throughout the site (Non-Critical Repair)



38. Attics & Eaves: Typical ridge vents found throughout the site.



39. Exterior Doors & Entry Systems: Typical unit door found throughout the site.



40. Exterior Doors & Entry Systems: Typical building access door found throughout the site.





41. Sidewall System: Typical sidewall unpainted brick found throughout the site.



42. Sidewall System: Typical sidewall unpainted brick found throughout the site.



43. Sidewall System: Typical sidewall unpainted brick found throughout the site.



44. Sidewall System: Typical sidewall unpainted brick found throughout the site.



45. Sidewall System: Typical cracked unpainted brick found throughout the site. (Non-Critical Repair)



46. Sidewall System: Typical weathered and damaged wood trim found throughout the site. (Non-Critical Repair)



47. Sidewall System: Typical weathered and damaged wood trim found throughout the site. (Non-Critical Repair)



48. Sidewall System: Typical weathered and damaged wood trim found throughout the site. (Non-Critical Repair)





49. Sidewall System: Typical weathered and damaged wood trim found throughout the site.  
(Non-Critical Repair)



50. Sidewall System: Building 2 northeast corner facade.



51. Sidewall System: Building 2 east facade.



52. Sidewall System: Building 2 southeast corner facade.





53. Sidewall System: Building 2 south facade.



54. Sidewall System: Building 2 southwest corner facade.



55. Sidewall System: Building 2 west internal facade.



56. Sidewall System: Building 1 southeast corner facade.





57. Sidewall System: Building 1 southwest corner facade.



58. Sidewall System: Building 1 west facade.



59. Sidewall System: Building 1 west facade.



60. Sidewall System: Building 1 northwest corner facade.





61. Sidewall System: Building 1 northeast internal corner facade.



62. Sidewall System: Building 3 southwest corner facade.



63. Sidewall System: Building 3 southwest corner facade.



64. Sidewall System: Building 3 south corner facade.





65. Sidewall System: Building 3 west facade.



66. Sidewall System: Building 3 northwest corner facade.



67. Windows: Typical single-hung style double-pane aluminum windows found throughout the site.



68. Windows: Typical single-hung style double-pane aluminum windows found throughout the site.





69. Roofing Finish: Typical asphalt shingle roofing found throughout the site.



70. Roofing Finish: Typical asphalt shingle roofing found throughout the site.



71. Roofing Finish: Typical gutters and downspouts found throughout the site.



72. Roofing Finish: Typical gutters and downspouts found throughout the site.



73. Plumbing: Typical cast iron and PVC waste pipes found throughout the property.



74. Plumbing: Typical cast iron and PVC waste pipes found throughout the property.



75. Plumbing: Typical cast iron and PVC waste pipes found throughout the property.



76. Plumbing: Typical corroded pipes found throughout the property. (Non-Critical Repair)






77. Plumbing: Typical corroded pipes found throughout the property. (Non-Critical Repair)



78. Central gas-fired boilers found on the property.



79. Plumbing: Storage tanks found on the property.



80. Plumbing: Circulation pumps found on the property.



81. HVAC Systems: Typical tenant owned window unit AC system found throughout the site.



82. HVAC Systems: Typical tenant owned window unit AC system found throughout the site.



83. HVAC Systems: Typical tenant owned window unit AC system found throughout the site.



84. HVAC Systems: 3 ton AC system found at the community room.





85. Central gas boilers found on the property.



86. Central gas boilers found on the property.



87. HVAC Systems: Typical hydronic radiant heater found in dwelling units throughout the property.



88. Electrical System: Typical electric meter bank found throughout the site.





89. Electrical System: Central electric meter found at the site.



90. Electrical System: Typical master breaker found throughout the site.



91. Electrical System: Typical dwelling unit electric panel found throughout the site.



92. Electrical System: Typical dwelling unit electric panel found throughout the site.



93. Life & Fire Safety: Typical emergency lighting found throughout the site.



94. Life & Fire Safety: Typical illuminated exit sign found throughout the site.



95. Life & Fire Safety: Typical non-compliant smoke detector found throughout the site. (Critical Repair)



96. Life & Fire Safety: Typical non-compliant smoke detector found throughout the site. (Critical Repair)





97. Life & Fire Safety: Typical fire extinguisher found throughout the site.



98. Common Area Interior Elements: Community room.



99. Common Area Interior Elements: Community room.



100. Common Area Interior Elements: Common laundry room.





101. Common Area Interior Elements: Community Kitchen.



102. Common Area Interior Elements: Typical staircase with worn down finishes found throughout the site. (Non-Critical Repair)



103. Common Area Interior Elements: Typical staircase with worn down finishes found throughout the site. (Non-Critical Repair)



104. Common Area Interior Elements: Typical staircase with worn down finishes found throughout the site. (Non-Critical Repair)




105. Dwelling Unit Interior Elements: Typical wood laminate flooring and sheetrock finish found in dwelling units throughout the site.



106. Dwelling Unit Interior Elements: Typical vinyl flooring and sheetrock finish found in dwelling units throughout the site.



107. Dwelling Unit Interior Elements: Typical tile flooring and sheetrock finish found in dwelling units throughout the site.



108. Dwelling Unit Interior Elements: Removed flooring and finishes due to decomposing body removal. (Critical Repair)





109. Dwelling Unit Interior Elements: Damaged finishes observed in unit 4. (Non-Critical Repair)



110. Dwelling Unit Interior Elements: Damaged finishes observed in unit 4. (Non-Critical Repair)



111. Dwelling Unit Interior Elements: Damaged finishes observed in unit 4. (Non-Critical Repair)



112. Dwelling Unit Interior Elements: Damaged finishes observed in unit 4. (Non-Critical Repair)





113. Dwelling Unit Interior Elements: Damaged finishes observed in unit 20. (Non-Critical Repair)



114. Dwelling Unit Interior Elements: Damaged finishes observed in unit 20. (Non-Critical Repair)



115. Dwelling Unit Interior Elements: Damaged finishes observed in unit 20. (Non-Critical Repair)



116. Dwelling Unit Interior Elements: Damaged finishes observed in unit 20. (Non-Critical Repair)



117. Dwelling Unit Interior Elements: Damaged finishes observed in unit 20. (Non-Critical Repair)



118. Dwelling Unit Interior Elements: Damaged finishes observed in unit 20. (Non-Critical Repair)



119. Dwelling Unit Interior Elements: Damaged finishes observed in unit 20. (Non-Critical Repair)



120. Dwelling Unit Interior Elements: Typical damaged sheetrock ceilings found throughout the site. (Non-Critical Repair)





121. Dwelling Unit Interior Elements: Typical damaged sheetrock ceilings found throughout the site. (Non-Critical Repair)



122. Appliances: Typical range found throughout the site.



123. Appliances: Typical appliance package found throughout the site.



124. Cabinets & Fixtures: Typical dwelling unit kitchen sink, countertop, and wood cabinets found throughout the site.






125. Cabinets & Fixtures: Typical dwelling unit kitchen sink, countertop, and wood cabinets found throughout the site.



126. Cabinets & Fixtures: Typical dwelling unit kitchen sink, countertop, and wood cabinets found throughout the site.



127. Cabinets & Fixtures: Typical dwelling unit porcelain sink and toilet found throughout the site.



128. Cabinets & Fixtures: Typical dwelling unit enamel tub and tile surround found throughout the site.



129. Moisture and Microbial Growth: Mold on water pipes observed throughout the site. (Critical Repair)



130. Moisture and Microbial Growth: Mold on water pipes observed throughout the site. (Critical Repair)



131. UFAS Concern: Common accessible restroom without levered sink hardware. (Critical Repair)


132. David Taylor signature

# **APPENDIX C**

## **Street Map and Aerial Photo**

DRAFT





DRAFT




## SITE MAP

52 Sumner Street, Dorchester, Massachusetts 02125  
 AEI Project Number: 463356







Leaflet | Powered by Esri | City of Boston, Esri, HERE, Garmin, GeoTechnologies, Inc., NGA, USGS



## STREET MAP

52 Sumner Street, Dorchester, Massachusetts 02125  
 AEI Project Number: 463356





# **APPENDIX D**

## **USGS Seismic Design Map**


DRAFT





## 52 Sumner St, Dorchester, MA 02125, USA

Latitude, Longitude: 42.3178178, -71.0617784



Date	7/25/2022, 6:23:30 AM
Design Code Reference Document	ASCE41-13
Custom Probability	
Site Class	D - Stiff Soil

Type	Description	Value
Hazard Level		BSE-2N
S <sub>s</sub>	spectral response (0.2 s)	0.212
S <sub>1</sub>	spectral response (1.0 s)	0.068
S <sub>xS</sub>	site-modified spectral response (0.2 s)	0.339
S <sub>x1</sub>	site-modified spectral response (1.0 s)	0.164
F <sub>a</sub>	site amplification factor (0.2 s)	1.6
F <sub>v</sub>	site amplification factor (1.0 s)	2.4
ssuh	max direction uniform hazard (0.2 s)	0.238
crs	coefficient of risk (0.2 s)	0.892
ssrt	risk-targeted hazard (0.2 s)	0.212
ssd	deterministic hazard (0.2 s)	1.5
s1uh	max direction uniform hazard (1.0 s)	0.076
cr1	coefficient of risk (1.0 s)	0.9
s1rt	risk-targeted hazard (1.0 s)	0.068
s1d	deterministic hazard (1.0 s)	0.6

Type	Description	Value
Hazard Level		BSE-1N
S <sub>xS</sub>	site-modified spectral response (0.2 s)	0.226
S <sub>x1</sub>	site-modified spectral response (1.0 s)	0.109

Type	Description	Value
Hazard Level		BSE-2E
$S_S$	spectral response (0.2 s)	0.128
$S_1$	spectral response (1.0 s)	0.044
$S_{XS}$	site-modified spectral response (0.2 s)	0.205
$S_{X1}$	site-modified spectral response (1.0 s)	0.105
$f_a$	site amplification factor (0.2 s)	1.6
$f_v$	site amplification factor (1.0 s)	2.4

Type	Description	Value
Hazard Level		BSE-1E
$S_S$	spectral response (0.2 s)	0.043
$S_1$	spectral response (1.0 s)	0.016
$S_{XS}$	site-modified spectral response (0.2 s)	0.069
$S_{X1}$	site-modified spectral response (1.0 s)	0.039
$F_a$	site amplification factor (0.2 s)	1.6
$F_v$	site amplification factor (1.0 s)	2.4

Type	Description	Value
Hazard Level		TL Data
T-Sub-L	Long-period transition period in seconds	6

## DISCLAIMER

While the information presented on this website is believed to be correct, SEAC / OSHPD and its sponsors and contributors assume no responsibility or liability for its accuracy. The material presented in this web application should not be used or relied upon for any specific application without competent examination and verification of its accuracy, suitability and applicability by engineers or other licensed professionals. SEAC / OSHPD do not intend that the use of this information replace the sound judgment of such competent professionals, having experience and knowledge in the field of practice, nor to substitute for the standard of care required of such professionals in interpreting and applying the results of the seismic data provided by this website. Users of the information from this website assume all liability arising from such use. Use of the output of this website does not imply approval by the governing building code bodies responsible for building code approval and interpretation for the building site described by latitude/longitude location in the search results of this website.

# **APPENDIX E**

## **Record of all Documents Reviewed, Interviews, and Supporting Information**

DRAFT



**From:** [Maggie Castelli](#)  
**To:** ["sjccountyclerk@sjc.state.ma.us"](mailto:sjccountyclerk@sjc.state.ma.us)  
**Cc:** [Gregory Banks](#)  
**Subject:** Public Records Request - 463341-463361  
**Date:** Thursday, May 26, 2022 12:58:00 PM  
**Attachments:** [image001.png](#)

---

Hello,

AEI Consultants has been commissioned to complete a Project Capital Needs Assessment and/or Phase I Environmental Site Assessment for the following properties:

Franklin Field	100 Ames Street	Dorchester	Suffolk	MA	02124
Peabody	1875 Dorchester Avenue	Dorchester	Suffolk	MA	02124
Joseph Malone	11 Gordon Avenue	Hyde Park	Suffolk	MA	02136
Highland Park	50 Highland Street	Roxbury	Suffolk	MA	02119
Commonwealth Elderly	35 Fidelis Way	Brighton	Suffolk	MA	02135
Commonwealth Family	35 Fidelis Way	Brighton	Suffolk	MA	02135
Bellflower	24 Bellflower Street	Dorchester	Suffolk	MA	02125
ML King	280 Martin Luther King Boulevard	Boston	Suffolk	MA	02119
JJ Meade	5 Melville Avenue	Boston	Suffolk	MA	02124
JJ Carroll	30 Chestnut Hill Avenue	Brighton	Suffolk	MA	02135
Washington Street	91 Washington Street	Brighton	Suffolk	MA	02135
Davison	101 Davison Street	Hyde Park	Suffolk	MA	02136
Groveland	15 Mary Moore Beatty Circle	Mattapan	Suffolk	MA	02126
Holgate	125 Elm Hill Avenue	Roxbury	Suffolk	MA	02121
Ashmont	374 Ashmont Street	Dorchester	Suffolk	MA	02124
Commonwealth Family	35 Fidelis Way	Brighton	Suffolk	MA	02135
Bellflower	24 Bellflower Street	Dorchester	Suffolk	MA	02125
ML King	280 Martin Luther King Boulevard	Boston	Suffolk	MA	02119
JJ Meade	5 Melville Avenue	Boston	Suffolk	MA	02124
JJ Carroll	30 Chestnut Hill Avenue	Brighton	Suffolk	MA	02135
Davison	101 Davison Street	Hyde Park	Suffolk	MA	02136
Groveland	15 Mary Moore Beatty Circle	Mattapan	Suffolk	MA	02126
Holgate	125 Elm Hill Avenue	Roxbury	Suffolk	MA	02121
Ashmont	374 Ashmont Street	Dorchester	Suffolk	MA	02124
Annapolis	52 Sumner Street	Dorchester	Suffolk	MA	02125
Margaret Collins (Pond St)	29 Pond Street	Jamaica Plain	Suffolk	MA	02130
Anne M Lynch Homes (Old Colony)	265 East 9th Street	South Boston	Suffolk	MA	02127
Alice Taylor	260 Ruggles Street	Roxbury	Suffolk	MA	02120

ME McCormack	10 Kemp Street	South Boston	Suffolk	MA	02127
Charlestown	55 Bunker Hill Street	Charlestown	Suffolk	MA	02129

Are these properties within your jurisdiction?

As part of this assessment, and due diligence, we are required to request the following information, including, but not limited to the following:

**Fire Department** for information on the storage, generation, usage, or spillage of hazardous substances, petroleum products, pollutants, or controlled substances, and any other environmental conditions for the property, records of fire inspections for the property, AND copies of any outstanding fire code violations.

**Building Department** for any copies of Certificates of Occupancy and building permits from the last 10 years (year, type of permit, and owner/applicant), as well as the following information regarding building codes:

1. Building code enforced at the time the property was constructed.
2. Additional building codes enforced at the property since construction.
3. Current building code enforced by the municipality.
4. Copies of any outstanding building code violations.

**Planning and Zoning** a zoning letter to identify if the property has Activity and Use Limitations (AULs), defined as legal or physical restrictions or limitations on the use of, or access to the property; the current zoning classification of the property; AND copies of any outstanding zoning code violations.

Who would be the appropriate contacts to provide all necessary information and documents? Please notify me in advance if the fees for this request are estimated to exceed \$75.

Thank you in advance for your help,

**Maggie Castelli** (she/her)  
 Administrative Assistant – HUD Services Division  
**AEI Consultants**  
 1525 Hugesunot Road, Suite 202  
 Midlothian VA, 23113

e. [mcastelli@aeiconsultants.com](mailto:mcastelli@aeiconsultants.com)  
[www.aeiconsultants.com](http://www.aeiconsultants.com)







BUILDING NO. 3


BUILDING NO. 1

BUILDING NO. 1


BUILDING NO. 2

**FIRST FLOOR PLAN**  
**BOSTON HOUSING AUTHORITY**  
 DEVELOPMENT MASS 2-27  
 ATHAPOLIS  
 PUBLIC HOUSING ADMINISTRATION  
**JOHN M. GRAY CO.**  
 ARCHITECTS

DATE	NO.
1954	1
1954	2
1954	3
1954	4
1954	5
1954	6
1954	7
1954	8
1954	9
1954	10
1954	11
1954	12
1954	13
1954	14
1954	15
1954	16
1954	17
1954	18
1954	19
1954	20
1954	21
1954	22
1954	23
1954	24
1954	25
1954	26
1954	27
1954	28
1954	29
1954	30
1954	31
1954	32
1954	33
1954	34
1954	35
1954	36
1954	37
1954	38
1954	39
1954	40
1954	41
1954	42
1954	43
1954	44
1954	45
1954	46
1954	47
1954	48
1954	49
1954	50
1954	51
1954	52
1954	53
1954	54
1954	55
1954	56
1954	57
1954	58
1954	59
1954	60
1954	61
1954	62
1954	63
1954	64
1954	65
1954	66
1954	67
1954	68
1954	69
1954	70
1954	71
1954	72
1954	73
1954	74
1954	75
1954	76
1954	77
1954	78
1954	79
1954	80
1954	81
1954	82
1954	83
1954	84
1954	85
1954	86
1954	87
1954	88
1954	89
1954	90
1954	91
1954	92
1954	93
1954	94
1954	95
1954	96
1954	97
1954	98
1954	99
1954	100




PROVIDED BY ARCHITECT FOR THE BOSTON HOUSING AUTHORITY. THIS PLAN IS TO BE USED FOR THE CONSTRUCTION OF THE BUILDING. IT IS NOT TO BE USED FOR ANY OTHER PURPOSE. THE ARCHITECT IS NOT RESPONSIBLE FOR ANY ERRORS OR OMISSIONS IN THIS PLAN.



**SECOND FLOOR**  
SCALE 1/8" = 1'-0"

IDENTICAL TO FIRST FLOOR PLAN EXCEPT STAIRWELL AS SHOWN



**FIRST FLOOR**  
SCALE 1/8" = 1'-0"

TYPE 'A' UNIT  
(typical, except for details)

ITEM	DESCRIPTION	FLOOR	PHASE	EXPOS	WALLS	CEILING	REMARKS
1	CONCRETE	1ST	1	1	1	1	CONCRETE SLAB ON GROUND
2	FOUNDATION	1ST	1	1	1	1	FOUNDATION WALLS
3	FRAMING	1ST	2	2	2	2	WOOD FRAMING
4	ROOFING	1ST	3	3	3	3	ROOFING MATERIALS
5	MECHANICAL	1ST	4	4	4	4	M.E. WORK
6	ELECTRICAL	1ST	5	5	5	5	ELECTRICAL WORK
7	PLUMBING	1ST	6	6	6	6	PLUMBING WORK
8	PAINTING	1ST	7	7	7	7	PAINTING WORK
9	FINISHES	1ST	8	8	8	8	FINISHES
10	INSULATION	1ST	9	9	9	9	INSULATION
11	GLAZING	1ST	10	10	10	10	GLAZING WORK
12	LANDSCAPING	1ST	11	11	11	11	LANDSCAPING
13	UTILITIES	1ST	12	12	12	12	UTILITIES
14	DEMOLITION	1ST	13	13	13	13	DEMOLITION
15	CONCRETE	2ND	1	1	1	1	CONCRETE SLAB ON GROUND
16	FOUNDATION	2ND	1	1	1	1	FOUNDATION WALLS
17	FRAMING	2ND	2	2	2	2	WOOD FRAMING
18	ROOFING	2ND	3	3	3	3	ROOFING MATERIALS
19	MECHANICAL	2ND	4	4	4	4	M.E. WORK
20	ELECTRICAL	2ND	5	5	5	5	ELECTRICAL WORK
21	PLUMBING	2ND	6	6	6	6	PLUMBING WORK
22	PAINTING	2ND	7	7	7	7	PAINTING WORK
23	FINISHES	2ND	8	8	8	8	FINISHES
24	INSULATION	2ND	9	9	9	9	INSULATION
25	GLAZING	2ND	10	10	10	10	GLAZING WORK
26	LANDSCAPING	2ND	11	11	11	11	LANDSCAPING
27	UTILITIES	2ND	12	12	12	12	UTILITIES
28	DEMOLITION	2ND	13	13	13	13	DEMOLITION




**TYPE 'A' UNIT PLAN**  
**BOSTON HOUSING AUTHORITY**  
 ANNAHOLIS DEVELOPMENT  
 DORCHESTER, MASS.  
 ARCHITECTS  
**JOHN M. GRAY CO.**  
 125 STATE STREET - BOSTON, MASS.  
 125 STATE STREET - BOSTON, MASS.  
 125 STATE STREET - BOSTON, MASS.









**SECOND FLOOR**




BOSTON HOUSING AUTHORITY  
 COMMUNITY PLAN  
 ANNAPOLIS DEVELOPMENT, DORCHESTER, MASS.  
 DEVELOPED UNDER THE UNITED STATES HOUSING ACT  
 PUBLIC HOUSING ACT, ADAPTATION  
 JOHN M. GRAY CO.  
 ARCHITECTS  
 133 WALK STREET - BOSTON, MASS.  
 REGISTERED PROFESSIONAL ARCHITECTS  
 LICENSE NO. 10000  
 STATE OF MASSACHUSETTS  
 ARCHITECTS  
 LICENSE NO. 10000


PLANS OF ALL APARTMENT STAIRS BY JOSEPH M. NUNEZ

APARTMENT	APARTMENTS	ROOM	FINISH	SCHEDULE
101	101	101	101	101
102	102	102	102	102
103	103	103	103	103
104	104	104	104	104
105	105	105	105	105
106	106	106	106	106
107	107	107	107	107
108	108	108	108	108
109	109	109	109	109
110	110	110	110	110
111	111	111	111	111
112	112	112	112	112
113	113	113	113	113
114	114	114	114	114
115	115	115	115	115
116	116	116	116	116
117	117	117	117	117
118	118	118	118	118
119	119	119	119	119
120	120	120	120	120


**FIRST FLOOR**







SECTION  
TYPICAL FRONT ENTRANCE DETAIL



SECTION  
TYPICAL REAR DOOR DETAIL

SECTION  
WALL SECTIONS - SHELVING  
ENTRANCE & BATH DETAILS


BOSTON HOUSING AUTHORITY  
DEVELOPMENT MASS 2-277  
ANNAPOLIS DORCHESTER, MASS.

DESIGNED BY  
PUBLIC HOUSING ADMINISTRATION

ARCHITECTS  
JOHN M. GRAY CO.  
120 N. STATE ST., BOSTON, MASS.

ENGINEER  
FRANK L. BROWN, INC.  
100 STATE ST., BOSTON, MASS.


DATE  
MAY 1954



SECTION  
TYPICAL BATHROOM DETAIL

SECTION  
TYPICAL BATHROOM DETAIL

SECTION  
TYPICAL BATHROOM DETAIL




SECTION  
TYPICAL KITCHEN DETAIL




SECTION  
TYPICAL LIVING ROOM DETAIL



SECTION  
TYPICAL BEDROOM DETAIL




SECTION  
TYPICAL WALL DETAIL




SECTION THROUGH TYPICAL  
EXTERIOR WALL

SECTION C-C THROUGH REAR EXTERIOR  
WALL OF COMMUNITY ROOM





**METAL BRICK MULLER & IN WOOD**  
SCALE: 1/4" = 1'-0"




**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"




**EXTERIOR WOOD DOOR FRAMES**  
SCALE: 1/4" = 1'-0"



**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"



**SELF-STUD-CYRUM DOOR FRAME WITH PLASTIC EXTERIOR SIDING**  
SCALE: 1/4" = 1'-0"



**EXTERIOR HOLLOW METAL DOOR FRAMES**  
SCALE: 1/4" = 1'-0"



**WOOD FOLDING DOORS IN CLOSET**  
SCALE: 1/4" = 1'-0"



**WOOD FOLDING DOORS IN CLOSET**  
SCALE: 1/4" = 1'-0"



**WOOD FOLDING DOORS IN CLOSET**  
SCALE: 1/4" = 1'-0"



**WOOD FOLDING DOORS IN CLOSET**  
SCALE: 1/4" = 1'-0"



**WOOD FOLDING DOORS IN CLOSET**  
SCALE: 1/4" = 1'-0"



**WOOD FOLDING DOORS IN CLOSET**  
SCALE: 1/4" = 1'-0"



**WOOD FOLDING DOORS IN CLOSET**  
SCALE: 1/4" = 1'-0"



**WOOD FOLDING DOORS IN CLOSET**  
SCALE: 1/4" = 1'-0"



**WOOD FOLDING DOORS IN CLOSET**  
SCALE: 1/4" = 1'-0"



**WOOD FOLDING DOORS IN CLOSET**  
SCALE: 1/4" = 1'-0"



**WOOD FOLDING DOORS IN CLOSET**  
SCALE: 1/4" = 1'-0"




**WOOD FOLDING DOORS IN CLOSET**  
SCALE: 1/4" = 1'-0"



**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"




**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"



**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"



**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"



**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"



**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"



**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"



**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"



**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"




**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"



**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"



**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"



**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"



**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"



**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"



**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"



**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"



**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"



**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"



**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"



**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"



**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"



**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"



**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"




**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"




**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"




**METAL IN CONCRETE**  
SCALE: 1/4" = 1'-0"




**ALUMINUM DOUBLE HUNG SASH & FRAME**  
SCALE: 1/4" = 1'-0"



**SECTION THROUGH ALUMINUM DOUBLE HUNG SASH ON 1 1/2\"/>**




**SECTION THROUGH ALUMINUM DOUBLE HUNG SASH ON 1 1/2\"/>**



**SECTION THROUGH ALUMINUM DOUBLE HUNG SASH ON 1 1/2\"/>**



**SECTION THROUGH ALUMINUM DOUBLE HUNG SASH ON 1 1/2\"/>**




**ALUMINUM PROJECTED SASH & FRAME**  
SCALE: 1/4" = 1'-0"



**SECTION THROUGH ALUMINUM PROJECTED SASH IN COMMUNITY WING**  
SCALE: 1/4" = 1'-0"




**SECTION THROUGH ALUMINUM PROJECTED SASH IN COMMUNITY WING**  
SCALE: 1/4" = 1'-0"




**SECTION THROUGH ALUMINUM PROJECTED SASH IN COMMUNITY WING**  
SCALE: 1/4" = 1'-0"




**SECTION THROUGH ALUMINUM PROJECTED SASH IN COMMUNITY WING**  
SCALE: 1/4" = 1'-0"




**SECTION THROUGH ALUMINUM PROJECTED SASH IN BASEMENT**  
SCALE: 1/4" = 1'-0"



**SECTION THROUGH ALUMINUM PROJECTED SASH IN BASEMENT**  
SCALE: 1/4" = 1'-0"



**SECTION THROUGH ALUMINUM PROJECTED SASH IN BASEMENT**  
SCALE: 1/4" = 1'-0"



**SECTION THROUGH ALUMINUM PROJECTED SASH IN BASEMENT**  
SCALE: 1/4" = 1'-0"



**SECTION THROUGH ALUMINUM PROJECTED SASH IN BASEMENT**  
SCALE: 1/4" = 1'-0"


**WINDOW & DOOR DETAILS**  
 BOSTON HOUSING AUTHORITY  
 DEVELOPMENT DEPARTMENT  
 100 STATE STREET - BOSTON, MASS.  
 JOHN M. GRAY CO.  
 ARCHITECTS  
 100 STATE STREET - BOSTON, MASS.  
 SCALE: 1/4" = 1'-0"




**BASEMENT FIREWALL DOORS**  
 SECTION  
 SCALE: 1/4" = 1'-0"

**DETAILS OF TYPICAL KITCHEN**  
 SECTION  
 SCALE: 1/4" = 1'-0"

**DETAILS OF TYPICAL KITCHEN**  
 SECTION  
 SCALE: 1/4" = 1'-0"



**FRONT ELEVATION ANNAPOLIS STREET** 01




**REAR ELEVATION** 02



**RIGHT SIDE ELEVATION** 03



**LEFT ELEVATION- SUMNER STREET** 04



**ANNAPOLIS BUILDING 1**


LOCKHEED WINDOW CORP.  
 P.O. BOX 166  
 ROUTE 100  
 ASCOAG, RI 02858  
 TEL: (401) 568-3061

PROJECT: 800715  
 DRAWING: BE1  
 SCALE: N/A  
 SHEET: BE1 of BE9  
 WINDOW CORP.


PROJECT: 800715  
 ARCHITECT: JAMES PAYNE  
 GENERAL CONTRACTOR: LOCKHEED WINDOW CORP.

LOCKHEED WINDOW CORP.  
 P.O. BOX 166  
 ROUTE 100  
 ASCOAG, RI 02858  
 TEL: (401) 568-3061

LOCKHEED WINDOW CORP.  
 P.O. BOX 166  
 ROUTE 100  
 ASCOAG, RI 02858  
 TEL: (401) 568-3061




**FRONT ELEVATION ANNAPOLIS STREET** 01



**REAR ELEVATION** 02



**RIGHT SIDE ELEVATION** 03



**LEFT ELEVATION** 04



**ANNAPOLIS BUILDING 2**

**WARRANTY NOTICE**  
 Lockheed Window Corp. warrants the materials and workmanship of the windows and window units shown on these drawings for the period of one year from the date of completion of the project. This warranty does not cover the cost of labor for removal and replacement of windows or window units. The warranty is void if the windows or window units are not installed in accordance with the manufacturer's instructions. For more information, please contact Lockheed Window Corp. at (401) 568-3061.


P.O. BOX 166  
 ROUTE 100  
 PASCOAG, RI 02859  
 TEL: (401) 568-3061




PROJECT: 800715  
 ARCHITECT: JAMES PAVNE  
 GENERAL CONTRACTOR: LOCKHEED WINDOW CORP.

DWG NO. 800715  
 DATE: 10/10/2007  
 SCALE: N/A  
 SHEET: BE2 OF BE9  
 DRAWN BY: [unintelligible]






FRONT ELEVATION 03




KEY PLAN


ANNAPOLIS BUILDING 3




REAR ELEVATION 04




RIGHT SIDE ELEVATION 05



RIGHT COURTYARD SIDE ELEVATION 01



LEFT SIDE ELEVATION 06



LEFT COURTYARD SIDE ELEVATION 02

LOCKHEED WINDOW CORP.  
 1000 LOCKHEED BLVD.  
 PASCOAG, RI 02859  
 TEL: (401) 586-3061

P.O. BOX 166  
 ROUTE 100  
 PASCOAG, RI 02859  
 TEL: (401) 586-3061

**LOCKHEED**  
 WINDOW CORP.


PROJECT: 800715  
 DRAWING: SITE  
 DATE: 10/05/2007  
 SCALE: N/A  
 SHEET: BE 3 OF BE 9  
 DRAWN BY: JAMES PAINTE  
 GENERAL CONTRACTOR: LOCKHEED WINDOW CORP.

800715  
 10/05/2007  
 N/A  
 BE 3 OF BE 9  
 JAMES PAINTE  
 LOCKHEED WINDOW CORP.


Lockheed Window Corp. prepared these drawings for the exclusive use by Lockheed Window Corp. for the manufacture and installation of the windows being supplied by Lockheed Window Corp. per our contract. These drawings are not to be used for any other trade during construction. Any trades using these drawings for the construction of their work and/or work being performed by Lockheed Window Corp. is at their own risk. Lockheed Window Corp. will not accept or consider any liability and/or damages for corrective work deemed necessary for any errors or omissions these drawings may contain.

REV	BY	DATE	DESCRIPTION
A	M.F.	10-22-07	REVISED PER MFC RECEIVED


**ANNAPOLIS BUILDING 1**




**01**  
FRONT ELEVATION ANNAPOLIS STREET




**02**  
REAR ELEVATION



**03**  
RIGHT SIDE ELEVATION



**04**  
LEFT ELEVATION-SUMMER STREET



PROJECT: BOSTON HOUSING AUTHORITY  
 FINE ELDERT DEVELOPMENTS  
 ARCHITECT: JONES PLYNNE  
 GENERAL CONTRACTOR: LOCKHEED WINDOW CORP.




P.O. BOX 166  
 ROUTE 100  
 PASCOAG, RI 02859  
 TEL: (401) 568-3061


ATTENTION: PLEASE READ  
 Lockheed Window Corp. provided these drawings for the exclusive use of the architect. These drawings are not to be used by any other trades during construction. Any changes to these drawings for the coordination of their work and/or work being performed by Lockheed Window Corp. is of their own risk. Lockheed Window Corp. will accept no liability for any errors or omissions these drawings may contain.

REV	BY	DATE	DESCRIPTION
A	M.F.	10-25-07	REVISED PER INFO RECEIVED


**ANNAPOLIS BUILDING 2**




**01**  
**FRONT ELEVATION ANNAPOLIS STREET**




**02**  
**REAR ELEVATION**




**03**  
**RIGHT SIDE ELEVATION**




**04**  
**LEFT ELEVATION**









**03**  
**FRONT ELEVATION**




**04**  
**REAR ELEVATION**




**05**  
**RIGHT SIDE ELEVATION**




**06**  
**LEFT SIDE ELEVATION**



**01**  
**RIGHT COURTYARD SIDE ELEVATION**



**02**  
**LEFT COURTYARD SIDE ELEVATION**



ANNAPOLIS STREET

KEY PLAN

**ANNAPOLIS BUILDING 3**

**LOCKHEED WINDOW CORP.**  
P.O. BOX 166  
ROUTE 100  
PASCOAG, RI 02859  
TEL: (401) 568-3061

PROJECT: BOSTON HOUSING AUTHORITY  
ARCHITECT: JONES PAYNE  
GENERAL CONTRACTOR: LOCKHEED WINDOW CORP.

JOB NO. 800715  
DATE: 10/02/2007  
DRAWN: M.F.  
SCALE: N/A

PROJECT: BOSTON HOUSING AUTHORITY  
ARCHITECT: JONES PAYNE  
GENERAL CONTRACTOR: LOCKHEED WINDOW CORP.

LOCKHEED WINDOW CORP. PROVIDES THESE DRAWINGS FOR THE EXCLUSIVE USE BY LOCKHEED WINDOW CORP. FOR THE MANUFACTURE AND INSTALLATION OF THE WINDOW BEING ORDERED BY LOCKHEED WINDOW CORP. PER OUR CONTRACT. THESE DRAWINGS ARE NOT TO BE USED BY ANY OTHER TRADES OR CONTRACTORS. ANY TRADES USING THESE DRAWINGS FOR THE CONSTRUCTION OF THEIR OWN WORK TAKING PERFORMED BY LOCKHEED WINDOW CORP. IS AT THEIR OWN RISK. LOCKHEED WINDOW CORP. WILL ACCEPT NO LIABILITY FOR ANY LIABILITY AND/OR DAMAGES FOR CORRECTIVE WORK DEEMED NECESSARY FOR ANY ERRORS OR OMISSIONS THESE DRAWINGS MAY CONTAIN.


ATTENTION: PLEASE READ

REV	BY	DATE	DESCRIPTION
Δ	M.F.	10-29-07	REVISED PER INFO RECEIVED

BE3 of BE9  
SHEET



**BASEMENT FLOOR PLAN**  
 BOSTON HOUSING AUTHORITY  
 DEVELOPMENT MASS. 2-27  
 ANNAPOLIS - DORCHESTER MASS.  
 DEVELOPER: BOSTON HOUSING AUTHORITY  
 ARCHITECTS: JOHN M. GRAY CO.  
 108 WASHINGTON STREET, BOSTON, MASS.  
 SCALE: AS SHOWN  
 DATE: JANUARY 1954



BUILDING NO. 5


BUILDING NO. 2

BUILDING NO. 1

**FINISH SCHEDULE**


DESCRIPTION	FINISH	REMARKS
CEILING	PLASTER	
WALLS	PLASTER	
FLOORS	CONCRETE	
DOORWAYS	WOOD	
TOILET	PLASTER	
STAIRS	PLASTER	
TRUSS	PLASTER	
ROOF	PLASTER	





SECOND FLOOR  
SCALE 1/8" = 1'-0"

IDENTICAL TO FIRST FLOOR PLAN EXCEPT STAIRWELL AS SHOWN.



FIRST FLOOR  
SCALE 1/8" = 1'-0"

**ROOM FINISH SCHEDULE**


ROOM NUMBER	FLOOR	BASE	WALLS	CEILING	DETAILS
MECHANICAL	001	3/4"	1/2"	1/2"	SEE 100-100
STAIRWELL	002	3/4"	1/2"	1/2"	SEE 100-100
STAIR	003	3/4"	1/2"	1/2"	SEE 100-100
STAIR	004	3/4"	1/2"	1/2"	SEE 100-100
STAIR	005	3/4"	1/2"	1/2"	SEE 100-100
STAIR	006	3/4"	1/2"	1/2"	SEE 100-100
STAIR	007	3/4"	1/2"	1/2"	SEE 100-100
STAIR	008	3/4"	1/2"	1/2"	SEE 100-100
STAIR	009	3/4"	1/2"	1/2"	SEE 100-100
STAIR	010	3/4"	1/2"	1/2"	SEE 100-100
STAIR	011	3/4"	1/2"	1/2"	SEE 100-100
STAIR	012	3/4"	1/2"	1/2"	SEE 100-100
STAIR	013	3/4"	1/2"	1/2"	SEE 100-100
STAIR	014	3/4"	1/2"	1/2"	SEE 100-100
STAIR	015	3/4"	1/2"	1/2"	SEE 100-100
STAIR	016	3/4"	1/2"	1/2"	SEE 100-100
STAIR	017	3/4"	1/2"	1/2"	SEE 100-100
STAIR	018	3/4"	1/2"	1/2"	SEE 100-100
STAIR	019	3/4"	1/2"	1/2"	SEE 100-100
STAIR	020	3/4"	1/2"	1/2"	SEE 100-100
STAIR	021	3/4"	1/2"	1/2"	SEE 100-100
STAIR	022	3/4"	1/2"	1/2"	SEE 100-100
STAIR	023	3/4"	1/2"	1/2"	SEE 100-100
STAIR	024	3/4"	1/2"	1/2"	SEE 100-100
STAIR	025	3/4"	1/2"	1/2"	SEE 100-100
STAIR	026	3/4"	1/2"	1/2"	SEE 100-100
STAIR	027	3/4"	1/2"	1/2"	SEE 100-100
STAIR	028	3/4"	1/2"	1/2"	SEE 100-100
STAIR	029	3/4"	1/2"	1/2"	SEE 100-100
STAIR	030	3/4"	1/2"	1/2"	SEE 100-100
STAIR	031	3/4"	1/2"	1/2"	SEE 100-100
STAIR	032	3/4"	1/2"	1/2"	SEE 100-100
STAIR	033	3/4"	1/2"	1/2"	SEE 100-100
STAIR	034	3/4"	1/2"	1/2"	SEE 100-100
STAIR	035	3/4"	1/2"	1/2"	SEE 100-100
STAIR	036	3/4"	1/2"	1/2"	SEE 100-100
STAIR	037	3/4"	1/2"	1/2"	SEE 100-100
STAIR	038	3/4"	1/2"	1/2"	SEE 100-100
STAIR	039	3/4"	1/2"	1/2"	SEE 100-100
STAIR	040	3/4"	1/2"	1/2"	SEE 100-100
STAIR	041	3/4"	1/2"	1/2"	SEE 100-100
STAIR	042	3/4"	1/2"	1/2"	SEE 100-100
STAIR	043	3/4"	1/2"	1/2"	SEE 100-100
STAIR	044	3/4"	1/2"	1/2"	SEE 100-100
STAIR	045	3/4"	1/2"	1/2"	SEE 100-100
STAIR	046	3/4"	1/2"	1/2"	SEE 100-100
STAIR	047	3/4"	1/2"	1/2"	SEE 100-100
STAIR	048	3/4"	1/2"	1/2"	SEE 100-100
STAIR	049	3/4"	1/2"	1/2"	SEE 100-100
STAIR	050	3/4"	1/2"	1/2"	SEE 100-100
STAIR	051	3/4"	1/2"	1/2"	SEE 100-100
STAIR	052	3/4"	1/2"	1/2"	SEE 100-100
STAIR	053	3/4"	1/2"	1/2"	SEE 100-100
STAIR	054	3/4"	1/2"	1/2"	SEE 100-100
STAIR	055	3/4"	1/2"	1/2"	SEE 100-100
STAIR	056	3/4"	1/2"	1/2"	SEE 100-100
STAIR	057	3/4"	1/2"	1/2"	SEE 100-100
STAIR	058	3/4"	1/2"	1/2"	SEE 100-100
STAIR	059	3/4"	1/2"	1/2"	SEE 100-100
STAIR	060	3/4"	1/2"	1/2"	SEE 100-100
STAIR	061	3/4"	1/2"	1/2"	SEE 100-100
STAIR	062	3/4"	1/2"	1/2"	SEE 100-100
STAIR	063	3/4"	1/2"	1/2"	SEE 100-100
STAIR	064	3/4"	1/2"	1/2"	SEE 100-100
STAIR	065	3/4"	1/2"	1/2"	SEE 100-100
STAIR	066	3/4"	1/2"	1/2"	SEE 100-100
STAIR	067	3/4"	1/2"	1/2"	SEE 100-100
STAIR	068	3/4"	1/2"	1/2"	SEE 100-100
STAIR	069	3/4"	1/2"	1/2"	SEE 100-100
STAIR	070	3/4"	1/2"	1/2"	SEE 100-100
STAIR	071	3/4"	1/2"	1/2"	SEE 100-100
STAIR	072	3/4"	1/2"	1/2"	SEE 100-100
STAIR	073	3/4"	1/2"	1/2"	SEE 100-100
STAIR	074	3/4"	1/2"	1/2"	SEE 100-100
STAIR	075	3/4"	1/2"	1/2"	SEE 100-100
STAIR	076	3/4"	1/2"	1/2"	SEE 100-100
STAIR	077	3/4"	1/2"	1/2"	SEE 100-100
STAIR	078	3/4"	1/2"	1/2"	SEE 100-100
STAIR	079	3/4"	1/2"	1/2"	SEE 100-100
STAIR	080	3/4"	1/2"	1/2"	SEE 100-100
STAIR	081	3/4"	1/2"	1/2"	SEE 100-100
STAIR	082	3/4"	1/2"	1/2"	SEE 100-100
STAIR	083	3/4"	1/2"	1/2"	SEE 100-100
STAIR	084	3/4"	1/2"	1/2"	SEE 100-100
STAIR	085	3/4"	1/2"	1/2"	SEE 100-100
STAIR	086	3/4"	1/2"	1/2"	SEE 100-100
STAIR	087	3/4"	1/2"	1/2"	SEE 100-100
STAIR	088	3/4"	1/2"	1/2"	SEE 100-100
STAIR	089	3/4"	1/2"	1/2"	SEE 100-100
STAIR	090	3/4"	1/2"	1/2"	SEE 100-100
STAIR	091	3/4"	1/2"	1/2"	SEE 100-100
STAIR	092	3/4"	1/2"	1/2"	SEE 100-100
STAIR	093	3/4"	1/2"	1/2"	SEE 100-100
STAIR	094	3/4"	1/2"	1/2"	SEE 100-100
STAIR	095	3/4"	1/2"	1/2"	SEE 100-100
STAIR	096	3/4"	1/2"	1/2"	SEE 100-100
STAIR	097	3/4"	1/2"	1/2"	SEE 100-100
STAIR	098	3/4"	1/2"	1/2"	SEE 100-100
STAIR	099	3/4"	1/2"	1/2"	SEE 100-100
STAIR	100	3/4"	1/2"	1/2"	SEE 100-100

**TYPE 'A' UNIT PLAN**

BOSTON HOUSING AUTHORITY  
 DEVELOPMENT MASS. 2-27  
 ANNAPOLIS

EXTENDED UNDER THE MASS. HOUSING ACT, REGULAR ACT  
 PUBLIC HOUSING ADMINISTRATION  
 JOHN M. GRAY CO. ARCHITECTS  
 110 STATE STREET BOSTON, MASS.  
 CHARLES L. HOSKINS ARCHITECTS A-4  
 100 STATE STREET BOSTON, MASS.





**SECOND FLOOR**  
SCALE 1/4" = 1'-0"

SECTIONAL TO FIRST FLOOR  
SEE PLAN 2-10



**TYPE 'B' UNIT PLAN A**  
**COMMUNITY HOUSING PLAN**  
**BOSTON HOUSING AUTHORITY**  
DEVELOPMENT MASS. 2-27  
ANNAPOLIS  
RECORDED WITH THE OFFICE OF THE REGISTERED  
PUBLIC HOUSING ADMINISTRATION  
**JOHN M. GRAY CO.**  
ARCHITECTS FOR ARCH.  
133 BELLAIR STREET, BOSTON, MASS.  
GENERAL CONTRACTOR: W. J. L. HAYES & CO.  
ELECTRICAL CONTRACTOR: J. J. HAYES & CO.  
MECHANICAL CONTRACTOR: W. J. L. HAYES & CO.  
PLUMBING CONTRACTOR: W. J. L. HAYES & CO.

**PLANS OF ALL APARTMENT STAIRS EXCEPT 'M' UNIT**

APARTMENT	AREA	FINISH	APARTMENT	FINISH	APARTMENT	FINISH	APARTMENT	FINISH
101	100	100	102	100	103	100	104	100
105	100	100	106	100	107	100	108	100
109	100	100	110	100	111	100	112	100
115	100	100	116	100	117	100	118	100
121	100	100	122	100	123	100	124	100
129	100	100	130	100	131	100	132	100
139	100	100	140	100	141	100	142	100
149	100	100	150	100	151	100	152	100
161	100	100	162	100	163	100	164	100
171	100	100	172	100	173	100	174	100
181	100	100	182	100	183	100	184	100
191	100	100	192	100	193	100	194	100
201	100	100	202	100	203	100	204	100
211	100	100	212	100	213	100	214	100
221	100	100	222	100	223	100	224	100
231	100	100	232	100	233	100	234	100
241	100	100	242	100	243	100	244	100
251	100	100	252	100	253	100	254	100
261	100	100	262	100	263	100	264	100
271	100	100	272	100	273	100	274	100
281	100	100	282	100	283	100	284	100
291	100	100	292	100	293	100	294	100
301	100	100	302	100	303	100	304	100
311	100	100	312	100	313	100	314	100
321	100	100	322	100	323	100	324	100
331	100	100	332	100	333	100	334	100
341	100	100	342	100	343	100	344	100
351	100	100	352	100	353	100	354	100
361	100	100	362	100	363	100	364	100
371	100	100	372	100	373	100	374	100
381	100	100	382	100	383	100	384	100
391	100	100	392	100	393	100	394	100
401	100	100	402	100	403	100	404	100
411	100	100	412	100	413	100	414	100
421	100	100	422	100	423	100	424	100
431	100	100	432	100	433	100	434	100
441	100	100	442	100	443	100	444	100
451	100	100	452	100	453	100	454	100
461	100	100	462	100	463	100	464	100
471	100	100	472	100	473	100	474	100
481	100	100	482	100	483	100	484	100
491	100	100	492	100	493	100	494	100
501	100	100	502	100	503	100	504	100

**FIRST FLOOR**  
SCALE 1/4" = 1'-0"





FRONT ELEVATION — BUILDING NO. 1 — HUBBARD'S STREET



FRONT ELEVATION — BUILDING NO. 2 — HUBBARD'S STREET



REAR ELEVATION — BUILDING NO. 1 — SEABOARD STREET




REAR ELEVATION — BUILDING NO. 2 — SEABOARD STREET



RIGHT SIDE ELEVATION — BUILDING NO. 1 — SACRAMENTO STREET



RIGHT SIDE ELEVATION — BUILDING NO. 2 — SACRAMENTO STREET



LEFT SIDE ELEVATION — BUILDING NO. 1 — SACRAMENTO STREET



LEFT SIDE ELEVATION — BUILDING NO. 2 — SACRAMENTO STREET



ELEVATIONS  
BUILDINGS NOS 1 & 2  
BOSTON HOUSING AUTHORITY  
DEVELOPMENT MASS 2-27  
ANNAPOLIS  
PUBLIC HOUSING ADMINISTRATION  
RELEVANT PARTS OF MASS. HOUSING ACT  
ARCHITECT  
JOHN M. GRAY CO.  
REGISTERED PROFESSIONAL ARCHITECTS  
CORPORATE OFFICE: 100 STATE STREET, BOSTON, MASS.  
TELEPHONE: 5-2300  
FACSIMILE: 5-2300  
MAILING ADDRESS: 100 STATE STREET, BOSTON, MASS.  
TELEPHONE: 5-2300  
FACSIMILE: 5-2300



APPROVED FOR THE  
COMMISSIONER OF REVENUE  
STATE OF MASSACHUSETTS  
DATE: FEBRUARY 2, 1966




ELEVATIONS - BLDG. NO. 3  
 FRAMING - COMMUNITY ROOM  
 BOSTON HOUSING AUTHORITY  
 DEVELOPMENT MASS 2-27  
 ANNAPOLIS - DORCHESTER, MASS  
 DELICIOUS WINDMILL, 111 STATE STREET, BOSTON, MASS  
 PUBLIC HOUSING ADMINISTRATION  
 ARCHITECTS  
 JOHN M. GRAY CO.  
 125 STATE STREET, BOSTON, MASS  
 PHONE: (617) 552-1111  
 A-B




COMMUNITY ROOM - COMMUNITY ROOM  
 BOSTON HOUSING AUTHORITY  
 DEVELOPMENT MASS 2-27  
 ANNAPOLIS - DORCHESTER, MASS  
 DELICIOUS WINDMILL, 111 STATE STREET, BOSTON, MASS  
 PUBLIC HOUSING ADMINISTRATION  
 ARCHITECTS  
 JOHN M. GRAY CO.  
 125 STATE STREET, BOSTON, MASS  
 PHONE: (617) 552-1111  
 A-B








TYPICAL FRONT ENTRANCE DETAIL



TYPICAL BATHROOM



SECTION THROUGH TYPICAL EXTERIOR WALL OF COMMUNITY ROOM



  
**WALL SECTIONS - SHELVING ENTRY & BATH DETAILS**  
 BOSTON HOUSING AUTHORITY  
 DEVELOPMENT MASS 2-27  
 ANNAPOLIS DORCHESTER, MASS.  
 PUBLIC HOUSING ADMINISTRATION  
 JOHN M. GRAY CO.  
 ARCHITECTS  
 125 N. WASHINGTON ST. - BOSTON, MASS.  
 125 N. WASHINGTON ST. - BOSTON, MASS.  
 125 N. WASHINGTON ST. - BOSTON, MASS.

SECTION THROUGH TYPICAL EXTERIOR WALL  
 SCALE 1/4" = 1'-0"


ATTENTION: PLEASE READ  
 Lockheed Window Corp. prepared these drawings for the exclusive use of the architect. It is the responsibility of the architect to see that these drawings are used in accordance with the contract. Lockheed Window Corp. is not responsible for any liability and/or changes for contract work caused necessary for any building or structure being designed and constructed.

REV	DATE	DESCRIPTION
A	10-25-07	REVISED PER ARCHITECT'S COMMENTS


**ANNAPOLIS BUILDING 1**




**01 FRONT ELEVATION ANNAPOLIS STREET**




**02 REAR ELEVATION**



**03 RIGHT SIDE ELEVATION**



**04 LEFT ELEVATION - SUMMER STREET**





P.O. BOX 166  
ROUTE 100  
PASCOAG, RI 02859  
TEL: (401) 568-3061


ANNAPOLIS PLAZA BLDG  
Lockheed Window Corp. prepared these drawings for the exclusive use of Lockheed Window Corp. for the manufacture and installation of the windows being ordered by Lockheed Window Corp. and for no other purpose. These drawings are not to be used by any other trades or contractors. Any change made to these drawings for the construction of these windows shall be performed by Lockheed Window Corp. in their own files, and no copies or master drawings shall be made or distributed by Lockheed Window Corp. without the written consent of Lockheed Window Corp. Any liability and/or damages for defective work deemed necessary for any errors or omissions these drawings may contain.

REV	BY	DATE	DESCRIPTION
1	WJ	10-20-17	REVISED PER AND RECEIVED


**ANNAPOLIS BUILDING 2**




**01**  
**FRONT ELEVATION ANNAPOLIS STREET**




**02**  
**REAR ELEVATION**




**03**  
**RIGHT SIDE ELEVATION**




**04**  
**LEFT ELEVATION**









**03**  
FRONT ELEVATION




**04**  
REAR ELEVATION




**05**  
RIGHT SIDE ELEVATION




**06**  
LEFT SIDE ELEVATION



**01**  
RIGHT COURTYARD SIDE ELEVATION



**02**  
LEFT COURTYARD SIDE ELEVATION



KEY PLAN  
ANNAPOLIS STREET  
SUNNER STREET  
**ANNAPOLIS BUILDING 3**

REV	BY	DATE	DESCRIPTION
1	W.F.	10/02/2007	REVISED PER INFO RECEIVED

Lockheed Window Corp. prepared these drawings for the exclusive use of the architect. These drawings are not to be used for any other purpose. These drawings are prepared by Lockheed Window Corp. and are not to be used for any other purpose. Lockheed Window Corp. is not responsible for any errors or omissions that may occur in any liability and/or damages for corrective work deemed necessary for any reason.

P.O. BOX 166  
ROUTE 100  
PASCOAG, RI 02859  
TEL: (401) 568-3061



PROJECT: BOSTON HOUSING AUTHORITY  
FIVE ELEVATION DEVELOPMENTS  
ARCHITECT: JAMES PAYNE  
GENERAL CONTRACTOR: LOCKHEED WINDOW CORP.

SUB NO. 800715  
DATE: 10/02/2007  
SCALE: 1/8" = 1'-0"  
SHEET BE.3 OF BE.9  
ANNAPOLIS

DWELLING UNIT DISTRIBUTION

BLDG. NO. 1	BLDG. NO. 2	BLDG. NO. 3	TOTAL
16	16	50	82
4	6	50	60
16	6	50	72
50	6	50	106

PERCENTAGE AND COLOR KEY


3 1/2 ROOM APT. = 84.7%  
 4 1/2 ROOM APT. = 10.7%  
 1-BEDROOM = 1-BEDROOM  
 2-BEDROOM = 2-BEDROOM

APARTMENT NUMBERS


APARTMENTS NUMBERS 1 TO 207 INCLUSIVE  
 APARTMENTS NUMBERS 41 TO 50 INCLUSIVE  
 APARTMENTS NUMBERS 41 TO 50 INCLUSIVE  
 NOTE: THIS FRONT ENTRANCE ROOM HAS THE HIGHEST NUMBER, AND ALL APARTMENT NUMBERS FOLLOWING IT RUN IN INCREASING ORDER. THE NUMBER OF CROSSERS AFTER EACH OF THE NUMBERS INDICATES THE NUMBER OF BEDROOMS IN THAT APARTMENT.

LEGEND

STREET NUMBER  
 APT. NO. IN WITH 2-BEDROOMS



**STREET AND APARTMENT NUMBERING PLAN**  
**BOSTON HOUSING AUTHORITY**  
**DEVELOPMENT MASS 2-27**  
**ANNAPOLIS**  
 BOSTON HOUSING AUTHORITY  
 100 STATE STREET, BOSTON, MASS. 02109  
 JOHN W. GRAY CO.  
 832 WALK STREET, BOSTON, MASS. 02108



P. L. U. H. B. / J. V. G.  
 BOSTON HOUSING AUTHORITY  
 ANIMPOUS  
 DORCHESTER, MASS.  
 PUBLIC HOUSING DEVELOPMENT  
 JOHN M. GRAY CO.  
 135 BEECH STREET, BOSTON, MASS.



PLAN OF ELEVATION

PLAN OF ELEVATION

DETAIL OF KITCHEN SINK FINISHING

PLAN OF ELEVATION

PLAN OF ELEVATION

FIRST FLOOR

FIRST FLOOR

FIRST FLOOR

FIRST FLOOR

FIRST FLOOR

FIRST FLOOR

DETAIL OF BATH TUB

DETAIL OF BATH TUB

DETAIL OF BATH TUB

DETAIL OF BATH TUB

DETAIL OF BATH TUB

DETAIL OF BATH TUB







**FOUNDATION PLAN**


BOSTON HOUSING AUTHORITY  
 DEVELOPMENT DEPARTMENT  
 ANNAPOLIS BOSTON, MASS.  
 DEVELOPED UNDER THE CIVIL SERVICE ACT  
 PUBLIC HOUSING ADMINISTRATION

**JOHN M. GRAY CO.**  
 ARCHITECTS  
 125 HIX STREET - BOSTON, MASS.  
 PHONE 5-3200




BASEMENT  
LEVELS  
SEE SHEET 5-100  
DATE: 1-15-54


BUILDING NO. 3



BUILDING NO. 1



BUILDING NO. 2



BUILDING NO. 3



**FIDELITY FLOOR PLAN**  
**BUILDING NO. 1, 2 AND 3**  
**BOSTON HOUSING AUTHORITY**  
 100 FLORENCE MASS. 2-27  
 ANNAPOLIS —  
 BRIDGEMAN UNDER THE UNITED STATES WORKING ACT  
 PUBLIC HOUSING ADMINISTRATION

**JOHN M. GRAY CO.**  
 ARCHITECTS  
 105 MALE STREET — BOSTON MASS.  
 5-22

DATE: 1-15-54  
 DRAWN BY: J. M. GRAY  
 CHECKED BY: J. M. GRAY  
 SCALE: AS SHOWN

APPROVED FOR THE CITY OF BOSTON  
 BY THE COMMISSIONER OF THE  
 DEPARTMENT OF PUBLIC WORKS  
 1-15-54






**SECOND FLOOR PLAN**  
**BUILDING NO. 1, 2 & 3.**  
 BOSTON HOUSING AUTHORITY  
 DEVELOPMENT MASS. 2 27  
 ANNAPOLIS  
 DESIGNED WITH THE VIEW OF THE BOSTON ACT  
 PUBLIC HOUSING ADMINISTRATION  
**JOHN M. GRAY CO.**  
 ARCHITECTS  
 135 MILBURN STREET  
 BOSTON, MASS.

DATE: 12/15/54  
 DRAWN BY: J. M. GRAY  
 CHECKED BY: J. M. GRAY  
 SCALE: AS SHOWN  
 SHEET NO. 5-3

**BUILDING No. 1**

**BUILDING No. 2**

**BUILDING No. 3**



**BUILDING No. 3**

**COMMUNITY ROOM**  
 (See Drawing 5-0)

**BUILDING No. 1**

**BUILDING No. 2**

**BUILDING No. 3**



BUILDING NO. 3

COMMUNITY BOOK - BLODE



BUILDING NO. 2




**SEALING PLATE**  
 SEALING PLATE NO. 1-2-3  
 BOSTON HOUSING AUTHORITY  
 DEVELOPMENT MASS. 2-27  
 ANNAPOLIS BOSTON, MASS.  
 RECORDS WITH THE OFFICE OF THE CLERK OF THE SUPERIOR COURT  
 PUBLIC HOUSING ADMINISTRATION  
 JOHN M. GRAY CO.  
 133 HALE STREET - BOSTON, MASS.  
 ARCHITECTS, ENGINEERS, INTERIORS, PLUMBERS, ELECTRICIANS, PAINTERS, ROOFERS, ETC.  
 5-4  
 1967

BUILDING NO. 2

BUILDING NO. 1

REVISIONS:  
 1. AS PER APPROVED PERMITS AND ALL CITY ORDINANCES.  
 2. AS PER APPROVED PERMITS AND ALL CITY ORDINANCES.  
 3. AS PER APPROVED PERMITS AND ALL CITY ORDINANCES.  
 4. AS PER APPROVED PERMITS AND ALL CITY ORDINANCES.

BUILDING NO 3



BUILDING NO 1

BUILDING NO 1

BUILDING NO 2

**ROOF FRAMING PLANS**  
**BUILDINGS NOS. 1-2 & 3**  
**BOSTON HOUSING AUTHORITY**  
 DEVELOPMENT, MASS. 2-27  
 ANNAPOLIS, MARYLAND

DESIGNED BY: J. J. ...  
 PUBLIC WORKS ADMINISTRATION  
 100 STATE STREET, BOSTON, MASS. 02109

DATE: ...  
 SCALE: ...  
 SHEET NO. ...

ARCHITECT: JOHN H. GRAY CO., INC.  
 115 NEW BRIDGE STREET, BOSTON, MASS. 02110  
 ENGINEER: ...  
 5-5

DRAFT

LIMITS  
 ALL WORK TO BE DONE IN ACCORDANCE WITH THE SPECIFICATIONS AND DRAWINGS FOR THE PROJECT.

LIMITS  
 ALL WORK TO BE DONE IN ACCORDANCE WITH THE SPECIFICATIONS AND DRAWINGS FOR THE PROJECT.




FIRST FLOOR FRAMING PLAN - UNIT A  
 SEE W SCALE PLAN FOR VARIATIONS

SECOND FLOOR FRAMING PLAN - UNIT A  
 SEE W SCALE PLAN FOR VARIATIONS

THIRD FLOOR FRAMING PLAN - UNIT A  
 SEE W SCALE PLAN FOR VARIATIONS


NOTE: FOR ROOF FRAMING PLAN SEE DRAWING NUMBER S-2




TYPICAL FRONT FRAMING ELEVATION - UNIT A  
 SEE W SCALE PLAN FOR VARIATIONS

TYPICAL REAR FRAMING ELEVATION - UNIT A  
 SEE W SCALE PLAN FOR VARIATIONS


TYPICAL BEAR FRAMING ELEVATION - UNIT A  
 SEE W SCALE PLAN FOR VARIATIONS



DETAIL OF COLUMN AND BEAM CONNECTION



TYPICAL FRAMING FOR ALL OPENINGS



TYPICAL FRAMING FOR EXCESS CONCRETE




TYPICAL DETAIL OF ROOF TRUSS CONNECTION



FRAMING DETAILS - UNIT A  
 BOSTON HOUSING AUTHORITY  
 DEVELOPMENT MASS 2 27  
 ANNAPOLIS, MARYLAND  
 PUBLIC HOUSING ADMINISTRATION  
 JOHN M. GRAY CO. ARCHITECTS  
 130 WASHINGTON STREET, BOSTON, MASS.  
 5-6



UNIT 1  
 1'-0" SCALE  
 1'-0" SCALE  
 1'-0" SCALE



**FIRST FLOOR FRAMING - UNIT B**  
 SEE 1'-0" SCALE PLAN FOR DIMENSIONS  
 SEE 1'-0" SCALE PLAN FOR DIMENSIONS  
 SEE 1'-0" SCALE PLAN FOR DIMENSIONS



**SECOND FLOOR FRAMING - UNIT B**  
 SEE 1'-0" SCALE PLAN FOR DIMENSIONS  
 SEE 1'-0" SCALE PLAN FOR DIMENSIONS  
 SEE 1'-0" SCALE PLAN FOR DIMENSIONS



**SECOND FLOOR CEILING PLAN - UNIT B**  
 SEE 1'-0" SCALE PLAN FOR DIMENSIONS  
 SEE 1'-0" SCALE PLAN FOR DIMENSIONS  
 SEE 1'-0" SCALE PLAN FOR DIMENSIONS

UNIT 2  
 1'-0" SCALE  
 1'-0" SCALE  
 1'-0" SCALE



**FRONT ELEVATION FRAMING - UNIT B**  
 SEE 1'-0" SCALE PLAN FOR DIMENSIONS  
 SEE 1'-0" SCALE PLAN FOR DIMENSIONS







**END ELEVATION FRAMING - UNIT B**  
 SEE 1'-0" SCALE PLAN FOR DIMENSIONS  
 SEE 1'-0" SCALE PLAN FOR DIMENSIONS



**REAR ELEVATION FRAMING - UNIT B**  
 SEE 1'-0" SCALE PLAN FOR DIMENSIONS  
 SEE 1'-0" SCALE PLAN FOR DIMENSIONS



**FRAMING DETAILS - UNIT B**  
 BOSTON HOUSING AUTHORITY  
 DEVELOPMENT MASS 2 27  
 ANNAPOLIS DORCHESTER, MASS.  
 BOSTON HOUSING AUTHORITY  
 PUBLIC HOUSING ADMINISTRATION  
 JOHN M. GRAY CO. ARCHITECTS  
 100 N. STATE ST. BOSTON, MASS. 02111  
 100 N. STATE ST. BOSTON, MASS. 02111  
 100 N. STATE ST. BOSTON, MASS. 02111




**JOHN M. GRAY CO.**  
ARCHITECTS  
125 WASHINGTON ST., BOSTON, MASS.  
TELEPHONE: 5-1111



SYMBOL	SCIENTIFIC NAME	HEIGHT IN FT.	HEIGHT CALIBER THORNT	NO. IN BALL
1	<i>Thalictrum flavum</i>	4-6	2-3	10
2	<i>Thalictrum aquilegifolium</i>	4-7	2	10
3	<i>Thalictrum minus</i>	6-10	2	10
4	<i>Thalictrum aquilegifolium</i>	4-6	2	10
5	<i>Thalictrum minus</i>	4-6	2	10
6	<i>Thalictrum aquilegifolium</i>	4-6	2	10
7	<i>Thalictrum minus</i>	4-6	2	10
8	<i>Thalictrum aquilegifolium</i>	4-6	2	10
9	<i>Thalictrum minus</i>	4-6	2	10
10	<i>Thalictrum aquilegifolium</i>	4-6	2	10
11	<i>Thalictrum minus</i>	4-6	2	10
12	<i>Thalictrum aquilegifolium</i>	4-6	2	10
13	<i>Thalictrum minus</i>	4-6	2	10
14	<i>Thalictrum aquilegifolium</i>	4-6	2	10
15	<i>Thalictrum minus</i>	4-6	2	10
16	<i>Thalictrum aquilegifolium</i>	4-6	2	10
17	<i>Thalictrum minus</i>	4-6	2	10
18	<i>Thalictrum aquilegifolium</i>	4-6	2	10
19	<i>Thalictrum minus</i>	4-6	2	10
20	<i>Thalictrum aquilegifolium</i>	4-6	2	10
21	<i>Thalictrum minus</i>	4-6	2	10
22	<i>Thalictrum aquilegifolium</i>	4-6	2	10
23	<i>Thalictrum minus</i>	4-6	2	10
24	<i>Thalictrum aquilegifolium</i>	4-6	2	10
25	<i>Thalictrum minus</i>	4-6	2	10
26	<i>Thalictrum aquilegifolium</i>	4-6	2	10
27	<i>Thalictrum minus</i>	4-6	2	10

NOTE: - See Appendix for details of plant. - See Appendix for details of plant.



NO.	SYMBOL	SCIENTIFIC NAME	HEIGHT IN FT.	HEIGHT CALIBER THORNT	NO. IN BALL
1	1	<i>Thalictrum flavum</i>	4-6	2-3	10
2	2	<i>Thalictrum aquilegifolium</i>	4-7	2	10
3	3	<i>Thalictrum minus</i>	6-10	2	10
4	4	<i>Thalictrum aquilegifolium</i>	4-6	2	10
5	5	<i>Thalictrum minus</i>	4-6	2	10
6	6	<i>Thalictrum aquilegifolium</i>	4-6	2	10
7	7	<i>Thalictrum minus</i>	4-6	2	10
8	8	<i>Thalictrum aquilegifolium</i>	4-6	2	10
9	9	<i>Thalictrum minus</i>	4-6	2	10
10	10	<i>Thalictrum aquilegifolium</i>	4-6	2	10
11	11	<i>Thalictrum minus</i>	4-6	2	10
12	12	<i>Thalictrum aquilegifolium</i>	4-6	2	10
13	13	<i>Thalictrum minus</i>	4-6	2	10
14	14	<i>Thalictrum aquilegifolium</i>	4-6	2	10
15	15	<i>Thalictrum minus</i>	4-6	2	10
16	16	<i>Thalictrum aquilegifolium</i>	4-6	2	10
17	17	<i>Thalictrum minus</i>	4-6	2	10
18	18	<i>Thalictrum aquilegifolium</i>	4-6	2	10
19	19	<i>Thalictrum minus</i>	4-6	2	10
20	20	<i>Thalictrum aquilegifolium</i>	4-6	2	10
21	21	<i>Thalictrum minus</i>	4-6	2	10
22	22	<i>Thalictrum aquilegifolium</i>	4-6	2	10
23	23	<i>Thalictrum minus</i>	4-6	2	10
24	24	<i>Thalictrum aquilegifolium</i>	4-6	2	10
25	25	<i>Thalictrum minus</i>	4-6	2	10
26	26	<i>Thalictrum aquilegifolium</i>	4-6	2	10
27	27	<i>Thalictrum minus</i>	4-6	2	10

PLANT LIST & PLAN  
 BOSTON HOUSING AUTHORITY  
 DEVELOPMENT MASS 2-27  
 ANNAPOLIS BOSTON, MASS  
 COLONIAL BOSTON, MASS  
 JOHN M. GRAY CO.  
 121 N. STATE ST. BOSTON, MASS  
 TEL: 552-1212






**TOPOGRAPHIC & UTILITY MAP**  
**ANNAPOLIS DEVELOPMENT**

BOSTON HOUSING AUTHORITY  
 BOSTON SUFFOLK COUNTY MASSACHUSETTS  
 NEW ENGLAND SURVEY SERVICE INC. 255 ATLANTIC AVE. BOSTON, MASS.  
 SCALE 1/6 FEET TO AN INCH  
 OCTOBER 27, 1959  
 PROJECT MASS 2-27  
 PLAN NO. X X-2

DATE: MARCH 2, 1960  
 DRAWN BY: J. M. O'NEIL  
 CHECKED BY: J. M. O'NEIL  
 SCALE: AS SHOWN



NOTE: Elevations are referred to Boston City Base. All elevations are as shown on this map. Subsurface utilities shown are from plans and records of the City of Boston Water and Sewer Department, and utility companies. For property line spots, see sheet.

Block Map Elev. 42.53  
 Right-of-way corner 2nd Cont. 294

I hereby certify that the information shown on this map is true and correct and that the information is accurately plotted and properly shown.


*J. M. O'Neil*  
 March 2, 1960  
 President, New England Survey Service Inc.



# National Flood Hazard Layer FIRMMette



71°4'1"W 42°19'16"N



## Legend

SEE FIS REPORT FOR DETAILED LEGEND AND INDEX MAP FOR FIRM PANEL LAYOUT

SPECIAL FLOOD HAZARD AREAS		Without Base Flood Elevation (BFE) <i>Zone A, V, A99</i>
		With BFE or Depth <i>Zone AE, AO, AH, VE, AR</i>
		Regulatory Floodway

OTHER AREAS OF FLOOD HAZARD		0.2% Annual Chance Flood Hazard, Areas of 1% annual chance flood with average depth less than one foot or with drainage areas of less than one square mile <i>Zone X</i>
		Future Conditions 1% Annual Chance Flood Hazard <i>Zone X</i>
		Area with Reduced Flood Risk due to Levee. See Notes. <i>Zone X</i>
		Area with Flood Risk due to Levee <i>Zone D</i>

OTHER AREAS		NO SCREEN Area of Minimal Flood Hazard <i>Zone X</i>
		Effective LOMRs
		Area of Undetermined Flood Hazard <i>Zone D</i>

GENERAL STRUCTURES		Channel, Culvert, or Storm Sewer
		Levee, Dike, or Floodwall

OTHER FEATURES		20.2 Cross Sections with 1% Annual Chance
		17.5 Water Surface Elevation
		Coastal Transect
		Base Flood Elevation Line (BFE)
		Limit of Study
		Jurisdiction Boundary
		Profile Baseline
	Hydrographic Feature	

MAP PANELS		Digital Data Available
		No Digital Data Available
		Unmapped

The pin displayed on the map is an approximate point selected by the user and does not represent an authoritative property location.

This map complies with FEMA's standards for the use of digital flood maps if it is not void as described below. The basemap shown complies with FEMA's basemap accuracy standards

The flood hazard information is derived directly from the authoritative NFHL web services provided by FEMA. This map was exported on **7/25/2022 at 7:24 AM** and does not reflect changes or amendments subsequent to this date and time. The NFHL and effective information may change or become superseded by new data over time.

This map image is void if the one or more of the following map elements do not appear: basemap imagery, flood zone labels, legend, scale bar, map creation date, community identifiers, FIRM panel number, and FIRM effective date. Map images for unmapped and unmodernized areas cannot be used for regulatory purposes.

## Assessing On-Line

[« New search](#)

[Map](#)

<b>Parcel ID:</b>	1301797000
<b>Address:</b>	11-19 BAKERSFIELD ST BOSTON MA 02125
<b>Property Type:</b>	Exempt
<b>Classification Code:</b>	0902 (Exempt Ownership / CITY OF BOSTON)
<b>Lot Size:</b>	55,218 sq ft
<b>Gross Area:</b>	41,961 sq ft
<b>Year Built:</b>	1950
<b>Owner on Saturday, January 1, 2022:</b>	BOSTON HOUSING AUTH
<b>Owner's Mailing Address:</b>	11 BAKERSFIELD DORCHESTER MA 02125
<b>Residential Exemption:</b>	No
<b>Personal Exemption:</b>	No

Value/Tax	Current Owner																																																																																																																					
<p><b>Assessment as of Friday, January 1, 2021, statutory lien date.</b></p> <p><b>FY2022 Building value:</b> \$4,198,600.00  <b>FY2022 Land Value:</b> \$1,684,300.00  <b>FY2022 Total Assessed Value:</b> \$5,882,900.00</p> <p><b>FY2022 Tax Rates</b> (per thousand):                      - Residential: \$10.88                      - Commercial: \$24.98</p> <p><b>FY2023 Preliminary Tax (Q1 + Q2):</b>                      Estimated Tax: \$0.00                      Community Preservation: \$0.00                      Total Tax, First Half: \$0.00</p>	<p>1 BOSTON HOUSING AUTH</p> <p>Owner information may not reflect any changes submitted to City of Boston Assessing after December 28, 2021.</p>																																																																																																																					
Abatements/Exemptions	Value History																																																																																																																					
<p>Applications for Abatements for FY2023 are not yet available online. Applications will become available for download beginning 1/1/2022</p> <p>This type of parcel is not eligible for a residential or personal exemption.</p>	<table border="0"> <thead> <tr> <th>Fiscal Year</th> <th>Property Type</th> <th>Assessed Value *</th> </tr> </thead> <tbody> <tr><td>2022</td><td>Exempt</td><td>\$5,882,900.00</td></tr> <tr><td>2021</td><td>Exempt</td><td>\$5,851,900.00</td></tr> <tr><td>2020</td><td>Exempt</td><td>\$5,761,000.00</td></tr> <tr><td>2019</td><td>Exempt</td><td>\$5,466,500.00</td></tr> <tr><td>2018</td><td>Exempt</td><td>\$5,214,000.00</td></tr> <tr><td>2017</td><td>Exempt</td><td>\$4,913,500.00</td></tr> <tr><td>2016</td><td>Exempt</td><td>\$4,421,000.00</td></tr> <tr><td>2015</td><td>Exempt</td><td>\$3,863,500.00</td></tr> <tr><td>2014</td><td>Exempt</td><td>\$3,228,000.00</td></tr> <tr><td>2013</td><td>Exempt</td><td>\$2,850,000.00</td></tr> <tr><td>2012</td><td>Exempt</td><td>\$2,684,000.00</td></tr> <tr><td>2011</td><td>Exempt</td><td>\$2,634,500.00</td></tr> <tr><td>2010</td><td>Exempt</td><td>\$2,660,000.00</td></tr> <tr><td>2009</td><td>Exempt</td><td>\$2,797,500.00</td></tr> <tr><td>2008</td><td>Exempt</td><td>\$2,797,500.00</td></tr> <tr><td>2007</td><td>Exempt</td><td>\$2,769,000.00</td></tr> <tr><td>2006</td><td>Exempt</td><td>\$2,588,000.00</td></tr> <tr><td>2005</td><td>Apartment Building</td><td>\$2,317,000.00</td></tr> <tr><td>2004</td><td>Apartment Building</td><td>\$2,425,500.00</td></tr> <tr><td>2003</td><td>Apartment Building</td><td>\$1,921,500.00</td></tr> <tr><td>2002</td><td>Exempt</td><td>\$2,039,000.00</td></tr> <tr><td>2001</td><td>Exempt</td><td>\$1,826,000.00</td></tr> <tr><td>2000</td><td>Exempt</td><td>\$1,864,500.00</td></tr> <tr><td>1999</td><td>Exempt</td><td>\$1,698,000.00</td></tr> <tr><td>1998</td><td>Exempt</td><td>\$1,698,000.00</td></tr> <tr><td>1997</td><td>Exempt</td><td>\$1,741,000.00</td></tr> <tr><td>1996</td><td>Exempt</td><td>\$1,669,500.00</td></tr> <tr><td>1995</td><td>Exempt</td><td>\$1,596,000.00</td></tr> <tr><td>1994</td><td>Exempt</td><td>\$1,509,000.00</td></tr> <tr><td>1993</td><td>Exempt</td><td>\$1,508,000.00</td></tr> <tr><td>1992</td><td>Exempt</td><td>\$1,579,500.00</td></tr> <tr><td>1991</td><td>Exempt</td><td>\$2,060,000.00</td></tr> <tr><td>1990</td><td>Exempt</td><td>\$2,060,000.00</td></tr> <tr><td>1989</td><td>Exempt</td><td>\$1,998,000.00</td></tr> <tr><td>1988</td><td>Exempt</td><td>\$1,637,500.00</td></tr> <tr><td>1987</td><td>Exempt</td><td>\$1,387,500.00</td></tr> <tr><td>1986</td><td>Exempt</td><td>\$1,273,000.00</td></tr> <tr><td>1985</td><td>Exempt</td><td>\$1,169,000.00</td></tr> </tbody> </table>	Fiscal Year	Property Type	Assessed Value *	2022	Exempt	\$5,882,900.00	2021	Exempt	\$5,851,900.00	2020	Exempt	\$5,761,000.00	2019	Exempt	\$5,466,500.00	2018	Exempt	\$5,214,000.00	2017	Exempt	\$4,913,500.00	2016	Exempt	\$4,421,000.00	2015	Exempt	\$3,863,500.00	2014	Exempt	\$3,228,000.00	2013	Exempt	\$2,850,000.00	2012	Exempt	\$2,684,000.00	2011	Exempt	\$2,634,500.00	2010	Exempt	\$2,660,000.00	2009	Exempt	\$2,797,500.00	2008	Exempt	\$2,797,500.00	2007	Exempt	\$2,769,000.00	2006	Exempt	\$2,588,000.00	2005	Apartment Building	\$2,317,000.00	2004	Apartment Building	\$2,425,500.00	2003	Apartment Building	\$1,921,500.00	2002	Exempt	\$2,039,000.00	2001	Exempt	\$1,826,000.00	2000	Exempt	\$1,864,500.00	1999	Exempt	\$1,698,000.00	1998	Exempt	\$1,698,000.00	1997	Exempt	\$1,741,000.00	1996	Exempt	\$1,669,500.00	1995	Exempt	\$1,596,000.00	1994	Exempt	\$1,509,000.00	1993	Exempt	\$1,508,000.00	1992	Exempt	\$1,579,500.00	1991	Exempt	\$2,060,000.00	1990	Exempt	\$2,060,000.00	1989	Exempt	\$1,998,000.00	1988	Exempt	\$1,637,500.00	1987	Exempt	\$1,387,500.00	1986	Exempt	\$1,273,000.00	1985	Exempt	\$1,169,000.00
Fiscal Year	Property Type	Assessed Value *																																																																																																																				
2022	Exempt	\$5,882,900.00																																																																																																																				
2021	Exempt	\$5,851,900.00																																																																																																																				
2020	Exempt	\$5,761,000.00																																																																																																																				
2019	Exempt	\$5,466,500.00																																																																																																																				
2018	Exempt	\$5,214,000.00																																																																																																																				
2017	Exempt	\$4,913,500.00																																																																																																																				
2016	Exempt	\$4,421,000.00																																																																																																																				
2015	Exempt	\$3,863,500.00																																																																																																																				
2014	Exempt	\$3,228,000.00																																																																																																																				
2013	Exempt	\$2,850,000.00																																																																																																																				
2012	Exempt	\$2,684,000.00																																																																																																																				
2011	Exempt	\$2,634,500.00																																																																																																																				
2010	Exempt	\$2,660,000.00																																																																																																																				
2009	Exempt	\$2,797,500.00																																																																																																																				
2008	Exempt	\$2,797,500.00																																																																																																																				
2007	Exempt	\$2,769,000.00																																																																																																																				
2006	Exempt	\$2,588,000.00																																																																																																																				
2005	Apartment Building	\$2,317,000.00																																																																																																																				
2004	Apartment Building	\$2,425,500.00																																																																																																																				
2003	Apartment Building	\$1,921,500.00																																																																																																																				
2002	Exempt	\$2,039,000.00																																																																																																																				
2001	Exempt	\$1,826,000.00																																																																																																																				
2000	Exempt	\$1,864,500.00																																																																																																																				
1999	Exempt	\$1,698,000.00																																																																																																																				
1998	Exempt	\$1,698,000.00																																																																																																																				
1997	Exempt	\$1,741,000.00																																																																																																																				
1996	Exempt	\$1,669,500.00																																																																																																																				
1995	Exempt	\$1,596,000.00																																																																																																																				
1994	Exempt	\$1,509,000.00																																																																																																																				
1993	Exempt	\$1,508,000.00																																																																																																																				
1992	Exempt	\$1,579,500.00																																																																																																																				
1991	Exempt	\$2,060,000.00																																																																																																																				
1990	Exempt	\$2,060,000.00																																																																																																																				
1989	Exempt	\$1,998,000.00																																																																																																																				
1988	Exempt	\$1,637,500.00																																																																																																																				
1987	Exempt	\$1,387,500.00																																																																																																																				
1986	Exempt	\$1,273,000.00																																																																																																																				
1985	Exempt	\$1,169,000.00																																																																																																																				

\* Actual Billed Assessments

View [Quarterly Tax Bill and Payment Information](#) for this parcel for FY2022 and FY2023.

View [approved building permits](#) associated with this parcel.

Questions? For CURRENT fiscal year tax bill Questions, contact the [Taxpayer Referral & Assistance Center](#). For PRIOR fiscal year tax payments, interest charges, fees, etc. contact the Collector's office at 617-635-



4131.

DRAFT



**NOTES TO USERS**

This map is for use in administering the National Flood Insurance Program. It does not necessarily identify all areas subject to flooding, particularly from local drainage sources of small size. The community map repository should be consulted for possible updated or additional flood hazard information.

To obtain more detailed information in areas where **Base Flood Elevations (BFEs)** and/or **floodways** have been determined, users are encouraged to consult the Flood Profiles and Floodway Data and/or Summary of Stillwater Elevations tables contained within the Flood Insurance Study (FIS) Report that accompanies this FIRM. Users should be aware that BFEs shown on the FIRM represent rounded whole-foot elevations. These BFEs are intended for flood insurance rating purposes only and should not be used as the sole source of flood elevation information. Accordingly, flood elevation data presented in the FIS Report should be used in conjunction with the FIRM for purposes of construction and/or floodplain management.

**Coastal Base Flood Elevations** shown on this map apply only landward of 0.0' North American Vertical Datum of 1988 (NAVD 88). Users of this FIRM should be aware that coastal flood elevations are also provided in the Summary of Stillwater Elevations table in the Flood Insurance Study Report for this jurisdiction. Elevations shown in the Summary of Stillwater Elevations table should be used for construction and/or floodplain management purposes when they are higher than the elevations shown on this FIRM.

Boundaries of the **floodways** were computed at cross sections and interpolated between cross sections. The floodways were based on hydraulic considerations with regard to requirements of the National Flood Insurance Program. Floodway widths and other pertinent floodway data are provided in the Flood Insurance Study Report for this jurisdiction.

The AE Zone category has been divided by a **Limit of Moderate Wave Action (LIMWA)**. The LIMWA represents the approximate landward limit of the 1.5-foot breaking wave. The effects of wave hazards between the VE Zone and the LIMWA (or between the shoreline and the LIMWA for areas where VE Zones are not identified) will be similar to, but less severe than those in the VE Zone.

Certain areas not in Special Flood Hazard Areas may be protected by **flood control structures**. Refer to Section 2.4 "Flood Protection Measures" of the Flood Insurance Study Report for information on flood control structures for this jurisdiction.

The **projection** used in the preparation of this map was Massachusetts State Plane Mainland Zone (FIPS zone 2001). The **horizontal datum** was NAD 83, GRS 1980 spheroid. Differences in datum, spheroid, projection or UTM zones used in the production of FIRMs for adjacent jurisdictions may result in slight positional differences in map features across jurisdiction boundaries. These differences do not affect the accuracy of this FIRM.

Flood elevations on this map are referenced to the North American Vertical Datum of 1988. These flood elevations must be compared to structure and ground elevations referenced to the same vertical datum. For information regarding conversion between the National Geodetic Vertical Datum of 1929 and the North American Vertical Datum of 1988, visit the National Geodetic Survey website at <http://www.ngs.noaa.gov> or contact the National Geodetic Survey at the following address:

NGS Information Services  
NOAA, NNGS12  
National Geodetic Survey  
SSMC-3, #9202  
1315 East-West Highway  
Silver Spring, Maryland 20910-3282  
(301) 713-3242

To obtain current elevation, description, and/or location information for **bench marks** shown on this map, please contact the Information Services Branch of the National Geodetic Survey at (301) 713-3242, or visit its website at <http://www.ngs.noaa.gov>.

**Base map** information shown on this FIRM is derived from Massachusetts Geographic Information System (MassGIS) digital ortho-photography produced at 45 centimeter (2005) and 30 centimeter (2008) resolution. Aerial photography is dated Spring 2005 and Spring 2008.

The **profile baselines** depicted on this map represent the hydraulic modeling baselines that match the flood profiles in the FIS report. As a result of improved topographic data, the **profile baseline**, in some cases, may deviate significantly from the channel centerline or appear outside the SFHA.

Based on updated topographic information, this map reflects more detailed and up-to-date **stream channel configurations** and **floodplain delineations** than those shown on the previous FIRM for this jurisdiction. As a result, the Flood Profiles and Floodway Data Tables for multiple streams in the Flood Insurance Study Report (which contains authoritative hydraulic data) may reflect stream channel distances that differ from what is shown on the map. Also, the road to floodplain relationships for unrevised streams may differ from what is shown on previous maps.


**Corporate limits** shown on this map are based on the best data available at the time of publication. Because changes due to annexations or de-annexations may have occurred after this map was published, map users should contact appropriate community officials to verify current corporate limit locations.

Please refer to the separately printed **Map Index** for an overview map of the county showing the layout of map panels, community map repository addresses, and a Listing of Communities table containing National Flood Insurance Program dates for each community as well as a listing of the panels on which each community is located.

For information on available products associated with this FIRM visit the **Map Service Center (MSC)** website at <http://msc.fema.gov>. Available products may include previously issued Letters of Map Change, a Flood Insurance Study Report, and/or digital versions of this map. Many of these products can be ordered or obtained directly from the MSC website.

If you have **questions about this map**, how to order products, or the National Flood Insurance Program in general, please call the **FEMA Map Information eXchange (FMIX)** at 1-877-FEMA-MAP (1-877-336-2627) or visit the FEMA website at <http://www.fema.gov/business/infp>.

Only coastal structures that are certified to provide protection from the 1-percent-annual-chance flood are shown on this panel. However, all structures taken into consideration for the purpose of coastal flood hazard analysis and mapping are present in the DFIRM database in S\_Gen\_Struct.



**LEGEND**

- SPECIAL FLOOD HAZARD AREAS (SFHAs) SUBJECT TO INUNDATION BY THE 1% ANNUAL CHANCE FLOOD. The 1% annual chance flood (100-year flood), also known as the base flood, is the flood area that has a 1% chance of being equaled or exceeded in any given year. The Special Flood Hazard Area is the area subject to flooding by the 1% annual chance flood. Areas of Special Flood Hazard include Zones A, AE, AH, AO, AR, A99, V, and VE. The Base Flood Elevation is the water-surface elevation of the 1% annual chance flood.
  - ZONE AE** No Base Flood Elevations determined.
  - ZONE AE** Base Flood Elevations determined.
  - ZONE AH** Flood depths of 1 to 3 feet (usually areas of ponding); Base Flood Elevations determined.
  - ZONE AO** Flood depths of 1 to 3 feet (usually sheet flow on sloping terrain); average depths determined. For areas of alluvial fan flooding, velocities also determined.
  - ZONE AR** Special Flood Hazard Areas formerly protected from the 1% annual chance flood by a flood control system that was subsequently identified. Zone AR indicates that the former flood control system is being restored to provide protection from the 1% annual chance or greater flood.
  - ZONE A99** Area to be protected from 1% annual chance flood by a Federal flood protection system under construction; no Base Flood Elevations determined.
  - ZONE V** Coastal flood zone with velocity hazard (wave action); no Base Flood Elevations determined.
  - ZONE VE** Coastal flood zone with velocity hazard (wave action); Base Flood Elevations determined.
  - FLOODWAY AREAS IN ZONE AE
- The floodway is the channel of a stream plus any adjacent floodplain areas that must be kept free of encroachments that the 1% annual chance flood can be carried without substantial increases in flood heights.
- OTHER FLOOD AREAS
  - ZONE X** Areas of 0.2% annual chance flood; areas of 1% annual chance flood with average depths of less than 1 foot or with drainage areas less than 1 square mile; and areas protected by levees from 1% annual chance flood.
  - OTHER AREAS
  - ZONE X** Areas determined to be outside the 0.2% annual chance floodplain.
  - ZONE D** Areas in which flood hazards are undetermined, but possible.
  - COASTAL BARRIER RESOURCES SYSTEM (CBRS) AREAS
  - OTHERWISE PROTECTED AREAS (OPAs)
- CBRS areas and OPAs are normally located within or adjacent to Special Flood Hazard Areas.
- 1% Annual Chance Floodplain Boundary
  - 0.2% Annual Chance Floodplain Boundary
  - Floodway boundary
  - Zone D boundary
  - CBRS and OPA boundary
  - Boundary dividing Special Flood Hazard Area Zones and boundary dividing Special Flood Hazard Areas of different Base Flood Elevations, flood depths, or flood velocities.
  - Limit of Moderate Wave Action
  - Limit of Moderate Wave Action coincident with Zone Break
  - Base Flood Elevation line and value; elevation in feet\*
  - Base Flood Elevation value where uniform within zone; elevation in feet\*

\*Referenced to the North American Vertical Datum of 1988

- Cross section line
- Transect line
- Culvert
- Bridge

Geographic coordinates referenced to the North American Datum of 1983 (NAD 83) Western Hemisphere

4989000 M  
4989000 N  
DX5510 X

MAP REPOSITORIES  
Refer to Map Repositories list on Map Index

EFFECTIVE DATE OF COUNTYWIDE FLOOD INSURANCE RATE MAP  
September 25, 2009

EFFECTIVE DATE(S) OF REVISION(S) TO THIS PANEL  
March 16, 2016 - to change Base Flood Elevations and Special Flood Hazard Areas, to change zone designations, to update the effects of wave action, to update corporate limits, to add roads and road names, to incorporate previously issued Letters of Map Revision and to modify Coastal Barrier Resource System units.

For community map revision history prior to countywide mapping, refer to the Community Map History table located in the Flood Insurance Study report for this jurisdiction.

To determine if flood insurance is available in this community, contact your insurance agent or call the National Flood Insurance Program at 1-800-638-6620.

MAP SCALE 1" = 500'

250 0 500 1000  
150 0 150 300  
FEET  
METERS

**NATIONAL FLOOD INSURANCE PROGRAM**

PANEL 0083J

**FIRM**  
FLOOD INSURANCE RATE MAP  
SUFFOLK COUNTY,  
MASSACHUSETTS  
(ALL JURISDICTIONS)

PANEL 83 OF 176  
(SEE MAP INDEX FOR FIRM PANEL LAYOUT)

CONTAINS:  
COMMUNITY NUMBER PANEL SUFFIX  
BOSTON, CITY OF 250286 0083 J

Notice to User: The **Map Number** shown below should be used when placing map orders; the **Community Number** shown above should be used on insurance applications for the subject community.


MAP NUMBER 25025C0083J  
MAP REVISED MARCH 16, 2016  
Federal Emergency Management Agency





## 52 Sumner St, Dorchester, MA 02125, USA

Latitude, Longitude: 42.3178178, -71.0617784



Date	7/25/2022, 6:23:30 AM
Design Code Reference Document	ASCE41-13
Custom Probability	
Site Class	D - Stiff Soil

Type	Description	Value
Hazard Level		BSE-2N
$S_s$	spectral response (0.2 s)	0.212
$S_1$	spectral response (1.0 s)	0.068
$S_{XS}$	site-modified spectral response (0.2 s)	0.339
$S_{X1}$	site-modified spectral response (1.0 s)	0.164
$F_a$	site amplification factor (0.2 s)	1.6
$F_v$	site amplification factor (1.0 s)	2.4
ssuh	max direction uniform hazard (0.2 s)	0.238
crs	coefficient of risk (0.2 s)	0.892
ssrt	risk-targeted hazard (0.2 s)	0.212
ssd	deterministic hazard (0.2 s)	1.5
s1uh	max direction uniform hazard (1.0 s)	0.076
cr1	coefficient of risk (1.0 s)	0.9
s1rt	risk-targeted hazard (1.0 s)	0.068
s1d	deterministic hazard (1.0 s)	0.6

Type	Description	Value
Hazard Level		BSE-1N
$S_{XS}$	site-modified spectral response (0.2 s)	0.226
$S_{X1}$	site-modified spectral response (1.0 s)	0.109



Type	Description	Value
Hazard Level		BSE-2E
$S_S$	spectral response (0.2 s)	0.128
$S_1$	spectral response (1.0 s)	0.044
$S_{XS}$	site-modified spectral response (0.2 s)	0.205
$S_{X1}$	site-modified spectral response (1.0 s)	0.105
$f_a$	site amplification factor (0.2 s)	1.6
$f_v$	site amplification factor (1.0 s)	2.4

Type	Description	Value
Hazard Level		BSE-1E
$S_S$	spectral response (0.2 s)	0.043
$S_1$	spectral response (1.0 s)	0.016
$S_{XS}$	site-modified spectral response (0.2 s)	0.069
$S_{X1}$	site-modified spectral response (1.0 s)	0.039
$F_a$	site amplification factor (0.2 s)	1.6
$F_v$	site amplification factor (1.0 s)	2.4

Type	Description	Value
Hazard Level		TL Data
T-Sub-L	Long-period transition period in seconds	6

## DISCLAIMER

While the information presented on this website is believed to be correct, SEAC / OSHPD and its sponsors and contributors assume no responsibility or liability for its accuracy. The material presented in this web application should not be used or relied upon for any specific application without competent examination and verification of its accuracy, suitability and applicability by engineers or other licensed professionals. SEAC / OSHPD do not intend that the use of this information replace the sound judgment of such competent professionals, having experience and knowledge in the field of practice, nor to substitute for the standard of care required of such professionals in interpreting and applying the results of the seismic data provided by this website. Users of the information from this website assume all liability arising from such use. Use of the output of this website does not imply approval by the governing building code bodies responsible for building code approval and interpretation for the building site described by latitude/longitude location in the search results of this website.

# **APPENDIX F**

## **Property Evaluator Qualifications**

DRAFT



# Juan C. Sequeira

## Project Manager

---

### EDUCATION

- Bachelor of Architecture - American University, 2008
- Minor in Finance - American University, 2010

### SUMMARY OF PROFESSIONAL EXPERIENCE

Mr. Sequeira has more than 11 years of experience in the architectural design and inspection as project management of residential and hospitality projects domestic and abroad. He has performed building and property assessments for varying scopes and customer requirements for the commercial real estate, banking and insurance industries.

Currently, Mr. Sequeira is responsible for performing Property Condition Assessments that include identifying deficiencies, providing overall professional judgment of a property's condition and preparing cost estimates for repairs and projected replacement costs. He performs Property Condition Assessments of varying property types including retail, office, commercial, hospitality, industrial, multi-family, and senior living facilities throughout the United States.

Prior to joining AEI Consultants, Mr. Sequeira has worked on construction documents, schematic design, design development and project management for many different types of architecture fields including: Corporate, Commercial, Mixed-Use, Retail, Hospitality, and Residential. In addition, these assessments included formulating replacement costs, assessing property and liability risks and providing recommendations.

### PROJECT EXPERIENCE

Project experience for Mr. Sequeira includes:

- Numerous multifamily assignments in accordance with Fannie Mae, Freddie Mac, and HUD requirements.
- Multi-Family - Tesora Apartments, Las Vegas, NV; 223(f) Refi-Acq and E-Tool.
- Multi-Family - Cherrydale Apartments, Baltimore, MD; 223(f) Refi-Acq and E-Tool.
- Multi-Family - Arella Forest at Woodland, Conroe, TX; 223(f) Refi-Acq and E-Tool.
- Multi-Family - Forrest Brook Apartments, York, SC; 223(f) Refi-Acq and E-Tool.
- Multi-Family - Lincoln Village Apartments, Lincoln, OR; 223(f) Refi-Acq and E-Tool.
- Multi-Family - Park Manor Apartments, Lebanon, OR; 223(f) Refi-Acq and E-Tool.



- Multi-Family - Willamalane Apartments, Milwaukee, OR; 223(f) Refi-Acq and E-Tool.
- Multi-Family - Pine Tree Apartments, Winston, OR; 223(f) Refi-Acq and E-Tool.
- Multi-Family - Parkside Village, Roseburg, OR; 223(f) Refi-Acq and E-Tool.
- Multi-Family - Primrose of Shadow Creek, Austin, TX; 223(f) Refi-Acq and E-Tool.
- Multi-Family - Ridge at Trinity, Dallas, TX; 223(f) Refi-Acq and E-Tool.
- Multi-Family - Friendship Haven Healthcare Center, Friendswood, TX; 223(f) Refi-Acq and E-Tool.
- Multi-Family - Heritage Square Fort Worth, Fort Worth, TX; 223(f) Refi-Acq and E-Tool.
- In depth experience with multifamily assessments that conform to all GSE (Fannie Mae & Freddie Mac) and HUD requirements for multifamily property condition assessments
- Multi-Family - Greenbriar Mansion, Fort Worth, TX; 223(f) Refi-Acq and E-Tool.
- Multi-Family - Regency Garden Apartments, Bryan, TX; 223(f) Refi-Acq and E-Tool.
- Multi-Family - The Duke Apartments, Victoria, TX; 223(f) Refi-Acq and E-Tool.
- Multi-Family - Castlewood Apartments, Houston, TX; 223(f) Refi-Acq and E-Tool.

## **William David Taylor – National Client Manager - HUD**

---

### **Training/Licenses/Registrations:**

International Code Council Certified Building Inspector  
International Code Council Certified Commercial Building Inspector  
International Code Council Certified Residential Building Inspector  
International Code Council Certified Accessibility Inspector / Plan Examiner  
Commonwealth of Virginia Certified Commercial Building Inspector  
Commonwealth of Virginia Certified Residential Building Inspector  
Integrated Pest Management in Multifamily Housing (Training)  
International Code Council Accessibility & Usability for Residential Buildings (Training)  
Integrated Pest Management in Multifamily Housing Course - National Healthy Homes Training Center  
Property Maintenance Inspection, Electrical Inspection & Understanding Braced Walls Training by Virginia  
Building Code Academy  
Building Performance Institute (BPI) Certified Multifamily Building Analyst Professional  
Basics of Elevator Inspections given by Sanjay Kamani, QEI, KP Property Advisors LLC  
VHDA Universal Design Course

### **Education:**

J. Sargent Reynolds Community College – Courses in Architectural Design

### **Experience:**

Mr. Taylor has extensive experience with regards to commercial and residential construction, design, and inspection issues. Mr. Taylor has greater than fifteen (15) years' experience in the construction field. He was in the Building Inspections for the City of Richmond and did construction design for Virginia based construction and engineering firms. During his former employment he was responsible for design, review, and inspection for code compliance on multiple projects throughout the Commonwealth of Virginia. Mr. Taylor has attended specialized building classes and has in depth understanding regarding building construction and inspection. He has performed and multiple building assessment projects for HUD MAP, HUD LEAN, and Public Housing Authority clients. He is knowledgeable of HUD's Capital Needs Assessment guidelines and software. In addition, he has extensive experience and training on numerous accessibility standards, including, UFAS, ADA, ANSI, and the Fair Housing Act Guidelines.

As a Project Manager - HUD, Mr. Taylor is responsible for conducting and preparing Property Condition Reports, Project Capital Needs Assessments, and Phase I Environmental Site Assessments throughout AEI.

Mr. Taylor's HUD's industry experience includes:

- Performing RAD Physical Condition Assessments at more than 50 Public Housing Authority's
- More than 5 years' experience in multifamily assessments including numerous assignments for Freddie Mac, HUD, and Fannie Mae execution
- Performing over 200 HUD MAP 223(f) assessments.
- Performing HUD Map 202 assessments in multiple states.
- Performing over 100 HUD LEAN assessments.
- Performing HUD MAP 223(a)(7) assessments.
- Performing Tax Credit assessments in multiple states.
- Performing HUD (SPRAC), HUD OAHP, Standard and Poor, ASTM, and Freddie Mac assessments.







# INTERNATIONAL CODE COUNCIL

## WILLIAM TAYLOR

*The International Code Council attests that the individual named on this certificate has satisfactorily demonstrated knowledge as required by the International Code Council by successfully completing the prescribed written examination based on codes and standards then in effect, and is hereby issued this certification as:*

**Accessibility Inspector/Plans Examiner**

*Given this day October 19, 2021*

Certificate No. 8076685

Handwritten signature of Cindy Davis in black ink.

**Cindy Davis, CBO**  
President, Board of Directors

Handwritten signature of Dominic Sims in black ink.

**Dominic Sims, CBO**  
Chief Executive Officer



## **Roy Anderson PE – Seismic Services Manager, Building Assessments**

---

University of California, San Diego; BS Structural Engineering 1990

Professional Engineer, California, Civil 82059

California Licensed General Contractor, B641049, Inactive

ATC First Responder Training, California OES Volunteer

Redwood Empire Remodelers Association, Board Member, Past President

Appointed to the City of Santa Rosa Board of Building Regulations Appeals, Chairman

Committee Member ASTM WK55885 Seismic Risk Assessment of Real Estate Portfolios

American Society of Civil Engineers (ASCE)

Structural Engineers Association of Northern California (SEAONC)

Earthquake Engineering Research Institute (EERI)

Mr. Anderson has over 39 years of construction, construction management, structural design, seismic retrofit, structural assessment, and commercial due diligence experience. He owned and operated a successful structural design consulting firm for over 14 years. His project experience includes public infrastructure, public works, and private developments including both residential and commercial projects. He has acted as a regional manager for a national consulting services firm overseeing property and casualty and seismic risk assessment operations in the western states, performing over 2000 Seismic Risk Assessment (Probable Maximum Loss) assessments and reports in the seismically active United States, Europe, and Mexico, over 100 Property Condition Assessments, and over 400 Property Damage Assessments for the insurance industry in 38 states. He has investigated and assessed damage in the 2014 Napa 6.0, Virginia 5.8, Oklahoma 5.7, and Northridge 6.7 earthquakes.

Mr. Anderson currently oversees and manages the Seismic Services Division of AEI's Building Assessments Department. Responsibilities include Senior Assessment of Seismic Risk Assessment Reports, Conducting Peer Reviews, scheduling, Seismic Retrofit Design, interfacing with Clients, providing outreach and education to Clients and Building Owners.

Some of his specific areas of expertise include: forensic analysis of architectural and structural damage, seismic assessments of buildings, structural remediation and rehabilitation of properties (URM, Historic, seismic, tornado, hurricane, flood, and fire), and structural design of swimming pools, wood and timber framed structures, structural steel structures, reinforced concrete structures, reinforced masonry structures, and pre-manufactured light gage steel structures.

Key experience for Mr. Anderson includes:

- Structural Design since 1991
- Seismic Retrofit Design since 1991
- Seismic Risk Assessments since 1994
- Forensic Assessments since 2007

Publications: 2016 ASTM Seismic Standards Update, California Mortgage Finance News, Fall 2016

---



# Jeb Bonnett

## Director of Building Assessments - HUD

---

### EDUCATION

- B.B.A - Finance, James Madison University
- Principles of Real Estate Program, James Madison University

### CERTIFICATIONS

- HUD Multi-Family Accelerated Processing (MAP) Cost/A&E Seminar - New York City
- HUD Multi-Family Accelerated Processing (MAP) PCNA Workshop - Columbus
- Virginia Housing Development Authority - Universal Design Training
- Fair Housing Act Accessibility Training Course- Phillip Zook
- Fair Housing Act Accessibility Training Seminar- Fair Housing Act First
- Elevator Training Courses - Sanjay Kamani, QEI, KP Property Advisors LLC
- Building Performance Institute - Training Services
- Building Specs Training Institute, Building/Design Inspection Courses

### SUMMARY OF PROFESSIONAL EXPERIENCE

Mr. Bonnett has worked exclusively in the niche HUD real estate due diligence consulting industry since 2005. He has performed and directed thousands of building assessment projects for HUD MAP, HUD LEAN, and Public Housing Authority clients. He has expert knowledge of HUD's Capital Needs Assessment guidelines and software reporting requirements. In addition, he has extensive experience and training on numerous accessibility standards, including, UFAS, ADA, ANSI, and the Fair Housing Act Guidelines.

As Director of Building Assessments - HUD, Mr. Bonnett is responsible for providing direction for the development of HUD Building Assessment services throughout AEI. Day to day responsibilities include, creating organizational process assets, training internal and external stakeholders, identifying and understanding industry guidelines for HUD Building Assessment services, senior reviewing, project oversight, business development and client management.

### PROJECT EXPERIENCE

Project experience for Mr. Bonnett includes:

- Performing and directing the successful completion of over 3,000 HUD MAP and HUD LEAN compliant Capital Needs Assessments.
- Performing and directing the successful completion of RAD and GPNA projects for over 100 HUD Public Housing Authority AMPs.
- Leading the creation of software reporting platforms to efficiently populate HUD's CNA E-Tool, RAD Tool, and GPNA Tool software systems.
- More than 5 years' experience in multifamily assessments including numerous assignments for Freddie Mac, Fannie Mae and HUD execution.
- Creating and performing HUD E-Tool training seminars for HUD MAP lenders and internal staff.





# Karla King, P.E., Esq., LEED AP

## Executive Vice President

---

### EDUCATION

- JD - Law, Concentration in Environmental Law, Massachusetts School of Law, Andover, MA
- MS - Engineering Management, Certificate in Environmental Management, Tufts University, Medford, MA
- BS - Civil/Environmental Engineering, Minor in Business Management, Northeastern University, Boston, MA

### CERTIFICATIONS

- Professional Engineer, Licensed in MA, CT, RI, VT, NH, ME, NY, NC
- LEED AP BD+C (Leadership in Energy and Environmental Design Accredited Professional Building Design and Construction)
- State Bar of Massachusetts, Admitted June 2017
- Massachusetts Certified Public Purchasing Official (MCPPO) Program Certification for School Project Designers and Owner's Project Managers
- OSHA 10-Hour Construction Certificate
- Confined Space and First Aid Training

### SUMMARY OF PROFESSIONAL EXPERIENCE

Ms. King is both an environmental engineer and an attorney specializing in navigating sustainability and regulatory compliance to ensure business continuity and operational objectives. Ms. King works across multiple markets including retail, healthcare, life science, industrial, aerospace, municipal, water, telecommunications, and education through the investigate, plan, design, construct, and operate stages of a project's life cycle. Ms. King holds a BS in Civil/Environmental Engineering from Northeastern, a MS in Engineering Management from Tufts, and a JD from Massachusetts School of Law. She is a Professional Engineer licensed in MA, CT, RI, VT, NH, ME, NY, and NC.

As Executive Vice President at AEI, Ms. King will leverage AEI's existing building assessment, capital planning, construction risk management, energy efficiency, industrial hygiene, environmental health & safety, zoning and permitting, and resilience consulting expertise to provide full-service sustainability services to our clients.

In her previous role, Ms. King managed the Environmental, Social, & Governance (ESG) business unit which consisted of four practices:

- Environmental, Social & Governance Services: Supporting clients with ESG initiatives and goals including ESG benchmarking, reporting, and supporting services to improve ESG scores.

- Energy & Sustainability Services: Energy Audits (ASHRAE Level 1-3), Retro-Commissioning, Commissioning, Mechanical Electrical Plumbing (MEP) assessments, ESG consulting, Carbon Footprint Evaluations, Energy & Water Benchmarking
- Building Sciences: Asbestos Management, Lead-based Paint Management, Mold and Radon Investigation and Remediation, Indoor air quality services, Safety services, Building Construction and Demolition Environmental services
- Environmental, Health & Safety Services: Environmental Health & Safety (EHS) on-site support services, industrial hygiene, environmental permitting and compliance, Stormwater Pollution Prevention Plans (SWPPP), Spill Prevention Control & Countermeasure Plans (SPCC), air permitting, tank registration, wastewater permitting, wastewater operations support.
- Owner's Project Management Services: Owner's Project Management/Representation services supporting clients through the full project life cycle including pre-deal approval, due diligence, entitlements and permitting, design, and construction.

## PROJECT EXPERIENCE

Project experience for Ms. King includes:

- Fox Rock Properties, Environmental Health & Safety and Energy & Sustainability Services: Services included indoor air quality assessments, Mechanical Electrical Plumbing (MEP) assessment, energy audits.
- Newton Pavilion, DCAMM, Boston, MA, Environmental Health & Safety/ COVID-19: Ms. King serviced as Principal-In-Charge for DCAMM for the Newton Pavilion Hospital with COVID-19 rapid response efforts by reviewing and approving cleaning protocols, including recommendations for the decontamination process and how the selected contractor should develop their work scope and plan. EBI also provided post-decommissioning assessment services, on-site coordination and facilitation of cleaning services, a mold assessment, and a review of the post-cleaning verification sampling plan and report.
- 7-11 Project Management Services, Nationwide: Ms. King served as Principal-In-Charge for 7-11 Stores in multiple states. Projects included portfolio management, ground-up with and without gas, tenant improvements, business conversion programs, and build-to-suit projects. 7-11 required a Program Manager to help manage their portfolio of projects from site due diligence through store turnover within the Northeast, Mid-Atlantic, and Florida regions. Services included Owner's Representation for projects in their portfolios throughout these regions.
- Novartis Institutes for BioMedical Research, Inc., Cambridge, MA: Compliance and Commissioning Services: Ms. King served as Principal-In-Charge for Novartis services from 2014-2020. She oversaw all permitting and environmental health and safety compliance efforts associated with Novartis' existing facilities as well as the \$600 Million Cambridge Campus Expansion Project. The Cambridge Campus Expansion project is a LEED Gold building consisting of two main biomedical buildings built upon a common below grade structure, vehicle parking garage, loading dock, building support spaces and central utilities trigeneration plant. Compliance and permitting services included stormwater, wastewater, health and safety, and laboratory safety. Services included full-time support throughout

the project to ensure compliance and health and safety program implementation with the new buildings as well as serving as the Commissioning Agent for the Cambridge Campus Expansion Project through Skanska.

- Steward Healthcare, Compliance and CMMS Services: Services included Joint Commission compliance mock surveys, indoor air quality assessments, mold remediation, asset management, and CMMS implementation and management services.
- EMD Serono, Compliance and Commissioning Services, Billerica, MA: Ms. King served as Principal-In-Charge for EMD Serono. She managed the teams supporting EMD Serono for environmental health and safety compliance for the existing facilities as well as for their Billerica Campus Expansion including the addition of the Sagamore building, a R&D facility that received both LEED Platinum certification from the U.S. Green Building Council as well as LEED Gold certification for New and Existing Buildings from the International WELL Building Institute. Services also included commissioning services and energy audits.
- Borrego Solar: Services included preparation of SPCCs and Tier II reports for several solar facilities.
- AT&T Environmental Compliance and Regulatory Services, Nationwide: Ms. King served as Client Manager for all Environmental, Health, and Safety (EHS) services. The entire portfolio consists of sites across 34 states, largely in the Midwest, for which EBI has been serving since 2016. EH&S Services to AT&T have included: Air assessment and permitting; tank assessment and permitting; industrial hygiene services; hazardous materials inventory forms; air emissions inventory and reporting; methane site assessment; Spill Prevention, Control, and Countermeasure (SPCC) planning, facilities' plans, and construction phase services; site-specific Health and Safety Plans (HASPs).
- McDonald's Restaurants, Multiple Locations, Multiple States: Ms. King served as Principal-In-Charge for McDonald's architectural and engineering services. Services included project and portfolio management to 273 locations across 14 states simultaneously. Additional tasks have included MEP, structural, ADA audits, asbestos surveys, permit plans, and existing conditions plans. This work is being done concurrently with other large portfolios. Services included both new construction as well as renovations, additions and modifications to existing restaurants.
- Interplex, Environmental Health & Safety Support: Services included EHS gap assessment, air permitting, SPCC planning, wastewater operations support.
- AJAX, Groundwater Discharge Permitting Services: Ms. King managed the review and provided consulting services to assist in the purchase of a MassDEP Groundwater Discharge Permit associated with real estate property.
- Emmanuel College, Wastewater and EHS Services: Services included EHS and wastewater operation and maintenance services for Industrial Wastewater Treatment System and prepared Tier II report for hazardous materials stored on-site.
- Good Start Genetics, Wastewater Operations & Maintenance: Services included wastewater operations and maintenance services for Industrial Wastewater Treatment System.
- GreenLight Biosciences: Services included preparation of MWRA Sewer User Discharge Permit Applications for Industrial Wastewater Treatment System (IWTS) for two new facilities in Medford, MA.



- Maverick Real Estate Partners LLC, Swansea Mall Wastewater Treatment Facility Assessment: As part of due diligence on retail mall property, Ms. King managed and prepared an assessment for a 90,000 gallon per day on-site wastewater treatment facility with groundwater discharge.
- Micron, Wastewater, SPCC, and SWPPP Services: Services included updates to Industrial Wastewater System Operations and Maintenance Manuals, Spill Prevention, Control and Countermeasure Plan and Stormwater Pollution Prevention Plan.
- Town of Milford, Site Development Water Peer Review: Services included peer review of the Water Distribution System Assessment for site development with significant water use.
- Belchertown NPDES Permitting Compliance: Services included management of the review of a draft National Pollutant Discharge Elimination System (NPDES) permit for the Belchertown Wastewater Treatment Facility.
- Marshfield Main Lift Station and Headworks Upgrade: Services included pump station upgrades and a headworks building for handling grit and screenings at a 2.1-mgd wastewater treatment facility in Marshfield, MA. Services included preparation of final design plans for the replacement of pumps at pump station, addition of building for the screenings and grit washing equipment, and addition of vortex grit removal system.
- Marshfield Avon Street and Central Street Pump Stations Upgrade: Services included design of a pump station upgrade for two pump stations in Marshfield, MA.
- Village Greens Wastewater Treatment Facility and Groundwater Discharge: Services included design and construction oversight of a 55,000 gallon per day on-site wastewater treatment facility system and on-site effluent disposal system in Littleton, MA. Services included preparation of a hydrogeologic report and corresponding permits for groundwater disposal and developed a set of permit plans for the design of a membrane bioreactor wastewater treatment facility.
- Madison Place Wastewater Treatment Facility and Groundwater Discharge: Services included design and oversight of the construction of a 22,000 gallon per day on-site wastewater treatment facility system and on-site effluent disposal system in Southborough, MA. Services included preparation of a hydrogeologic report and corresponding permits for groundwater disposal and developed a set of permit plans for the design of a membrane bioreactor wastewater treatment facility.
- Wayland Groundwater Discharge: Services included design of a wastewater effluent disposal area in Wayland, MA and completion of hydrogeologic reports and corresponding permits for groundwater disposal.
- Seabrook, NH MS4 and MSGP Stormwater Compliance Program : Services included coordination and completion of stormwater outfall mapping and investigations in Seabrook, NH as part of the Municipal Separate Storm Sewer Systems (MS4) permit program and the Multi-Sector General Permit (MSGP) at the Town's transfer station. MS4 permit program compliance included peer reviews of site developments and assessment for compliance with stormwater control measures.
- Westborough Wastewater Treatment Plant Upgrade: Services included design and management of upgrades to 7.68-mgd advanced treatment facility in Westborough, MA for phosphorus removal. As part of the preliminary design, coordinated pilot testing of four phosphorous treatment systems. Oversaw design and construction of the project including: tertiary treatment building for

- phosphorus removal utilizing Kruger ActiFlo®; modifications to the headworks, primary treatment facilities, and activated sludge process to achieve biological phosphorus reduction; addition of a third secondary clarifier; rehabilitation of filters; and upgrade to UV disinfection.
- Glen Ellen Country Club Wastewater Treatment Facility: Services included preparation of a Preliminary design report and designed wastewater collection system and wastewater treatment facility for a 341-unit housing development and 9-hole golf course at Glen Ellen Country Club in Millis, MA. Initiated design utilizing membrane bioreactor technology with potential for effluent wastewater reuse for use as golf course irrigation with the remaining effluent being discharged to subsurface disposal beds beneath the golf course.
  - Nantucket Downtown Sewer Replacement: Services included design and construction services for replacement of wastewater infrastructure in the downtown area of Nantucket, MA to eliminate surge charging, infiltration/inflow problems, and deteriorated structural integrity of the pipes. Designed and oversaw replacement of 2.4 miles of sewer using pipe bursting and open trench excavation due to numerous utilities, high tidal influenced groundwater conditions, narrow roadways, and difficult soil conditions.
  - North Weymouth/ Mill River Infiltration Rehabilitation: Services included oversight of the construction phase of this project, which consisted of pipe cleaning, inspection, testing, and sealing; manhole coating and repairs; chemical root treatment; cured-in-place pipe repairs using short liner technology; sealing and testing service connections; and other repairs and replacements.
  - Sea Quarters Sewer System : Services included design and construction oversight of gravity sewer, force mains, and pump stations in a new development in New Seabury, MA.
  - Bayview Sewer Extension Design: Services included the design of 13,000 linear feet of 8- and 10-inch gravity sewer, 1,000 linear feet of low-pressure sewer, 6,750 linear feet of force main, and two package suction lift pump stations to eliminate failing septic systems and provide service to properties within a coastal flood hazard area in Dartmouth, MA.
  - Logan International Airport BIF Sewer Lift Station Upgrade: Services included the design of the replacement of self-priming suction pumps with submersible pumps for Massachusetts Port Authority.

## PRESENTATIONS:

CREW Coastal Virginia “February Luncheon: Due Diligence & Construction in 2021”, presentation on changes to the ASTM due diligence standard and the impacts of the pandemic on construction and transformation in the marketplace, February 2021.

Bisnow Boston “Health & Safety: What’s Next for Building Management”, a panel discussion on COVID-19 return to workplace, April 2020.